

Wooden
Debris dam
with 2 X
100Ø orifice
at 200
centers
Timber
Access
Bridge with
Timber
Handrails
Re-profiled
Local Bank
(Both sides)
Flow
Flow
Location Plan
Scale 1:50
Proposed
Access Path

