



Photograph 1

View of property from North Street at line of junction between the Railway Inn and the adjoining terraced house



Detail 1

Brickwork not coursing on either side of boundary and return headers indicate separate walls built on line of boundary



Photograph 2

View of property from North Street at line of junction between the Railway Inn and the adjoining terraced house



Detail 2

Chimney Brickwork to adjoining property built on line of boundary with no encroachment onto the boundary wall of The Railway Inn



Photograph 3

Oblique view of The Railway Inn viewed from North Street and the adjoining terraced house



Detail 3

Lead flashings at junction between properties and showing boundary wall of the Railway Inn extending above the roof level of the adjacent terraced house



Photograph 4

View from above at roof level showing the boundary wall to The Railway Inn forming enclosure to the rooms at second floor level separate to the adjacent property



Detail 4

Independent wall on line of boundary between properties



Photograph 5

Rear of the property viewed from the existing flat roof at line of junction between the Railway Inn and the adjoining terraced house



Detail 5

Line of boundary wall clearly within the property boundary with a position consistent with the same boundary line visible elsewhere