




This section of inner skin wall to
be rebuilt in 7 Nmm strength
blockwork ie Thermalite Hi
strength 7 blocks (see **Structural**
note above, page 2)