


Additional Structural note



This section of inner skin wall to be rebuilt in 7 Nmm strength blockwork ie Thermalite Hi strength 7 blocks (see **Structural** note above, page 2)