

Staunton Country Park Works to Northern Wall of Storey Gardens

Photo Montage



Fig 1: Historic Maps



Fig 2: Construction History



Fig 3: Storey Gardens aerial view



Fig 4: Image to show leaning wall



Fig 5: North wall South elevation viewed from Storey Gardens



Fig 6: North wall historic collapse viewed from Storey Gardens



Fig 7: North wall viewed from within Stable Cottage garden



Fig 8: North wall viewed from within Stable Cottage garden, showing collapsed wall.



Fig 9: North wall viewed from within Stable Cottage.