



BH REF:	BH101	BH DEPTH (m bgl):	15	STANDING WATER DEPTH (m bgl):	6.2	
CASING DEPTH (m bgl):		14	BH DIAMETER (m):	0.15	CASING DIAMETER (m):	0.15

[illegible]


Project	Manor Farm, Bedhampton			Title	Falling Head Test in Borehole BH101 at 15m bgl		
Client:	Bargate Homes			Geo-Environmental Services Ltd Unit 7 Danworth Farm, Cuckfield Road Hurstpierpoint, West Sussex BN6 9GL +44(0)1273 832972 www.gesl.net		 Geo-Environmental	
Ref No:	17736	Revisio	1.0				
Drawn:	RG	Date:	01/11/2018				
Figure:	-	Scale:					

BH REF:	BH102	BH DEPTH (m bgl):	5	STANDING WATER DEPTH (m bgl):	DRY	
CASING DEPTH (m bgl):	3	BH DIAMETER (m):	0.15	CASING DIAMETER (m):	0.15	

[illegible]

Project:	Manor Farm, Bedhampton			Title:	Falling Head Test in Borehole BH102 at 5m bgl		
Client:	Bargate Homes			Geo-Environmental Services Ltd Unit 7 Danworth Farm, Cuckfield Road Hurstpierpoint, West Sussex BN6 9GL +44(0)1273 832972 www.gesl.net	 Geo-Environmental		
Ref No:	17736	Revisio	1.0				
Drawn:	RG	Date:	01/11/2018				
Figure:	-	Scale:					

BH REF:	BH102	BH DEPTH (m bgl):	15	STANDING WATER DEPTH (m bgl):	5	
CASING DEPTH (m bgl):		14	BH DIAMETER (m):	0.15	CASING DIAMETER (m):	0.15

[illegible]

Project	Manor Farm, Bedhampton			Title	Falling Head Test in Borehole BH102 at 15m bgl		
Client:	Bargate Homes			Geo-Environmental Services Ltd Unit 7 Danworth Farm, Cuckfield Road Hurstpierpoint, West Sussex BN6 9GL +44(0)1273 832972 www.gesl.net		 Geo-Environmental	
Ref No:	GE17736	Revisio	1.0				
Drawn:	RG	Date:	01/11/2018				
Figure:	-	Scale:					