




Access: via front door, or via alley between 7A and 8 and through back door.




9 Langstone High Street – Attic photos Sep. 2020.



Above - view of western end of the attic, partywall with number 8.




Right hand side of party wall doesn't look too bad.



Photos of the left hand side of chimney stack, next to newer fire wall. Bricks don't look too bad here.




These are all photos of the left hand side of the chimney stack.
The bricks don't look too bad here. Little bit of sky showing top left hand side.





The worst bit is in the centre – upper section.



Same bit – lower section.



Same bit from round the corner (left hand side).



Front view from right hand side of the worst bit.

