

## Appendix B - Developed Properties in Area Examples



Location 9 – Full width side dormer visible from street in Sutton Road



Location 10 – Side dormers and roof alterations visible from street in Lynwood Avenue



Location 11 – Looking down Silverdale Drive from Lynwood Avenue Junction



Location 12 – Developed property in Sutton Road



Raised ridge height in Silverdale Drive with Dormers



Change to Ridge and addition of small dormer in Silverdale Drive