



Trekennick Surveys Ltd.

Telecom services.

Waterlooville, Tree survey
Ref.1243978

TNE1243978 Waterloooville

Date of visit.	Co-ordinates: 467407-107802, Nearest Postcode, PO7 5RP
19-06-20	Ladybridge road, Waterloooville

SLIDES

- (3) Sketch of tree position
- (4) Overview showing position of two trees requiring reduction
- (5) Photos of Tree area
- (6) Photo of access and base of trunk


Summary: Tree area requiring reduction are two common oaks, in the back garden of 3 Ladyville road. There is access by foot through the pedestrian gate at the premises, vehicles can be parked on the adjacent car park near recycling bins. Access is also possible to the trees (using ladder) from the parkland at the rear of the property and would be easier for disposing of the waste materials.

TPO1042- 3 LADYBRIDGE ROAD, WATERLOOVILLE K07 5RP

TREES LOCATED TO THE REAR OF THE PROPERTY BEHIND A
SINGLE STOREY DWELLING. COMPRISING 2x OAKS

T1 - OAK (14m)
T2 - OAK (14m)

MBNL REQUEST IS TO
REDUCE BOTH TREES
(T1/T2) TO 12M





Two common oaks in the rear garden of 3 Ladybridge road.



Various views
of oak trees in
the garden of
3 Ladybridge
road





View of both oak trunks and the area around the base in the garden at 3 Ladybridge road.