




KEY

- Viewpoints with views of proposed site
- Reservoir Footprint
- 2 km Study Area

Notes:

Service Layer Credits:

Contains Ordnance Survey data Crown copywrite and database right 2019 © Attribution statement:
(c) Environment Agency copyright and/or database right 2019. All rights reserved.

Site visits conducted in October 2019 and March 2020.
All photographs taken using a Nikon digital SLR camera with a 35 mm Fixed Focal length lens.
Camera mounted on a tripod. Viewer height above ground level; approximately 1.6 m.
All images subsequently merged with brightness/

Print Document on A3 size Format.

C01	GC	DB	PT	LB	PUBLISHED	24/08/20
Rev. Status	Drn By	Ckd By	Rev By	Auth By	Description	Date



Member of the SNC-Lavalin Group

Aztec West
500 Park Avenue
Almondsbury
Bristol
BS32 4RZ
Tel: +44 (0)1454 662000
Fax: +44 (0)1454 663333
www.atkinsglobal.com

Copyright C Atkins Limited (2020)

Drawing Suitability: PUBLISHED	Status: A1
-----------------------------------	---------------

Contractors Drawing Number:
HTR - ATK - RZ - RE - DR - L - 0002

Project

Originator

Volume

Location

Type

Role

Number

Telephone: Havant (023) 9249 9888
Fax: Havant (023) 9245 3632
Website: www.portsmouthwater.co.uk
Registered Office: PO Box 8 West Street
Havant Hampshire PO9 1LG
REGISTERED IN ENGLAND No. 2536455



Project Ref. No: 5169117	Sheet: 1 of 13	Scale: N.A.	Sheet Size: A3
-----------------------------	-------------------	----------------	-------------------

Project Title:
HAVANT THICKET RESERVOIR

Drawing Title:
FIGURE 11.9 - VIEWPOINT LOCATION PLAN:
CONFIRMED VIEWS

Portsmouth Water Drawing Number: -	Rev: C01
---------------------------------------	-------------

Photo Viewpoint 1
View looking north west along The Avenue (Winter Season)



View looking north west along The Avenue (Summer Season)



Photo Viewpoint 2
View looking north west along The Avenue.(Winter Season)



View looking north west along The Avenue. (Summer Season)



Notes //
Site visits conducted in October 2019 and March 2020.
All photographs taken using a Nikon digital SLR camera with a 35 mm Fixed Focal length lens. Camera mounted on a tripod.
Viewer height above ground level; approximately 1.6 m
All images subsequently merged with brightness/ contrast adjusted using computer software.


Havant Thicket Reservoir
Landscape & Visual Impact Assessment



Figure 11.10: Viewpoint Photograph Sheets, Confirmed Views Sheet 2 of 13

Photo Viewpoint 3A

View looking north west towards the site adjacent The Terrace of Staunton Country Park approximately 0.5 km. (Winter Season)




View looking north west towards the site adjacent The Terrace of Staunton Country Park approximately 0.5 km. (Summer Season)



Photo Viewpoint 3B

View looking north west towards the site from The Terrace of Staunton Country Park approximately 0.5 km. (Winter Season)



Notes //
Site visits conducted in October 2019 and March 2020.
All photographs taken using a Nikon digital SLR camera with a 35 mm Fixed Focal length lens. Camera mounted on a tripod.
Viewer height above ground level; approximately 1.6 m
All images subsequently merged with brightness/ contrast adjusted using computer software.

Havant Thicket Reservoir
Landscape & Visual Impact Assessment



Photo Viewpoint 5A

View from back of houses on Manor Lodge Road looking west/southwest towards site. (Winter Season)



View from back of houses on Manor Lodge Road looking west/southwest towards site. (Summer Season)



Photo Viewpoint 5B

View from roundabout on Manor Lodge Way looking west/southwest towards site. (Winter Season)



Notes //

Site visits conducted in October 2019 and March 2020.

All photographs taken using a Nikon digital SLR camera with a 35 mm Fixed Focal length lens. Camera mounted on a tripod.

Viewer height above ground level; approximately 1.6 m

All images subsequently merged with brightness/ contrast adjusted using computer software.


Havant Thicket Reservoir
Landscape & Visual Impact Assessment



Figure 11.12: Viewpoint Photograph Sheets, Confirmed Views Sheet 4 of 13

Photo Viewpoint 6

View along bridleway at back of houses on Manor Lodge Road looking north to south west towards The Avenue. (Winter Season)



View along bridleway at back of houses on Manor Lodge Road looking north to south west towards The Avenue. (Summer Season)



Photo Viewpoint 7

View from within site looking west to south west towards The Avenue. (Winter Season)



View from within site looking west to south west towards The Avenue. (Summer Season)



Notes //
Site visits conducted in October 2019 and March 2020.
All photographs taken using a Nikon digital SLR camera with a 35 mm Fixed Focal length lens. Camera mounted on a tripod.
Viewer height above ground level; approximately 1.6 m
All images subsequently merged with brightness/ contrast adjusted using computer software.

Havant Thicket Reservoir
Landscape & Visual Impact Assessment



Figure 11.13: Viewpoint Photograph Sheets, Confirmed Views Sheet 5 of 13

Photo Viewpoint 8

View adjacent to permissive footpath looking south towards Bells Copse. (Winter Season)



View adjacent to permissive footpath looking south towards Bells Copse. (Summer Season)



Photo Viewpoint 9

View from within site looking north east to south towards The Avenue and Middle Clearing. (Winter Season)




View from within site looking north east to south towards The Avenue and Middle Clearing. (Summer Season)



Notes //
Site visits conducted in October 2019 and March 2020.
All photographs taken using a Nikon digital SLR camera with a 35 mm Fixed Focal length lens. Camera mounted on a tripod.
Viewer height above ground level; approximately 1.6 m
All images subsequently merged with brightness/ contrast adjusted using computer software.

Photo Viewpoint 10A

View from within site looking north east to south east towards Middle Clearing and Round Wood. (Winter Season)



View from within site looking north east to south east towards Middle Clearing and Round Wood. (Summer Season)



Photo Viewpoint 10B

View from footpath 121 looking north east to south west towards Middle Clearing and Round Wood. (Winter Season)



Notes //
Site visits conducted in October 2019 and March 2020.
All photographs taken using a Nikon digital SLR camera with a 35 mm Fixed Focal length lens. Camera mounted on a tripod.
Viewer height above ground level; approximately 1.6 m
All images subsequently merged with brightness/ contrast adjusted using computer software.


Havant Thicket Reservoir
Landscape & Visual Impact Assessment



Figure 11.15: Viewpoint Photograph Sheets, Confirmed Views Sheet 7 of 13

Photo Viewpoint 11

View from within site looking north to south towards Middle Clearing, Round Wood and The Avenue. (Winter Season)



View from within site looking north to south towards Middle Clearing, Round Wood and The Avenue. (Summer Season)



Photo Viewpoint 12

View from within site looking north to east towards Middle Clearing, Round wood and The Avenue. (Winter Season)



View from within site looking north to east towards Middle Clearing, Round wood and The Avenue. (Summer Season)



Notes //

Site visits conducted in October 2019 and March 2020.
All photographs taken using a Nikon digital SLR camera with a 35 mm Fixed Focal length lens. Camera mounted on a tripod.
Viewer height above ground level; approximately 1.6 m
All images subsequently merged with brightness/ contrast adjusted using computer software.

Photo Viewpoint 13

View from within site looking north to east from edge of Leigh Park housing estate towards Middle Clearing, The Avenue and Round Wood. (Winter Season)



View from within site looking north to east from edge of Leigh Park housing estate towards Middle Clearing, The Avenue and Round Wood. (Summer Season)



Photo Viewpoint 14

View from Gammons Hill within site looking south to east. (Winter Season)



Notes //
Site visits conducted in October 2019 and March 2020.
All photographs taken using a Nikon digital SLR camera with a 35 mm Fixed Focal length lens. Camera mounted on a tripod.
Viewer height above ground level; approximately 1.6 m
All images subsequently merged with brightness/ contrast adjusted using computer software.

Photo Viewpoint 15

View from Deerslaughter Plain looking north west to south east towards Middle Clearing, The Avenue and Round Wood. (Winter Season)




View from Deerslaughter Plain looking north west to south east towards Middle Clearing, The Avenue and Round Wood. (Summer Season)




Photo Viewpoint 16

View from Deerslaughter Plain within site looking north east to south east towards Middle Clearing, The Avenue and Round Wood. (Winter Season)



View from Deerslaughter Plain within site looking north east to south east towards Middle Clearing, The Avenue and Round Wood. (Summer Season)



Notes //
Site visits conducted in October 2019 and March 2020.
All photographs taken using a Nikon digital SLR camera with a 35 mm Fixed Focal length lens. Camera mounted on a tripod.
Viewer height above ground level; approximately 1.6 m
All images subsequently merged with brightness/ contrast adjusted using computer software.

Havant Thicket Reservoir
Landscape & Visual Impact Assessment



Figure 11.18: Viewpoint Photograph Sheets, Confirmed Views Sheet 10 of 13

Photo Viewpoint 17

View along bridleway within site looking north east to south east towards The Avenue, Middle Clearing and Round Wood. (Winter Season)



View along bridleway within site looking north east to south east towards The Avenue, Middle Clearing and Round Wood. (Summer Season)



Photo Viewpoint 18

View from within site looking north to south east towards The Avenue. (Winter Season)



View from within site looking north to south east towards The Avenue. (Summer Season)



Notes //
Site visits conducted in October 2019 and March 2020.
All photographs taken using a Nikon digital SLR camera with a 35 mm Fixed Focal length lens. Camera mounted on a tripod.
Viewer height above ground level; approximately 1.6 m
All images subsequently merged with brightness/ contrast adjusted using computer software.