



View upon arrival as existing; differing scales, materials and lack of clear entrance. Lack of privacy and security through historic space planning and various access points.



Illustrative View of proposed; Defined 'Front Door' and entrance from driveway, scale and consistency in materials and massing.

128 Victoria Road | P008