

Before:




G2 showing stair, archway and screen at FF1 and FF2. (Source: The House Shop)



G3 showing stair in G2 through archway (Source: Zoopla)




6. Exposed brickwork to south, east and west walls with view through to G4 - late Victorian Cross Wing.




7. Arch leading from G2 to G3, showing line of former 'bay' window. Hardboard covering poor quality floorboards.



4. Open Stair will curtail, stick balusters, closed string (assume once 'open').



5. Joists to G2 ceiling showing later additions and burn marks. Traces of modern gypsum plaster to each of arch (right of image).



SHEET 2
Photographic Record / Inventory:
Ground Floor: G2, G3

December 2019