

PHOTOGRAPHS

Photographic Schedule of Condition –ESSC



1. Lobby outside toilets.



2. Lobby outside toilets.

Photographic Schedule of Condition –ESSC



3. Lobby outside toilets.



4. Lobby outside toilets.



5. Lobby outside Female toilets.



6. Dividing wall within male toilets, exposed beam above partition wall.



- 7. Proposed wall right of column to be removed. New dividing Timber wall to be installed underbeam to divide galley and male toilet.**



- 8. Existing male toilets to be refurbished.**

Photographic Schedule of Condition –ESSC



9. Part of the male toilets that will form part of the proposed galley area.



10. Part of the male toilets that will form part of the new male toilets.

Photographic Schedule of Condition –ESSC



11. Female toilets to be refurbished.



12. Female toilets to be refurbished.



13. Lobby outside the female toilets.



14. Exposed beam within the female toilets.



15. Recessed section of wall to be removed and new opening formed behind fridge.



16. Recessed section of wall to be removed and new opening formed behind fridge.