



Legend:	
①	Note Marker
— —	Cladding Remnants
	Brickwork

—	—	Cladding Remnants
—	—	
—	—	

--	--



- ① 75mm brickwork
- ② Concrete dwarf wall remnants.
- ③ Rat Trap boundary wall
- ④ Single skin brickwork
- ⑤ Chimney remnants
- ⑥ All timbers approximately 50% charred.



South Internal Elevation: Post Fire Damage

CAD

The Old Brewery, 15E South Street, Havant, PO9 1BU

19008-615⁰

10m

15m

20m