



Existing Southern Retaining Wall It is assumed that the rooting extremities of the southern and south-western boundary trees adjacent to the retaining wall have been restricted growing to the north and north-east due to the a) depth of the current retaining wall foundations; and b) trees being set over 1 m above current on-Site ground level. Investigations to establish the extent of roots from off-Site trees that may be present on-Site should be undertaken to inform an Arboricultural Method Statement and before any on-Site work are begun.

