



ROOT GROWING UNDER WALL
CRACKING AND DAMAGING WALL



TREE LEANING TOWARDS
RECTORY ANNEX ROOT GOING UNDER WALL



THE OLD RECTORY. ROOT IS GOING UNDER
CRACKING WALL