

Appendix A

FORTY ACRE FARM										idpPARTNERSHIP NORTHERN	
BDW SOUTHAMPTON										4-JUN-2019	
HOUSE TYPE										TOTAL SQ FT	
BARRATT										TOTAL SQ M	
AMBERSHAM	2	Apartment	3	6	1.9	884	84.3	3564	328.88		
HACKSON	2	Apartment	3	6	1.9	876	83.8	4096	376.80		
ROSEBERRY	2	Terraced	2	25	7.8	679	63.1	16975	1577.50		
KENLEY	2	Terraced	2	24	7.5	614	57.1	14736	1370.40		
ALVERTON V1	2	Apartment	2	2	0.6	687	63.8	1374	127.80		
HADSTONE	3	Terraced	2	28	8.8	830	77.1	23240	2158.80		
HOLDSBY	2	Terraced	2	23	7.2	655	60.4	16685	1558.20		
KINGSVILLE	3	Terraced	2.5	19	5.9	1073	99.8	20387	1892.40		
DWH											
WILFORD P204-ECT107	2	Terraced	2	4	1.3	620	57.60	2480	228.40		
HADLEY P241-E-1041-107	2	Semi-Detached	2	20	6.3	1001	93.00	20020	1860.00		
HADLEY P241-1041-107	2	Detached	2	5	1.8	1001	93.00	8005	745.00		
ARCHDESD P242-E-7	3	Semi	2	24	7.8	832	77.30	19688	1826.20		
KENNETT P210-E-7	3	Semi	2.5	8	2.5	1089	101.21	8712	803.88		
BARWATER H408-7	4	Detached	2.5	7	2.3	1342	124.70	5984	552.80		
EXETER H418-7	4	Detached	2	10	3.1	1484	137.80	14840	1378.00		
CORNELL H435-7	4	Detached	2	9	2.8	1374	127.65	12966	1198.85		
HOLDER H469-37	4	Detached	2	4	1.3	1538	142.70	8144	752.80		
BARRATT AFFORDABLE											
TYPE B6 - FLAT 1	1	Apartment	3	6	1.9	488	43.28	2788	258.88		
TYPE B6 - FLAT 2	1	Apartment	3	6	1.9	488	43.28	2788	258.88		
TYPE B6 - FLAT 3	2	Apartment	3	6	1.9	568	52.82	3388	313.72		
TYPE E5	1	Apartment	2	4	1.3	488	43.18	1844	170.84		
TYPE E5	1	Apartment	2	4	1.3	488	43.00	1872	174.00		
TYPE E5	3	Terraced	2	9	2.8	858	80.00	8822	801.00		
TYPE E5	4	Semi	2	4	1.3	878	80.88	3876	358.32		
TYPE E6	3	Terraced	2.5	13	4.1	928	86.10	13038	1199.30		
TYPE E7	2	Terraced	2	16	6.0	921	85.14	11216	1042.24		
TYPE T2	2	Apartment	2	1	0.3	704	65.43	704	65.43		
TYPE T3	2	Apartment	2	2	0.6	704	65.43	1408	130.86		
TYPE T3	2	Apartment	2	1	0.3	704	65.43	704	65.43		
DWH AFFORDABLE											
SH89	3	Terraced	2	3	0.9	628	58.88	2484	228.84		
SH87	2	Terraced	2	5	1.6	931	85.14	3605	335.70		
SH50	2	Semi	2	5	1.8	760	69.70	3780	348.80		
SH14	3	Semi	2	7	2.2	850	78.88	3685	340.00		
SH68	3	Semi	2.5	4	1.3	928	86.10	3704	344.40		
TOTAL										320	190
OVERALL TOTALS										273356	25398.43
OVERALL DENSITY											
SHEA PRIVATE MIX										TOTAL	%
1 BED APARTMENT	41.18	1	2							67	25.91
2 BED HOUSE/APARTMENT	18.66	3	2							127	46.70
3 BED HOUSE	3289	4	2							30	13.39
4 BED HOUSE	14200									284	100.00
SHEA AFFORDABLE MIX										TOTAL	%
1 BED APARTMENT										20	20.83
2 BED HOUSE/APARTMENT										96	37.50
3 BED HOUSE										36	37.60
4 BED HOUSE										4	4.17
										86	100.00


NOTE: Net area excludes all public open space and associated structural landscaping / buffer planting / half roads adjacent green etc.

DO NOT SCALE
All dimensions to be checked on site and Architect to be notified of any discrepancies prior to commencement

DESIGNER'S RISK ASSESSMENT
Construction Design and Management Regulations 2015

RESIDUAL RISKS:

REF.	DESCRIPTION	DATE
3		



KEY

SITE BOUNDARY

CARE HOME SITE BOUNDARY

SALES AREA - DWH

SALES AREA - BARRATT

GRASSCRETE AREAS - CONSTRUCTION TO BE CAPABLE OF ALLOWING EMERGENCY VEHICLE ACCESS

HEAVY DUTY CONSTRUCTION FOOTPATH OR DRIVE - CONSTRUCTION TO BE CAPABLE OF ALLOWING EMERGENCY VEHICLE ACCESS

DENOTES TREES TO BE REMOVED

SHARED OWNERSHIP

AFFORDABLE RENT



REVISION	DATE	DESCRIPTION	CHECKED
----------	------	-------------	---------



ARCHITECTURE | MASTERPLANNING | URBAN DESIGN

IDPartnership Northern, St Jude's, Barker Street, Shieldfield, Newcastle upon Tyne, NE2 1AS
T: +44 (0)191 281 4442 | W: idpartnership.com | E: info@idpartnership-northern.com

JOB / CLIENT
Forty Acre Farm
for BDW Southampton

DRAWING TITLE
Proposed Site Layout Plan

PROJECT: KD
ARCHITECT: KD
SCALE: 1:1000 at A0
DATE: April 2018

DRAWN BY: FY
PROJECT NO: N81:2393
DRAWING NO: PL04M

DESIGN STATUS: DRAFT | CONSULTATION | TENDER | CONSTRUCTION | RECORD

COPYRIGHT : IDPartnership Northern

Appendix B

MEETING MINUTES

Meeting: Pre-application Meeting for proposed residential development at Forty Acre Farm, Bedhampton

Date: 26th October 2016 **Time:** 14:00

Location: Hampshire County Council Offices, Ell Court West, Winchester, SO23 8UJ

Attendees:

Holly Drury (HD)	Hampshire County Council (HCC)
Will Hubbard (WH)	Hampshire County Council (HCC)
Nick Laker (NL)	Barratt Homes (BH)
Jessica Lloyd (JL)	Paul Basham Associates (PBA)
Mark Smith (MS)	Paul Basham Associates (PBA)

Agenda:

1. Introduction
2. Accessibility
3. Trip Rates
4. Trip Distribution
5. Traffic Impact
6. Access Design
7. AOB

	Minutes	Action
1.1	Introduction	
1.1.1	JL confirmed the site proposals of approximately 315 C3: General Residential, a 60-bed care and 60 retirement living units.	N/A
1.2	Accessibility	
1.2.1	HD outlined concerns over the walking distance and environment to the local primary school and requested further research into existing sustainable travel schemes in place such as a 'park and stride' within any TA/TP. Noted that even on school holidays, the area around the school is busy with parking. HD requested an NMU appraisal of walking and cycling routes as part of site's full application.	PBA to complete NMU appraisal in TA
1.2.2	HD requested as part of TA to clarify walking distances (ensure walking routes not 'as crow flies') and to explore maximum and minimum distances based on furthest parts of site. Include distances to bus stops.	PBA to clarify walking distances in TA
1.2.3	HD requested that PBA approach Stagecoach to look at routing services through the site. HD accepted that should Stagecoach not support, then little BH could do.	JL to liaise with Stagecoach
1.2.4	As part of the NMU PBA to research crossing facilities at Rusty Cutter for pedestrians and cyclists. PBA to assess pedestrian and cyclist desire lines, and review routes north and south around Rusty Cutter.	PBA to include in TA
1.2.5	HD requested PBA look at a signalised pedestrian crossing across Havant Road. (PBA to use a reverse engineered approach to assess PV ² value and the demand required for a pedestrian crossing.) HD to forward response from HCC ITS team regarding the principle of signalised crossing on Havant Road and whether ITS would support such	PBA to complete PV ² calculations

MEETING MINUTES

	a crossing. <i>Post Meeting Note – HD forwarded this email dated 01.11.16 and have confirmed principle, therefore PBA will complete reverse engineered approach.</i>	
1.2.6	PBA to confirm how well used the south of Havant Road bus stop is during the AM peak in case this further supports crossing demand.	PBA to address in TA
1.3	Trip Rates	
1.3.1	HD believed trip rates are too low for general C3: Residential when compared to those put forward for One Eight Zero. PBA highlighted these rates were almost identical to those HD agreed for nearby 'Havant Road, Emsworth' application, and confirmed trip rates for care home and retirement flats were acceptable. <i>Post Meeting Note – HD and WH confirmed through email dated 01.11.16 that the care home, retirement flats and general C3 residential trip rates were acceptable.</i>	HD to provide comments on TRICS outputs – PBA received this 01.11.16 and confirmed all land trip rates were acceptable
1.4	Trip Distribution	
1.4.1	HD outlined broad agreement with percentage trip distributions, but requested further justification on increase in percentage of vehicles travelling west – Justify where the additional 10% has come from compared to 5% travel to work statistics. HD however confirmed that 15% seems reasonable.	PBA to address in TA
1.4.2	Peak hours also to be confirmed in TA.	PBA to address in TA
1.5	Traffic Impact	
1.5.1	HD requested PBA obtain traffic turning counts at Glebe Park Avenue/Bedhampton Hill/Havant Road and Auriol Drive (eastern access only)/Havant Road junctions to ensure these aren't materially affected by the proposed development. Whilst Auriol Drive western access was discussed based on distributions HD accepted that traffic impact on that junction would be minimal.	PBA to complete in TA
1.5.2	PBA to provide percentage impact on each arm of Rusty Cutter to assess the impact on Havant Road, whilst still demonstrating the average in the TA.	PBA to complete in TA
1.5.3	HD confirmed percentage traffic impact assessment required on the following junctions: • Glebe Park Avenue/Bedhampton Hill/Havant Road • Auriol Drive/Havant Road • Rusty Cutter Roundabout • A27 Tear Drop Junction • Bedhampton Hill/Portsdown Hill Road/Bedhampton Road	PBA to complete in TA
1.5.4	Modelling scope therefore dependent on 1.5.3, however HD confirmed the Rusty Cutter and A27 Tear Drop junction must be modelled.	PBA to complete in TA
1.5.5	HD to send PBA a list of application numbers of recent sites to be included in the modelling as 'committed development'.	HD to send PBA list
1.5.6	HD requested PBA assess the soon to be published HBC Housing Statement to assist with determining the potential future housing sites.	PBA to complete as part of TA

MEETING MINUTES


1.5.7	HD requires justification of access use (percentage) for access modelling, whilst also providing the modelling results for if 100% of traffic uses each access.	PBA to action in TA
1.5.8	HD confirmed that if Barratt Homes' 'One Eight Zero' scheme is treated as a committed development PBA will only need to add half of the number of trips given the site was already half built and occupied over traffic survey periods.	N/A
1.6	Access Design	
1.6.1	HD concerned about overhang of refuse vehicle on access road. HD requested a wider road or increased radius until the refuse vehicle can straighten up.	PBA to update access drawings
1.6.2	HD requested that the internal path following the northern boundary of the site, between the two site accesses is illuminated. The alternative would be to move the path to the south side of Havant Road as a footway.	PBA to assess
1.6.3	PBA to assess route to south of Havant Road bus stop, and whether a footpath can be provided (mindful of levels etc) or whether moving the bus stop may be an option through discussions with Stagecoach.	PBA to complete for TA
1.6.4	Tracking of 16.5m articulated vehicle required as part of site's full application.	PBA to complete for TA
1.6.5	HD confirmed different geometries for the two accesses would be acceptable if needed.	N/A
1.6.6	HD requested a visibility splay with a 4.5m x-distance is shown in accordance with DMRB.	PBA to update access drawings
1.6.7	HD confirmed the principle of right turn lanes are acceptable, however requested that the right turn lane is 3m wide and the two through lanes are 3.05m wide (same overall width of the road).	PBA to update drawings
1.6.8	HD requested result of speed survey to be sent separately as opposed to being in the appendix.	JL to re-send speed survey results
1.6.9	Access road levels should fall into the road, not into the site. HD confirmed 'high point' to be existing highway boundary'.	PBA to update access drawings
1.6.10	HD suggested resurfacing would be required on Havant Road where white lining is to be replaced to ensure old lining is not visible.	N/A
1.6.11	HD confirmed that pedestrian refuge island widths should be 2.4m with this dimension shown on the drawing. HD confirmed reflective bollard would be suitable for both pedestrian refuge islands.	N/A
1.7	AOB	
1.7.1	HD confirmed acceptance of PIA assessment with a 5 year assessment period.	N/A
1.7.2	HD to speak to Engineering Consultancy about the model for the Rusty Cutter and A27 Tear Drop junctions. HD to send PBA a PDF of the as-built/approved drawing for Rusty Cutter which includes the remedial measures such a signage and lining. MS confirmed PBA would require HCC's confirmation that any details that PBA/BH purchase from HCC are correct and will be supported as such by HCC through an application.	HCC to provide PBA with modelling outputs and PDF layout of Rusty Cutter and A27 Tear Drop. <i>Post</i>

MEETING MINUTES

		<i>Meeting Note – HD to confirm cost of obtaining junction layout drawings and signal timings for PBA to build models.</i>
--	--	--

These meeting minutes have been agreed by Hampshire County Council Transport Officers.

Signed by:



Jessica Lloyd
Assistant Transport Planner
Paul Basham Associates

Date: 02.11.16

Appendix C



Project Number:
041.0023

Project Name:
FORTY ACRE FARM,
BEDHAMPTON

Title:

ACCESSIBILITY MAP



paulbasham
ASSOCIATES

Paul Basham Associates Ltd
Lancaster Court
8 Barnes Wallis Road
Fareham Hampshire
PO15 5TU
T +44 (0) 1489 668134
E info@paulbashamassociates.com
W www.paulbashamassociates.com

Checked By: JL	Checked Date: 20.09.16	Scale: N/A
Drawn By: SG	Drawn Date: 09.09.16	

Appendix D

PrimeTec Data Ltd, Speed Report

Report Id - CustomList-1277

Site Name - PRIBED01

Description - A2030 HAVANT ROAD WEST OF BEDHAMPTON ROUNDABOUT

Direction - East

09 November 2015

Time	Total	Vbin 0 5	Vbin 5 10	Vbin 10 15	Vbin 15 20	Vbin 20 25	Vbin 25 30	Vbin 30 35	Vbin 35 40	Vbin 40 45	Vbin 45 50	Vbin 50 55	Vbin 55 60	Vbin 60 65	Vbin 65 70	Vbin 70 75	Vbin 75 80	Vbin 80 85	Vbin 85 100	Vbin 100 140	Mean	Vpp 85	SD	
0000	10	0	0	1	0	0	1	2	2	1	2	1	0	0	0	0	0	0	0	0	37.2	-	10.7	
0100	6	0	0	0	0	0	0	1	0	2	3	0	0	0	0	0	0	0	0	0	43.6	-	5.2	
0200	6	0	0	0	0	0	0	1	2	1	2	0	0	0	0	0	0	0	0	0	40.6	-	6.5	
0300	7	0	0	0	0	0	0	1	1	4	1	0	0	0	0	0	0	0	0	0	42.2	-	4.7	
0400	19	0	0	0	1	0	0	1	8	7	1	0	0	1	0	0	0	0	0	0	39.4	42.9	9	
0500	137	0	0	2	3	1	0	11	53	40	18	7	2	0	0	0	0	0	0	0	40.2	46.1	7.2	
0600	328	0	0	3	5	0	7	54	154	81	17	6	0	1	0	0	0	0	0	0	38.2	42.5	5.6	
0700	643	0	0	0	6	7	17	178	320	103	11	0	1	0	0	0	0	0	0	0	36.5	40.3	4.4	
0800	697	0	0	2	7	6	7	151	395	120	8	0	0	0	1	0	0	0	0	0	36.9	40.3	4.3	
0900	462	0	0	5	1	0	13	102	227	94	16	3	1	0	0	0	0	0	0	0	37.2	41.4	4.9	
1000	498	0	0	1	3	0	29	164	232	56	10	2	1	0	0	0	0	0	0	0	35.9	39.6	4.5	
1100	441	0	0	0	1	0	59	227	139	13	0	1	1	0	0	0	0	0	0	0	33.8	37.1	3.6	
1200	490	0	0	1	0	1	42	267	154	17	7	1	0	0	0	0	0	0	0	0	34.4	37.6	3.7	
1300	535	0	0	1	2	3	14	145	282	78	9	0	1	0	0	0	0	0	0	0	36.6	40	4.1	
1400	518	0	0	0	0	1	10	143	282	71	7	3	1	0	0	0	0	0	0	0	36.9	40	3.8	
1500	521	0	0	1	0	1	30	143	270	56	16	3	1	0	0	0	0	0	0	0	36.5	39.8	4.4	
1600	595	0	0	0	5	22	44	260	214	39	8	3	0	0	0	0	0	0	0	0	34.4	38.5	4.8	
1700	429	1	39	34	30	35	51	130	81	26	0	1	0	0	0	0	0	1	0	0	27.8	36.7	10.5	
1800	396	0	0	0	0	2	10	126	199	50	8	1	0	0	0	0	0	0	0	0	36.4	39.8	4	
1900	288	0	0	0	1	3	8	66	149	46	13	2	0	0	0	0	0	0	0	0	37.2	40.7	4.4	
2000	203	0	0	0	0	0	3	50	91	44	10	3	0	2	0	0	0	0	0	0	38.2	42.5	5.1	
2100	124	0	0	0	0	0	7	32	59	17	5	3	1	0	0	0	0	0	0	0	37.5	42.3	5.3	
2200	107	0	0	0	1	2	0	22	53	21	4	4	0	0	0	0	0	0	0	0	37.9	41.8	5.4	
2300	32	0	0	0	0	0	3	9	6	11	2	0	0	1	0	0	0	0	0	0	38.2	42.3	7	
00-06	185	0	0	3	4	1	1	17	66	55	27	8	2	1	0	0	0	0	0	0	40.2	46.5	7.5	
06-09	1668	0	0	5	18	13	31	383	869	304	36	6	1	1	1	0	0	0	0	0	37	40.7	4.7	
09-15	2944	0	0	8	7	5	167	1048	1316	329	49	10	5	0	0	0	0	0	0	0	35.8	39.6	4.3	
15-19	1941	1	39	35	35	60	135	659	764	171	32	8	1	0	0	0	0	1	0	0	33.9	38.9	7.2	
19-00	754	0	0	0	2	5	21	179	358	139	34	12	1	3	0	0	0	0	0	0	37.7	41.6	5	
00-00	7492	1	39	51	66	84	355	2286	3373	998	178	44	10	5	1	0	0	1	0	0	35.9	40	5.6	

PrimeTec Data Ltd, Speed Report

Report Id - CustomList-1277

Site Name - PRIBED01

Description - A2030 HAVANT ROAD WEST OF BEDHAMPTON ROUNDABOUT

Direction - East

10 November 2015

Time	Total	Vbin 0 5	Vbin 5 10	Vbin 10 15	Vbin 15 20	Vbin 20 25	Vbin 25 30	Vbin 30 35	Vbin 35 40	Vbin 40 45	Vbin 45 50	Vbin 50 55	Vbin 55 60	Vbin 60 65	Vbin 65 70	Vbin 70 75	Vbin 75 80	Vbin 80 85	Vbin 85 100	Vbin 100 140	Mean	Vpp 85	SD	
0000	16	0	0	0	2	0	0	2	7	4	0	0	0	0	1	0	0	0	0	0	37.4	42.9	11.2	
0100	13	0	0	0	1	0	0	2	0	9	0	1	0	0	0	0	0	0	0	0	39.8	43.6	8.2	
0200	7	0	0	0	0	1	1	1	1	3	0	0	0	0	0	0	0	0	0	0	36.3	-	8.7	
0300	8	0	0	0	0	0	0	1	2	3	0	2	0	0	0	0	0	0	0	0	42.8	-	6.2	
0400	21	0	0	0	0	0	0	1	9	6	2	1	2	0	0	0	0	0	0	0	41.9	46.5	6.4	
0500	145	0	0	2	3	2	0	6	49	51	18	9	4	0	0	1	0	0	0	0	41	46.5	8	
0600	347	0	0	2	6	3	3	59	181	70	19	3	1	0	0	0	0	0	0	0	37.7	42.1	5.4	
0700	645	0	0	0	5	7	7	204	329	76	12	2	2	0	1	0	0	0	0	0	36.4	39.8	4.5	
0800	689	0	0	1	8	5	29	208	332	94	8	2	1	0	1	0	0	0	0	0	36.1	40	4.7	
0900	488	0	0	2	0	1	12	119	269	75	9	1	0	0	0	0	0	0	0	0	36.8	40.3	4	
1000	458	0	0	3	2	1	29	155	206	52	9	1	0	0	0	0	0	0	0	0	35.7	39.6	4.5	
1100	481	0	0	0	1	0	28	166	231	49	6	0	0	0	0	0	0	0	0	0	35.8	39.4	3.6	
1200	464	0	0	0	0	0	23	138	223	67	8	4	1	0	0	0	0	0	0	0	36.6	40.3	4.2	
1300	486	0	0	0	2	1	15	165	254	43	4	2	0	0	0	0	0	0	0	0	36.1	39.1	3.7	
1400	476	0	0	3	1	2	8	164	237	55	3	2	0	1	0	0	0	0	0	0	36.1	39.4	4.3	
1500	568	0	0	2	1	3	45	195	248	66	7	1	0	0	0	0	0	0	0	0	35.5	39.6	4.4	
1600	589	2	30	21	23	17	58	217	179	38	2	2	0	0	0	0	0	0	0	0	31.3	37.6	8.7	
1700	391	0	3	24	11	34	72	135	91	17	3	0	0	0	0	0	0	0	0	1	30.8	37.1	8.7	
1800	507	0	0	0	4	1	30	186	238	40	5	3	0	0	0	0	0	0	0	0	35.5	38.9	4.2	
1900	299	0	0	0	0	2	20	99	126	44	6	1	1	0	0	0	0	0	0	0	36.3	40.7	4.5	
2000	181	0	0	0	1	0	9	48	73	43	7	0	0	0	0	0	0	0	0	0	37.1	41.4	4.5	
2100	181	0	0	0	0	0	10	54	82	28	4	1	2	0	0	0	0	0	0	0	36.5	40.5	4.7	
2200	99	0	0	2	0	0	5	28	39	18	4	2	1	0	0	0	0	0	0	0	37.2	42.1	6.1	
2300	47	0	0	0	1	0	2	9	19	5	9	1	1	0	0	0	0	0	0	0	38.9	45.6	7	
00-06	210	0	0	2	6	3	1	13	68	76	20	13	6	0	1	1	0	0	0	0	40.7	46.5	8.1	
06-09	1681	0	0	3	19	15	39	471	842	240	39	7	4	0	2	0	0	0	0	0	36.6	40.3	4.8	
09-15	2853	0	0	8	6	5	115	907	1420	341	39	10	1	1	0	0	0	0	0	0	36.2	39.6	4.1	
15-19	2055	2	33	47	39	55	205	733	756	161	17	6	0	0	0	0	0	0	0	1	33.4	38.7	7.1	
19-00	807	0	0	2	2	2	46	238	339	138	30	5	5	0	0	0	0	0	0	0	36.8	41.4	5	
00-00	7606	2	33	62	72	80	406	2362	3425	956	145	41	16	1	3	1	0	0	0	1	35.7	40	5.7	

PrimeTec Data Ltd, Speed Report

Report Id - CustomList-1277

Site Name - PRIBED01

Description - A2030 HAVANT ROAD WEST OF BEDHAMPTON ROUNDABOUT

Direction - East

11 November 2015

Time	Total	Vbin 0 5	Vbin 5 10	Vbin 10 15	Vbin 15 20	Vbin 20 25	Vbin 25 30	Vbin 30 35	Vbin 35 40	Vbin 40 45	Vbin 45 50	Vbin 50 55	Vbin 55 60	Vbin 60 65	Vbin 65 70	Vbin 70 75	Vbin 75 80	Vbin 80 85	Vbin 85 100	Vbin 100 140	Mean	Vpp 85	SD	
0000	23	0	0	1	0	0	0	5	5	6	3	0	1	0	2	0	0	0	0	0	41.2	47.6	11.9	
0100	7	0	0	1	0	0	0	1	2	3	0	0	0	0	0	0	0	0	0	0	35.4	-	10.5	
0200	5	0	0	0	0	1	0	0	2	0	2	0	0	0	0	0	0	0	0	0	38.3	-	9.7	
0300	5	0	0	0	0	0	0	2	1	1	1	0	0	0	0	0	0	0	0	0	39	-	7.5	
0400	22	0	0	1	1	0	0	2	5	6	5	2	0	0	0	0	0	0	0	0	40.2	49.4	10	
0500	148	0	0	2	1	0	1	11	56	38	19	16	2	1	0	0	0	1	0	0	41.5	48.1	7.8	
0600	333	0	0	1	7	0	1	42	163	85	26	2	4	2	0	0	0	0	0	0	39	43.4	5.7	
0700	655	0	0	1	5	4	8	184	337	98	16	1	1	0	0	0	0	0	0	0	36.7	40.3	4.4	
0800	705	0	0	2	1	1	13	242	357	78	9	0	0	1	0	1	0	0	0	0	36.2	39.4	4	
0900	498	0	0	4	3	0	18	145	238	77	9	3	0	1	0	0	0	0	0	0	36.5	40.3	4.9	
1000	494	0	0	0	3	0	10	178	225	62	13	3	0	0	0	0	0	0	0	0	36.3	40	4.1	
1100	482	0	0	0	0	3	19	122	254	77	6	1	0	0	0	0	0	0	0	0	36.6	40.3	3.8	
1200	514	0	0	2	2	1	7	159	263	73	7	0	0	0	0	0	0	0	0	0	36.3	40	3.9	
1300	500	0	0	1	1	1	15	155	280	40	7	0	0	0	0	0	0	0	0	0	36.1	39.4	3.7	
1400	530	0	0	1	0	0	14	184	254	70	7	0	0	0	0	0	0	0	0	0	36.2	39.8	3.7	
1500	532	0	0	1	2	1	21	211	214	74	7	1	0	0	0	0	0	0	0	0	35.8	40	4.2	
1600	559	0	0	0	5	3	39	223	239	47	2	1	0	0	0	0	0	0	0	0	35.1	38.5	4.1	
1700	448	0	0	3	4	10	29	160	196	35	9	2	0	0	0	0	0	0	0	0	34.9	38.9	5.2	
1800	409	0	0	1	5	2	15	144	185	47	8	2	0	0	0	0	0	0	0	0	35.8	39.8	4.6	
1900	300	0	0	0	1	0	9	85	138	51	9	6	1	0	0	0	0	0	0	0	37.3	41.4	4.9	
2000	194	0	0	0	2	1	5	36	95	42	11	2	0	0	0	0	0	0	0	0	37.8	42.3	5	
2100	146	0	0	0	1	0	2	35	65	29	10	2	1	1	0	0	0	0	0	0	38.1	43.2	5.6	
2200	116	0	0	1	3	0	0	24	57	14	10	4	3	0	0	0	0	0	0	0	38	44.7	7.1	
2300	50	0	0	1	1	1	3	11	20	7	5	0	0	1	0	0	0	0	0	0	36.7	40.5	7.6	
00-06	210	0	0	5	2	1	1	21	71	54	30	18	3	1	2	0	0	1	0	0	41	48.8	8.7	
06-09	1693	0	0	4	13	5	22	468	857	261	51	3	5	3	0	1	0	0	0	0	37	40.5	4.6	
09-15	3018	0	0	8	9	5	83	943	1514	399	49	7	0	1	0	0	0	0	0	0	36.3	39.8	4	
15-19	1948	0	0	5	16	16	104	738	834	203	26	6	0	0	0	0	0	0	0	0	35.4	39.1	4.5	
19-00	806	0	0	2	8	2	19	191	375	143	45	14	5	2	0	0	0	0	0	0	37.6	42.3	5.6	
00-00	7675	0	0	24	48	29	229	2361	3651	1060	201	48	13	7	2	1	0	1	0	0	36.5	40.3	4.8	

PrimeTec Data Ltd, Speed Report

Report Id - CustomList-1277

Site Name - PRIBED01

Description - A2030 HAVANT ROAD WEST OF BEDHAMPTON ROUNDABOUT

Direction - East

12 November 2015

Time	Total	Vbin 0 5	Vbin 5 10	Vbin 10 15	Vbin 15 20	Vbin 20 25	Vbin 25 30	Vbin 30 35	Vbin 35 40	Vbin 40 45	Vbin 45 50	Vbin 50 55	Vbin 55 60	Vbin 60 65	Vbin 65 70	Vbin 70 75	Vbin 75 80	Vbin 80 85	Vbin 85 100	Vbin 100 140	Mean	Vpp 85	SD	
0000	14	0	0	1	0	1	1	2	4	2	1	0	2	0	0	0	0	0	0	0	38.1	45.4	12.1	
0100	6	0	0	1	1	0	0	1	1	0	1	0	0	1	0	0	0	0	0	0	34.8	-	18.2	
0200	9	0	0	0	0	0	0	0	4	4	1	0	0	0	0	0	0	0	0	0	41.3	-	3.9	
0300	7	0	0	0	0	0	0	0	3	0	4	0	0	0	0	0	0	0	0	0	43	-	6.1	
0400	21	0	0	0	0	0	0	3	4	6	6	1	1	0	0	0	0	0	0	0	42.6	48.3	6.5	
0500	128	0	0	3	1	0	0	11	42	38	21	8	2	1	1	0	0	0	0	0	41	47.2	8	
0600	340	0	0	5	1	1	0	57	182	66	19	8	0	1	0	0	0	0	0	0	38.1	42.5	5.4	
0700	645	0	0	2	7	4	7	161	354	98	8	2	1	0	1	0	0	0	0	0	36.7	40.3	4.5	
0800	662	0	0	2	7	2	12	196	327	105	9	2	0	0	0	0	0	0	0	0	36.5	40.3	4.3	
0900	539	0	2	4	1	3	14	204	235	68	8	0	0	0	0	0	0	0	0	0	35.7	39.8	4.6	
1000	483	0	0	0	3	0	12	170	234	52	8	2	1	0	1	0	0	0	0	0	36.2	39.6	4.3	
1100	496	0	0	1	2	0	12	157	229	83	10	0	0	2	0	0	0	0	0	0	36.8	40.9	4.5	
1200	479	0	0	1	0	0	29	133	245	59	9	3	0	0	0	0	0	0	0	0	36.4	39.8	4.1	
1300	507	0	0	0	1	0	15	144	277	59	8	1	2	0	0	0	0	0	0	0	36.5	39.6	3.9	
1400	533	0	0	0	0	1	16	157	279	67	11	1	0	0	0	0	1	0	0	0	36.7	39.8	4.2	
1500	558	0	0	2	1	1	21	204	253	65	9	0	0	2	0	0	0	0	0	0	36	39.6	4.2	
1600	566	1	22	38	8	13	52	201	190	39	2	0	0	0	0	0	0	0	0	0	31.7	38	8.7	
1700	473	0	0	0	6	1	33	204	182	39	8	0	0	0	0	0	0	0	0	0	35	38.9	4.4	
1800	405	0	0	1	5	1	19	138	188	41	11	0	1	0	0	0	0	0	0	0	35.9	39.6	4.7	
1900	293	0	0	1	0	0	10	90	145	36	11	0	0	0	0	0	0	0	0	0	36.4	40	4.2	
2000	162	0	0	0	0	0	4	44	77	28	8	1	0	0	0	0	0	0	0	0	37.4	41.8	4.3	
2100	117	0	0	0	0	0	5	32	50	25	3	0	0	2	0	0	0	0	0	0	37.6	41.6	5.4	
2200	128	0	0	1	1	0	5	30	59	19	8	5	0	0	0	0	0	0	0	0	37.6	42.5	5.9	
2300	65	0	0	0	0	1	3	13	31	12	5	0	0	0	0	0	0	0	0	0	37.6	41.8	5.2	
00-06	185	0	0	5	2	1	1	17	58	50	34	9	5	2	1	0	0	0	0	0	40.8	47.9	8.5	
06-09	1647	0	0	9	15	7	19	414	863	269	36	12	1	1	1	0	0	0	0	0	36.9	40.5	4.7	
09-15	3037	0	2	6	7	4	98	965	1499	388	54	7	3	2	1	0	1	0	0	0	36.4	39.8	4.3	
15-19	2002	1	22	41	20	16	125	747	813	184	30	0	1	2	0	0	0	0	0	0	34.5	39.1	6.2	
19-00	765	0	0	2	1	1	27	209	362	120	35	6	0	2	0	0	0	0	0	0	37.1	41.4	4.8	
00-00	7636	1	24	63	45	29	270	2352	3595	1011	189	34	10	9	3	0	1	0	0	0	36.2	40	5.3	

PrimeTec Data Ltd, Speed Report

Report Id - CustomList-1277

Site Name - PRIBED01

Description - A2030 HAVANT ROAD WEST OF BEDHAMPTON ROUNDABOUT

Direction - East

13 November 2015

Time	Total	Vbin 0 5	Vbin 5 10	Vbin 10 15	Vbin 15 20	Vbin 20 25	Vbin 25 30	Vbin 30 35	Vbin 35 40	Vbin 40 45	Vbin 45 50	Vbin 50 55	Vbin 55 60	Vbin 60 65	Vbin 65 70	Vbin 70 75	Vbin 75 80	Vbin 80 85	Vbin 85 100	Vbin 100 140	Mean	Vpp 85	SD	
0000	25	0	0	1	1	0	1	3	8	7	3	1	0	0	0	0	0	0	0	0	37.4	43.8	8.7	
0100	6	0	0	0	0	0	0	2	1	1	2	0	0	0	0	0	0	0	0	0	39.7	-	6.8	
0200	10	0	0	0	0	0	0	0	0	7	0	1	2	0	0	0	0	0	0	0	46.4	-	6.7	
0300	5	0	0	0	0	0	0	0	2	3	0	0	0	0	0	0	0	0	0	0	39.8	-	2.8	
0400	26	0	0	0	0	1	1	2	3	9	5	4	0	1	0	0	0	0	0	0	42.8	51.2	8	
0500	113	0	0	1	2	0	1	8	37	31	12	13	4	1	1	0	0	0	2	0	42.9	52.3	10.7	
0600	314	0	0	0	6	1	7	72	126	80	19	3	0	0	0	0	0	0	0	0	37.6	42.3	5.4	
0700	599	0	0	0	5	5	11	119	347	97	10	4	0	1	0	0	0	0	0	0	37.2	40.7	4.4	
0800	664	0	0	3	6	3	8	179	347	102	15	1	0	0	0	0	0	0	0	0	36.6	40.3	4.4	
0900	532	0	0	2	2	2	11	156	280	67	7	5	0	0	0	0	0	0	0	0	36.5	39.8	4.3	
1000	550	0	0	0	1	0	12	169	290	70	5	3	0	0	0	0	0	0	0	0	36.4	39.8	3.6	
1100	497	0	0	0	0	1	13	137	265	69	9	3	0	0	0	0	0	0	0	0	36.7	40.3	3.7	
1200	544	0	0	1	0	7	8	156	237	116	15	2	1	0	0	1	0	0	0	0	37.1	41.4	4.6	
1300	529	0	0	0	1	1	11	103	265	114	28	4	1	1	0	0	0	0	0	0	38	41.8	4.4	
1400	566	0	0	1	0	4	10	130	285	118	15	1	1	1	0	0	0	0	0	0	37.4	41.2	4.2	
1500	611	0	0	1	2	0	15	196	295	90	10	2	0	0	0	0	0	0	0	0	36.5	40	4	
1600	548	0	0	0	0	2	44	193	223	80	5	0	1	0	0	0	0	0	0	0	35.7	40	4.1	
1700	486	0	0	0	4	1	31	164	226	44	14	1	1	0	0	0	0	0	0	0	36	39.4	4.5	
1800	444	0	0	1	2	0	11	147	215	58	6	2	2	0	0	0	0	0	0	0	36.4	39.8	4.2	
1900	322	0	0	0	1	1	15	88	147	56	13	1	0	0	0	0	0	0	0	0	36.9	41.2	4.6	
2000	190	0	0	1	0	4	7	43	92	29	10	1	2	0	0	0	0	1	0	0	37.5	41.6	6.3	
2100	147	0	1	0	0	0	10	43	59	29	4	1	0	0	0	0	0	0	0	0	36.3	40.9	5.4	
2200	114	0	0	0	0	1	5	23	55	22	5	1	1	0	0	0	0	1	0	0	38	41.6	6.3	
2300	80	0	0	0	0	0	0	16	29	25	6	3	1	0	0	0	0	0	0	0	39.7	43.8	5.4	
00-06	185	0	0	2	3	1	3	15	51	58	22	19	6	2	1	0	0	0	2	0	42.1	49.9	9.8	
06-09	1577	0	0	3	17	9	26	370	820	279	44	8	0	1	0	0	0	0	0	0	37	40.9	4.6	
09-15	3218	0	0	4	4	15	65	851	1622	554	79	18	3	2	0	1	0	0	0	0	37	40.7	4.2	
15-19	2089	0	0	2	8	3	101	700	959	272	35	5	4	0	0	0	0	0	0	0	36.1	39.8	4.2	
19-00	853	0	1	1	1	6	37	213	382	161	38	7	4	0	0	0	0	2	0	0	37.4	41.6	5.5	
00-00	7922	0	1	12	33	34	232	2149	3834	1324	218	57	17	5	1	1	0	2	2	0	36.9	40.9	4.7	

PrimeTec Data Ltd, Speed Report

Report Id - CustomList-1277

Site Name - PRIBED01

Description - A2030 HAVANT ROAD WEST OF BEDHAMPTON ROUNDABOUT

Direction - West

09 November 2015

Time	Total	Vbin 0 5	Vbin 5 10	Vbin 10 15	Vbin 15 20	Vbin 20 25	Vbin 25 30	Vbin 30 35	Vbin 35 40	Vbin 40 45	Vbin 45 50	Vbin 50 55	Vbin 55 60	Vbin 60 65	Vbin 65 70	Vbin 70 75	Vbin 75 80	Vbin 80 85	Vbin 85 100	Vbin 100 140	Mean	Vpp 85	SD	
0000	23	0	0	0	1	0	1	2	7	5	4	2	0	1	0	0	0	0	0	0	41.3	49.4	9.5	
0100	7	0	0	0	0	0	0	1	2	4	0	0	0	0	0	0	0	0	0	0	39 -		4	
0200	1	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0	0	41.7 -	-		
0300	6	0	0	0	1	0	0	4	0	1	0	0	0	0	0	0	0	0	0	0	32 -		9.2	
0400	21	0	1	0	0	0	2	1	9	5	0	3	0	0	0	0	0	0	0	0	38.3	43.4	9.5	
0500	58	0	0	0	3	0	1	12	16	15	6	4	1	0	0	0	0	0	0	0	39.1	45.4	8.1	
0600	188	0	0	2	3	0	6	45	64	38	15	8	4	2	0	0	1	0	0	0	38.7	45.2	8.1	
0700	449	0	0	1	0	0	13	171	207	39	11	6	1	0	0	0	0	0	0	0	36	39.1	4.3	
0800	481	0	0	1	2	1	41	160	200	61	9	5	0	1	0	0	0	0	0	0	36	40	4.9	
0900	434	0	0	0	0	0	27	187	167	36	12	4	1	0	0	0	0	0	0	0	35.5	39.1	4.3	
1000	453	0	0	1	0	6	57	172	151	46	15	4	1	0	0	0	0	0	0	0	35.1	39.8	5.2	
1100	425	0	0	1	0	19	127	156	100	22	0	0	0	0	0	0	0	0	0	0	32.2	36.9	4.6	
1200	415	0	0	0	2	10	121	167	84	22	9	0	0	0	0	0	0	0	0	0	32.5	36.9	4.9	
1300	483	0	0	0	0	4	46	186	188	50	6	3	0	0	0	0	0	0	0	0	35.3	39.4	4.3	
1400	560	0	0	0	0	2	71	220	205	51	10	1	0	0	0	0	0	0	0	0	34.8	39.1	4.3	
1500	554	0	0	0	1	8	44	243	206	45	5	1	0	0	1	0	0	0	0	0	34.7	38.7	4.3	
1600	694	0	0	0	2	18	146	312	163	42	8	2	1	0	0	0	0	0	0	0	33.2	37.8	4.8	
1700	651	3	5	1	3	22	114	318	159	21	4	1	0	0	0	0	0	0	0	0	32.5	36.9	5.3	
1800	439	0	0	3	1	4	49	176	159	35	11	1	0	0	0	0	0	0	0	0	34.7	38.9	4.8	
1900	321	0	1	0	0	1	15	112	139	40	11	2	0	0	0	0	0	0	0	0	36.1	40	4.7	
2000	205	0	0	0	1	0	14	51	93	33	9	2	0	1	0	0	1	0	0	0	37.5	42.1	6	
2100	141	0	0	0	0	0	7	35	52	37	8	2	0	0	0	0	0	0	0	0	37.8	42.1	4.7	
2200	85	0	0	0	0	0	5	17	26	25	8	1	2	0	0	1	0	0	0	0	39.5	44.5	6.8	
2300	35	0	0	0	0	0	1	9	6	12	4	1	1	0	1	0	0	0	0	0	40.6	45	7.6	
00-06	116	0	1	0	5	0	4	20	34	31	10	9	1	1	0	0	0	0	0	0	39	45.6	8.6	
06-09	1118	0	0	4	5	1	60	376	471	138	35	19	5	3	0	0	1	0	0	0	36.5	40.5	5.4	
09-15	2770	0	0	2	2	41	449	1088	895	227	52	12	2	0	0	0	0	0	0	0	34.3	38.7	4.8	
15-19	2338	3	5	4	7	52	353	1049	687	143	28	5	1	0	1	0	0	0	0	0	33.6	38	4.9	
19-00	787	0	1	0	1	1	42	224	316	147	40	8	3	1	1	1	1	0	0	0	37.3	42.1	5.6	
00-00	7129	3	7	10	20	95	908	2757	2403	686	165	53	12	5	2	1	2	0	0	0	34.8	39.4	5.3	

PrimeTec Data Ltd, Speed Report

Report Id - CustomList-1277

Site Name - PRIBED01

Description - A2030 HAVANT ROAD WEST OF BEDHAMPTON ROUNDABOUT

Direction - West

10 November 2015

Time	Total	Vbin 0 5	Vbin 5 10	Vbin 10 15	Vbin 15 20	Vbin 20 25	Vbin 25 30	Vbin 30 35	Vbin 35 40	Vbin 40 45	Vbin 45 50	Vbin 50 55	Vbin 55 60	Vbin 60 65	Vbin 65 70	Vbin 70 75	Vbin 75 80	Vbin 80 85	Vbin 85 100	Vbin 100 140	Mean	Vpp 85	SD	
0000	14	0	0	0	0	0	2	4	3	3	2	0	0	0	0	0	0	0	0	0	37.7	42.7	7.1	
0100	10	0	1	0	0	0	0	2	3	3	1	0	0	0	0	0	0	0	0	0	36.5	-	10.8	
0200	3	0	0	0	0	0	0	0	0	2	0	1	0	0	0	0	0	0	0	0	46.1	-	5.6	
0300	6	0	0	1	0	0	0	1	0	3	0	0	0	1	0	0	0	0	0	0	38.9	-	16.8	
0400	22	0	0	0	0	0	1	5	3	7	3	2	0	1	0	0	0	0	0	0	41.3	49.4	7.6	
0500	54	0	0	2	0	0	4	5	15	17	5	2	4	0	0	0	0	0	0	0	39.9	48.5	8.8	
0600	175	0	0	0	2	0	7	61	64	26	13	2	0	0	0	0	0	0	0	0	36.9	42.5	5.6	
0700	477	0	0	3	0	0	60	191	166	41	6	7	0	2	1	0	0	0	0	0	35	39.1	5.4	
0800	476	0	0	1	6	7	45	184	164	55	9	4	1	0	0	0	0	0	0	0	35	39.6	5.3	
0900	456	0	0	0	1	5	54	176	176	35	4	3	1	0	0	1	0	0	0	0	35	38.7	4.8	
1000	437	0	0	0	0	1	30	173	172	48	11	2	0	0	0	0	0	0	0	0	35.6	39.6	4.3	
1100	472	0	0	0	1	2	51	212	157	40	8	1	0	0	0	0	0	0	0	0	34.7	38.9	4.2	
1200	462	0	0	0	0	0	26	180	187	53	14	2	0	0	0	0	0	0	0	0	35.9	39.8	4.2	
1300	467	0	0	0	0	0	33	173	183	62	10	5	1	0	0	0	0	0	0	0	36	40.3	4.7	
1400	510	0	0	0	0	0	19	242	191	45	12	1	0	0	0	0	0	0	0	0	35.4	39.1	3.9	
1500	558	0	0	0	0	3	35	229	223	51	14	2	1	0	0	0	0	0	0	0	35.5	39.1	4.2	
1600	645	0	2	2	0	17	119	282	190	21	11	1	0	0	0	0	0	0	0	0	33.2	37.4	4.7	
1700	660	0	0	3	2	24	114	280	196	33	5	2	1	0	0	0	0	0	0	0	33.3	37.6	4.8	
1800	455	0	0	0	0	1	42	215	137	51	8	1	0	0	0	0	0	0	0	0	34.9	39.6	4.3	
1900	347	0	0	1	1	0	27	125	135	39	11	6	1	0	1	0	0	0	0	0	36	40.3	5.4	
2000	197	0	0	0	0	0	12	53	86	33	8	4	1	0	0	0	0	0	0	0	37.3	41.4	4.9	
2100	170	0	0	0	1	0	4	52	81	20	9	2	0	0	0	1	0	0	0	0	37.2	41.6	5.3	
2200	125	0	0	1	0	1	3	32	58	21	5	4	0	0	0	0	0	0	0	0	37.4	42.3	5.6	
2300	41	0	0	1	0	0	1	9	18	6	2	4	0	0	0	0	0	0	0	0	38	44.3	7.6	
00-06	109	0	1	3	0	0	7	17	24	35	11	5	4	2	0	0	0	0	0	0	39.7	48.8	9	
06-09	1128	0	0	4	8	7	112	436	394	122	28	13	1	2	1	0	0	0	0	0	35.3	39.8	5.4	
09-15	2804	0	0	0	2	8	213	1156	1066	283	59	14	2	0	0	1	0	0	0	0	35.4	39.4	4.4	
15-19	2318	0	2	5	2	45	310	1006	746	156	38	6	2	0	0	0	0	0	0	0	34.1	38.3	4.7	
19-00	880	0	0	3	2	1	47	271	378	119	35	20	2	0	1	1	0	0	0	0	36.8	41.2	5.4	
00-00	7239	0	3	15	14	61	689	2886	2608	715	171	58	11	4	2	2	0	0	0	0	35.2	39.4	5	

PrimeTec Data Ltd, Speed Report

Report Id - CustomList-1277

Site Name - PRIBED01

Description - A2030 HAVANT ROAD WEST OF BEDHAMPTON ROUNDABOUT

Direction - West

11 November 2015

Time	Total	Vbin 0 5	Vbin 5 10	Vbin 10 15	Vbin 15 20	Vbin 20 25	Vbin 25 30	Vbin 30 35	Vbin 35 40	Vbin 40 45	Vbin 45 50	Vbin 50 55	Vbin 55 60	Vbin 60 65	Vbin 65 70	Vbin 70 75	Vbin 75 80	Vbin 80 85	Vbin 85 100	Vbin 100 140	Mean	Vpp 85	SD	
0000	20	0	0	0	0	0	0	5	7	4	3	1	0	0	0	0	0	0	0	0	39.5	48.3	6.4	
0100	7	0	0	0	0	0	1	3	2	1	0	0	0	0	0	0	0	0	0	0	36 -		4.4	
0200	4	0	0	0	0	0	0	1	1	1	0	1	0	0	0	0	0	0	0	0	42 -		8.7	
0300	5	0	0	0	1	0	0	1	0	1	0	1	1	0	0	0	0	0	0	0	40.2 -		16.6	
0400	22	0	1	2	0	0	1	5	4	8	1	0	0	0	0	0	0	0	0	0	34.2	41.4	10.1	
0500	71	0	0	2	0	0	3	10	31	12	8	2	2	1	0	0	0	0	0	0	38.9	45.6	7.9	
0600	172	0	0	0	3	1	11	47	59	31	15	3	1	1	0	0	0	0	0	0	37.4	43.6	6.5	
0700	468	0	0	3	2	3	50	162	173	60	7	3	3	2	0	0	0	0	0	0	35.5	40	5.6	
0800	521	0	0	0	2	3	73	179	197	45	14	5	2	1	0	0	0	0	0	0	35.1	39.4	5.3	
0900	444	0	0	1	1	3	42	166	168	48	11	4	0	0	0	0	0	0	0	0	35.5	39.8	4.8	
1000	459	0	0	0	0	0	46	182	175	40	13	2	1	0	0	0	0	0	0	0	35.5	39.6	4.5	
1100	449	0	0	0	0	0	28	179	186	44	9	3	0	0	0	0	0	0	0	0	35.6	39.4	4.1	
1200	521	0	0	0	0	1	35	209	216	49	6	3	1	1	0	0	0	0	0	0	35.5	38.9	4.2	
1300	466	0	0	0	0	0	38	186	177	49	13	2	1	0	0	0	0	0	0	0	35.6	39.4	4.4	
1400	541	1	0	0	0	0	22	232	206	59	13	6	1	1	0	0	0	0	0	0	35.9	39.8	4.6	
1500	575	0	0	0	1	3	43	280	187	49	9	2	1	0	0	0	0	0	0	0	34.9	38.9	4.3	
1600	716	0	0	1	1	29	129	334	172	35	11	0	2	2	0	0	0	0	0	0	33.3	37.1	4.9	
1700	683	0	0	1	2	12	151	328	149	29	11	0	0	0	0	0	0	0	0	0	32.9	36.9	4.5	
1800	510	0	0	2	2	1	51	220	164	57	5	7	1	0	0	0	0	0	0	0	35.2	39.6	5	
1900	325	1	0	0	1	0	19	104	141	49	5	3	1	1	0	0	0	0	0	0	36.1	40.5	5.1	
2000	194	0	0	0	0	0	6	57	82	36	11	2	0	0	0	0	0	0	0	0	37.6	41.2	4.5	
2100	165	0	0	0	0	1	4	49	62	28	11	9	0	0	1	0	0	0	0	0	38.1	43.4	6.4	
2200	106	0	0	0	0	0	4	23	38	21	14	4	2	0	0	0	0	0	0	0	39.3	46.3	6.3	
2300	57	0	0	0	0	0	1	10	21	13	7	2	1	2	0	0	0	0	0	0	40.6	46.3	7.3	
00-06	129	0	1	4	1	0	5	25	45	27	12	5	3	1	0	0	0	0	0	0	38.2	45.6	8.5	
06-09	1161	0	0	3	7	7	134	388	429	136	36	11	6	4	0	0	0	0	0	0	35.6	40.5	5.6	
09-15	2880	1	0	1	1	4	211	1154	1128	289	65	20	4	2	0	0	0	0	0	0	35.6	39.4	4.5	
15-19	2484	0	0	4	6	45	374	1162	672	170	36	9	4	2	0	0	0	0	0	0	34	38.3	4.8	
19-00	847	1	0	0	1	1	34	243	344	147	48	20	4	3	1	0	0	0	0	0	37.5	42.5	5.7	
00-00	7501	2	1	12	16	57	758	2972	2618	769	197	65	21	12	1	0	0	0	0	0	35.3	39.6	5.1	

PrimeTec Data Ltd, Speed Report

Report Id - CustomList-1277

Site Name - PRIBED01

Description - A2030 HAVANT ROAD WEST OF BEDHAMPTON ROUNDABOUT

Direction - West

12 November 2015

Time	Total	Vbin 0 5	Vbin 5 10	Vbin 10 15	Vbin 15 20	Vbin 20 25	Vbin 25 30	Vbin 30 35	Vbin 35 40	Vbin 40 45	Vbin 45 50	Vbin 50 55	Vbin 55 60	Vbin 60 65	Vbin 65 70	Vbin 70 75	Vbin 75 80	Vbin 80 85	Vbin 85 100	Vbin 100 140	Mean	Vpp 85	SD	
0000	30	0	0	1	0	0	3	9	7	4	4	1	1	0	0	0	0	0	0	0	36.9	46.5	9	
0100	7	0	0	0	0	0	0	0	2	4	0	1	0	0	0	0	0	0	0	0	42.8	-	3.9	
0200	4	0	0	0	0	0	0	0	1	2	0	1	0	0	0	0	0	0	0	0	43.6	-	6.8	
0300	8	0	0	0	2	0	0	3	1	0	2	0	0	0	0	0	0	0	0	0	33.2	-	12.9	
0400	17	0	0	0	0	0	0	1	4	9	0	2	0	0	1	0	0	0	0	0	42.9	43.8	8	
0500	66	0	0	2	2	0	5	14	23	7	8	4	1	0	0	0	0	0	0	0	37.6	45.9	8.8	
0600	187	0	0	2	0	0	10	50	65	30	22	5	2	1	0	0	0	0	0	0	38.3	45	6.6	
0700	481	0	0	1	4	1	44	162	192	61	9	3	2	2	0	0	0	0	0	0	35.7	40	5.3	
0800	495	0	0	0	0	2	19	185	205	70	11	1	2	0	0	0	0	0	0	0	36.2	40.5	4.2	
0900	466	0	1	0	0	1	31	163	199	52	15	3	1	0	0	0	0	0	0	0	35.9	39.8	4.7	
1000	497	0	0	0	0	2	30	189	206	59	7	2	2	0	0	0	0	0	0	0	35.8	39.6	4.3	
1100	463	0	0	0	0	0	13	163	213	55	13	4	2	0	0	0	0	0	0	0	36.5	40	4.3	
1200	454	0	0	0	0	0	38	150	178	64	17	6	1	0	0	0	0	0	0	0	36.4	40.7	4.9	
1300	501	0	0	0	1	6	54	172	197	55	14	2	0	0	0	0	0	0	0	0	35.4	39.8	4.7	
1400	503	0	0	0	0	0	30	169	210	80	9	4	1	0	0	0	0	0	0	0	36.3	40.5	4.5	
1500	576	0	0	0	0	2	77	222	195	57	21	2	0	0	0	0	0	0	0	0	35.1	39.6	4.8	
1600	687	0	3	6	2	20	121	281	192	48	8	2	3	1	0	0	0	0	0	0	33.4	38	5.8	
1700	637	0	0	0	2	7	93	266	224	37	6	1	0	0	1	0	0	0	0	0	34.2	38	4.5	
1800	468	0	0	1	1	1	50	187	183	35	7	1	1	1	0	0	0	0	0	0	34.9	38.7	4.6	
1900	368	0	0	0	0	0	14	131	157	49	14	3	0	0	0	0	0	0	0	0	36.6	40.3	4.3	
2000	227	0	0	0	0	0	10	71	90	39	13	2	1	1	0	0	0	0	0	0	37.2	41.4	5.2	
2100	162	0	0	0	1	0	6	44	81	20	8	2	0	0	0	0	0	0	0	0	37.1	40.9	4.6	
2200	86	0	0	0	0	0	1	22	40	17	6	0	0	0	0	0	0	0	0	0	38	41.6	4.5	
2300	54	0	0	0	0	0	2	8	18	18	4	4	0	0	0	0	0	0	0	0	40	44.7	5.6	
00-06	132	0	0	3	4	0	8	27	38	26	14	9	2	0	1	0	0	0	0	0	38.3	47	9	
06-09	1163	0	0	3	4	3	73	397	462	161	42	9	6	3	0	0	0	0	0	0	36.4	40.7	5.2	
09-15	2884	0	1	0	1	9	196	1006	1203	365	75	21	7	0	0	0	0	0	0	0	36	40	4.6	
15-19	2368	0	3	7	5	30	341	956	794	177	42	6	4	2	1	0	0	0	0	0	34.4	38.5	5	
19-00	897	0	0	0	1	0	33	276	386	143	45	11	1	1	0	0	0	0	0	0	37.2	41.4	4.7	
00-00	7444	0	4	13	15	42	651	2662	2883	872	218	56	20	6	2	0	0	0	0	0	35.7	40	5.1	

PrimeTec Data Ltd, Speed Report

Report Id - CustomList-1277

Site Name - PRIBED01

Description - A2030 HAVANT ROAD WEST OF BEDHAMPTON ROUNDABOUT

Direction - West

13 November 2015

Time	Total	Vbin 0 5	Vbin 5 10	Vbin 10 15	Vbin 15 20	Vbin 20 25	Vbin 25 30	Vbin 30 35	Vbin 35 40	Vbin 40 45	Vbin 45 50	Vbin 50 55	Vbin 55 60	Vbin 60 65	Vbin 65 70	Vbin 70 75	Vbin 75 80	Vbin 80 85	Vbin 85 100	Vbin 100 140	Mean	Vpp 85	SD	
0000	21	0	0	0	0	0	0	7	7	6	1	0	0	0	0	0	0	0	0	0	37.6	41.4	3.9	
0100	10	0	0	0	0	0	0	2	3	3	2	0	0	0	0	0	0	0	0	0	40	-	5.6	
0200	6	0	0	0	0	0	0	2	3	0	1	0	0	0	0	0	0	0	0	0	38.1	-	5.7	
0300	8	0	0	1	0	0	0	2	0	2	1	1	1	0	0	0	0	0	0	0	40.7	-	14.2	
0400	12	0	0	0	0	0	1	1	4	2	2	0	1	0	1	0	0	0	0	0	43.1	48.3	10.6	
0500	63	0	0	0	2	0	1	14	23	12	8	0	2	0	1	0	0	0	0	0	38.7	45.9	8.1	
0600	170	0	0	0	1	1	9	40	74	21	13	8	0	1	1	0	0	0	0	0	38.2	44.5	7.1	
0700	500	0	0	0	2	0	40	166	208	62	12	5	4	0	0	0	1	0	0	0	36.1	40.3	5.4	
0800	472	0	0	1	0	0	22	204	160	59	15	7	4	0	0	0	0	0	0	0	36.2	40.5	5.1	
0900	451	0	0	0	0	1	23	181	187	45	12	1	1	0	0	0	0	0	0	0	35.7	39.4	4.2	
1000	417	0	0	0	0	0	43	177	155	38	4	0	0	0	0	0	0	0	0	0	35	39.1	4	
1100	475	0	0	0	0	1	19	161	213	66	10	4	1	0	0	0	0	0	0	0	36.4	40.3	4.2	
1200	555	0	0	0	0	2	37	231	197	73	10	4	0	1	0	0	0	0	0	0	35.7	40	4.5	
1300	542	0	0	0	0	0	22	178	222	97	17	5	1	0	0	0	0	0	0	0	36.8	40.9	4.6	
1400	578	0	0	0	0	0	46	196	246	66	19	3	2	0	0	0	0	0	0	0	36.1	40	4.6	
1500	663	0	0	0	0	5	59	264	256	65	11	3	0	0	0	0	0	0	0	0	35.2	39.4	4.3	
1600	694	0	0	0	0	3	161	295	177	48	7	2	0	1	0	0	0	0	0	0	33.5	37.8	4.5	
1700	614	0	0	1	0	2	86	285	197	31	10	2	0	0	0	0	0	0	0	0	34.1	37.8	4.2	
1800	483	0	0	0	0	0	43	197	192	39	8	3	0	1	0	0	0	0	0	0	35.4	39.1	4.3	
1900	331	0	0	1	0	0	20	103	158	38	8	3	0	0	0	0	0	0	0	0	36.1	39.8	4.4	
2000	175	0	0	0	0	0	1	54	73	35	9	0	2	1	0	0	0	0	0	0	37.6	41.4	4.9	
2100	140	0	1	0	0	3	5	36	55	30	8	2	0	0	0	0	0	0	0	0	37.2	42.3	5.9	
2200	122	0	0	0	0	0	3	27	55	25	8	3	1	0	0	0	0	0	0	0	38.2	42.3	5.1	
2300	106	0	0	0	0	0	1	23	45	25	6	3	1	1	1	0	0	0	0	0	39.2	43.8	6	
00-06	120	0	0	1	2	0	2	28	40	25	15	1	4	0	2	0	0	0	0	0	39.2	45.9	8.1	
06-09	1142	0	0	1	3	1	71	410	442	142	40	20	8	1	1	1	1	0	0	0	36.4	40.7	5.6	
09-15	3018	0	0	0	0	4	190	1124	1220	385	72	17	5	1	0	0	0	0	0	0	36	40	4.4	
15-19	2454	0	0	1	0	10	349	1041	822	183	36	10	0	2	0	0	0	0	0	0	34.5	38.7	4.4	
19-00	874	0	1	1	0	3	30	243	386	153	39	11	4	2	1	0	0	0	0	0	37.2	41.8	5.2	
00-00	7608	0	1	4	5	18	642	2846	2910	888	202	59	21	6	4	1	1	0	0	0	35.8	40	4.9	

Appendix E

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

Notes:

Selected Polygon:AW CHQ/SR/0418/058 HAVANT ROAD

120027284 19/01/2012 Time 1744 Vehicles 2 Casualties 1 Serious
E:469405 N: 105522 First Road: A 27 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: no street lighting Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to judge other persons path or speed	Vehicle 1	Possible
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING E ALONG A27 TRIES TO SLOW FOR HEAVY TRAFFIC IN FRONT BUT BRAKES DIDN'T SEEM TO WORK EFFECTIVELY, AND COLLIDES INTO REAR OF VEH 2 (CAR).

Occurred on A27 EASTBOUND MARKER POST 50.7, HAVANT, HAMPSHIRE

Vehicle Reference 1 Motor Cycle over 50 cc and up to 125cc Going ahead other
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 28 Male
Not hit and run Breath test Negative
Left hand drive:
Casualty Reference: 1 Vehicle: 1 Age: 28 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Vehicle Reference 2 Car Going ahead other
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 23 Female
Not hit and run Breath test Negative
Left hand drive:

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

120100631 12/03/2012 Time 1655 Vehicles 3 Casualties 1 Slight
E:468783 N: 105826 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Very Likely
2nd:	Failed to judge other persons path or speed	Vehicle 2	Very Likely
3rd:	Inexperienced or learner driver/rider	Vehicle 2	
4th:			
5th:			
6th:			

VEH 3 (CAR) TRAVELLING SW ALONG A2030 HAVANT ROAD STOPS AND WAITS TO TURN RIGHT INTO RECTORY AVENUE. FOLLOWING VEH 2 (CAR) STOPS BEHIND STATIC VEH 3, FOLLOWING VEH 1 (CAR) FAILS TO SLOW FOR TRAFFIC AHEAD AND COLLIDES WITH REAR OF STATIC VEH 2.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH RECTORY AVENUE, FARLINGTON, HAMPSHIRE

Vehicle Reference 1 Car Going ahead but held up
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 28 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Stopping
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 19 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 19 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

Vehicle Reference	3	Car		Waiting to turn right
Vehicle movement from	NE	to SW	No tow / articulation	Leaving the main road
On main carriageway			No skidding, jack-knifing or overturning	
Location at impact	Leaving main road		First impact	Did not impact
Hit object in road	None		Off road:	None
Did not leave carr			Age of Driver	Unknown
Non-stop, not hit	Breath test	Driver not contacted		
			Left hand drive:	No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

120122498 28/03/2012 Time 0830 Vehicles 2 Casualties 1 Slight
E:468694 N: 105828 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Possible
2nd:	Careless/Reckless/In a hurry	Vehicle 2	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 2 (CAR) TRAVELLING S ALONG OLD RECTORY ROAD PASSES VEH 1 (P/CYCLE) TRAVELLING IN THE SAME DIRECTION APPROACHING JUNCTION WITH A2030 HAVANT ROAD AND COLLIDES. VEH 2 FAILS TO STOP.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH OLD RECTORY ROAD, PORTSMOUTH, HAMPSHIRE

Vehicle Reference 1 Pedal Cycle Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 14 Male
Not hit and run Breath test Not requested
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 14 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not known

Vehicle Reference 2 Car Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver Not traced
Hit and run Breath test Not requested
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

120153150 20/04/2012 Time 1845 Vehicles 2 Casualties 1 Slight
E:469777 N: 106189 First Road: B 2177 Road Type Single carriageway
Speed limit: 40 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Daylight Raining without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Distraction in vehicle	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) WAS TRAVELLING N ALONG B2177 BEDHAMPTON HILL ROAD. DRIVER WAS DISTRACTED BY
MOBILE PHONE RINGING AND FAILED TO NOTICE VEH 2 (P/CYCLE) AHEAD. VEH 1 COLLIDED WITH VEH 2
CAUSING THE RIDER TO FALL.

Occurred on B2177 BEDHAMPTON HILL ROAD OUTSIDE THE RUSTY CUTTER, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 23 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Pedal Cycle Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 32 Male
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 32 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not known

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

120249994 29/06/2012 Time 1329 Vehicles 2 Casualties 2 Slight
E:469480 N: 106014 First Road: A 2030 Road Type Dual carriageway
Speed limit: 40 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Following too close	Vehicle 1	Possible
2nd:	Failed to look properly	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (TAXI) TRAVELLING NE ALONG A2030 HAVANT ROAD COLLIDED WITH REAR OF VEH 2 (TAXI) TRAVELLING IN FRONT.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH BEDHAMPTON HILL, HAVANT, HAMPSHIRE

Vehicle Reference 1 Taxi/Private hire car Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 25 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 26 Female Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
Front seat

Vehicle Reference 2 Taxi/Private hire car Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 54 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 2 Vehicle: 2 Age: 54 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

120259885 06/07/2012 Time 1330 Vehicles 2 Casualties 1 Slight
E:469610 N: 105985 First Road: A 27 Road Type 1 A 2030
Speed limit: 40 Junction Detail: Roundabout Automatic traffic signal
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Daylight Raining without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 2 (CAR) TRAVELLING W AROUND A2030 HAVANT ROAD RBT IN LANE 2 MOVES OFF WHEN LIGHTS CHANGE AND MOVES INTO LANE 3 IN ORDER TO TURN RIGHT COLLIDING WITH VEH 1 (CAR) TRAVELLING IN LANE 3.

Occurred on A27 EASTBOUND OFFSLIP AT JUNCTION WITH A2030 HAVANT ROAD, HAMPSHIRE

Vehicle Reference 1 Van or Goods 3.5 tonnes mgw and under Starting
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 41 Male
Not hit and run Breath test Not requested
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 41 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Changing lane to right
Vehicle movement from E to NW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 51 Male
Not hit and run Breath test Driver not contacted
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

120264040 09/07/2012 Time 1449 Vehicles 1 Casualties 1 Slight
E:468017 N: 105724 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: Pelican, puffin, toucan etc. Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG GALT ROAD TURNED RIGHT ONTO A2030 HAVANT ROAD AND
ACCELERATED OUT AFTER SEEING A VEH BEHIND. VEH 1 FAILED TO SEE CAS 1 (PEDESTRIAN)
TRAVELLING N ACROSS A2030 HAVANT ROAD ON PEDESTRIAN CROSSING AND HIT CAS 1.
Occurred on A2030 HAVANT ROAD AT JUNCTION WITH GALT ROAD, COSHAM, HAMPSHIRE

Vehicle Reference 1 Car Turning left
Vehicle movement from N to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Cleared junction or waiting/park First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 78 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 6 Female Pedestrian Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
On Ped Crossing N bound
Driver's nearside

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

120297738 01/08/2012 Time 1737 Vehicles 1 Casualties 1 Serious
E:467867 N: 105699 First Road: A 2030 Road Type Dual carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Casualty 1	Possible
2nd:			
3rd:			
4th:			
5th:			
6th:			

CAS 1 (PEDESTRIAN) TRAVELLING S ACROSS A2030 HAVANT ROAD ON PUSH SCOOTER, CROSSES
BETWEEN STATIONARY VEHS IN LANE 2 AND INTO LANE 1 IN FRONT OF VEH 1 (CAR) TRAVELLING W
ALONG A2030 HAVANT ROAD CAUSING COLLISION.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH WATERWORKS ROAD, PORTSMOUTH, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Cleared junction or waiting/park First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 40 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 11 Male Pedestrian Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
In carr elsewhere S bound
Driver's offside masked

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

120313338 11/08/2012 Time 1800 Vehicles 3 Casualties 2 Slight
E:469617 N: 105881 First Road: (M) 3 Road Type Slip road
Speed limit: 70 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Following too close	Vehicle 1	Very Likely
2nd:	Failed to judge other persons path or speed	Vehicle 1	Possible
3rd:	Sudden braking	Vehicle 2	Very Likely
4th:	Sudden braking	Vehicle 3	Very Likely
5th:			
6th:			

VEH 2 (CAR) TRAVELLING N ALONG A3 (M) EXITS AT JUNCTION 5 ONTO SLIP ROAD AND FORCED TO BRAKE HARD FOR UNKNOWN VEH AHEAD BRAKING, CAUSING FOLLOWING VEH 1 TO COLLIDE WITH REAR OF VEH 2.

Occurred on A3 (M) NORTHBOUND JUNCTION 5 OFF-SLIP 86 METRES NORTH OF A3(M) NORTHBOUND, BEDHAMPTON, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 58 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Stopping
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 32 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 32 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Unknown Cycle helmet: Not a cyclist

Casualty Reference: 2 Vehicle: 2 Age: 32 Male Passenger Severity: Slight
Not a pupil
Seatbelt Unknown Cycle helmet: Not a cyclist

Front seat

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

Vehicle Reference	3	Car		Stopping	
Vehicle movement from	S	to N	No tow / articulation		Leaving the main road
On main carriageway				No skidding, jack-knifing or overturning	
Location at impact	Cleared junction or waiting/park		First impact	Did not impact	Hit vehicle:
Hit object in road	None		Off road:	None	
Did not leave carr				Age of Driver	Not traced
Non-stop, not hit	Breath test	Driver not contacted			
			Left hand drive:	No	

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

120338317 29/08/2012 Time 1354 Vehicles 2 Casualties 2 Slight
E:468903 N: 105865 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Daylight Raining without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Rain, sleet, snow, or fog	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 2 (CAR) TRAVELLING SW ALONG A2030 HAVANT ROAD TURNED RIGHT INTO AURIOL DRIVE AND STOPPED TO ALLOW OTHER VEHS TO PASS A PARKED VEH. FOLLOWING VEH 1 (CAR) FAILED TO NOTICE VEH 2 HAD STOPPED AND HIT REAR OF VEH 2. VEH 1 LEFT ROAD AND HIT WALL
Occurred on A2030 HAVANT ROAD AT JUNCTION WITH AURIOL DRIVE, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from E to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: Wall or fence
Nearside Age of Driver 81 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 81 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Casualty Reference: 2 Vehicle: 1 Age: 80 Female Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Front seat

Vehicle Reference 2 Car Turning right
Vehicle movement from E to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 54 Male
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

120469372 03/12/2012 Time 1620 Vehicles 2 Casualties 1 Slight
E:469744 N: 106111 First Road: B 2177 Road Type 1 A 27
Speed limit: 40 Junction Detail: Roundabout Give way or controlled
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Sudden braking	Vehicle 1	Possible
2nd:	Failed to look properly	Vehicle 2	Possible
3rd:	Failed to judge other persons path or speed	Vehicle 2	
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SW ALONG B2177 BEDHAMPTON HILL APPROACHES THE RUSTY CUTTER RBT, ATTEMPTS TO MOVE OFF AND FORCED TO STOP FOR APPROACHING MOTORIST NEGOTIATING RBT, CAUSING FOLLOWING VEH 2 (CAR) TO COLLIDE WITH REAR OF VEH 1.

Occurred on B2177 BEDHAMPTON HILL AT JUNCTION WITH A27, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Stopping
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Entering roundabout First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 39 Male
Not hit and run Breath test Not requested Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 39 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Starting
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 60 Female
Not hit and run Breath test Not requested Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

120474916 07/12/2012 Time 2040 Vehicles 2 Casualties 1 Serious
E:469746 N: 106117 First Road: B 2177 Road Type Single carriageway
Speed limit: 30 Junction Detail: Roundabout Give way or controlled A 27
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Passing too close to cyclist, horse rider or pedestrian	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG B2177 BEDHAMPTON HILL ROAD COLLIDED WITH VEH 2 (P/CYCLE)
WAITING AT JUNCTION TO MOVE ONTO RBT.

Occurred on B2177 BEDHAMPTON HILL ROAD AT JUNCTION WITH A27 HAVANT ROAD, HAVANT,
HAMPSHIRE

Vehicle Reference 1 Car Stopping
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 43 Male
Not hit and run Breath test Not requested
Left hand drive: No

Vehicle Reference 2 Pedal Cycle Going ahead but held up
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 47 Male
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 47 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Yes

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

120484988 15/12/2012 Time 1635 Vehicles 1 Casualties 1 Slight
E:469620 N: 105892 First Road: (M) 3 Road Type Slip road
Speed limit: 70 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Slippery road (due to weather)	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING N ALONG A3(M) OFFSLIP LOST CONTROL DUE TO WET CONDITIONS CAUSING
VEH TO SPIN AND TO LEAVE THE CARRIAGEWAY TO THE OFFSIDE COLLIDING WITH A SIGN AND LAMP
POST.

Occurred on A3(M) NORTHBOUND OFFSLIP 105 METRES NORTH OF A3(M) NORTHBOUND, HAVANT,
HAMPSHIRE

Vehicle Reference 1 Car Going ahead left bend
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: Road sign / ATS
O/S Age of Driver 67 Female
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 67 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

130026226 18/01/2013 Time 0725 Vehicles 2 Casualties 1 Slight
E:469602 N: 105981 First Road: B 2177 Road Type 1
Speed limit: 40 Junction Detail: Roundabout Automatic traffic signal A(M) 3
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Snowing without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (P/CYCLE) TRAVELLING W AROUND B2177 BEDHAMPTON HILL RBT WAS HIT BY VEH 2 (CAR)
TRAVELLING N ALONG A3(M) OFFSLIP AND ENTERING RBT. VEH 2 FAILED TO SEE VEH 1.
Occurred on A3(M) NORTHBOUND JUNCTION 5 OFFSLIP AT JUNCTION WITH B2177 BEDHAMPTON HILL
ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Pedal Cycle Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 25 Male
Not hit and run Breath test Not applicable
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 25 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Yes

Vehicle Reference 2 Car Starting
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver Not traced
Not hit and run Breath test Driver not contacted
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

130028489 23/01/2013 Time 0905 Vehicles 2 Casualties 1 Slight
E:469571 N: 105601 First Road: A 27 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Other	Vehicle 1	Very Likely
2nd:	Sudden braking	Vehicle 1	Possible
3rd:	Following too close	Vehicle 2	
4th:			
5th:			
6th:			

BONNET FLY UP ONTO WINDSCREEN
VEH 2 (CAR) TRAVELLING NE ALONG THE A27 FAILS TO SEE VEH AHEAD BRAKE HEAVILY
SUBSEQUENTLY COLLIDING ON ITS FORNT WITH VEH 1 (CAR)
Occurred on A27 EASTBOUND AT MARKER POST 50.9, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Stopping
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 26 Female
Not hit and run Breath test Negative
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 26 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 49 Male
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

130031826 25/01/2013 Time 1723 Vehicles 1 Casualties 1 Slight
E:469472 N: 105473 First Road: (M) 3 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Slip Road Give way or controlled A 27
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: no street lighting Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Tyres illegal, defective or under inflated	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SW ALONG A3(M) IN LANE 2 WHEN VEH SUFFERED A BLOW OUT CAUSING VEH TO CROSS 2 LANE OF CARRIAGEWAY AND 2 LANES OF THE ONSLIP BEFORE COLLIDING WITH THE SIDE BARRIER AND HITTING A LAMPPOST.

Occurred on A3(M) SOUTHBOUND AT JUNCTION WITH A27 WESTBOUND ONSLIP, BEDHAMPTON, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: Near / off crash barrier
Nearside Age of Driver 21 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 21 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

130248104 06/07/2013 Time 1545 Vehicles 1 Casualties 1 Serious
E:469790 N: 105781 First Road: A 27 Road Type 1
Speed limit: 60 Junction Detail: Roundabout Give way or controlled A 27
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Loss of control	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING N ALONG A27 HARTS FARM WAY LOSES CONTROL ON RBT CAUSING
RIDER TO FALL OFF.

Occurred on A27 HARTS FARM WAY AT JUNCTION WITH A27 EASTBOUND ONSLIP, HAVANT, HAMPSHIRE

Vehicle Reference 1 Motorcycle over 500cc Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 40 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 40 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

130254105 10/07/2013 Time 1940 Vehicles 2 Casualties 1 Slight
E:468765 N: 105821 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Disobeyed Give Way or Stop sign or markings	Vehicle 2	Very Likely
2nd:	Failed to judge other persons path or speed	Vehicle 2	Very Likely
3rd:	Careless/Reckless/In a hurry	Vehicle 2	Possible
4th:	Dazzling sun	Vehicle 2	Possible
5th:			
6th:			

VEH 2 (CAR) TRAVELLING N ALONG WESTWAYS TURNS RIGHT ONTO A2030 HAVANT ROAD ACROSS
PATH OF VEH 1 (M/CYCLE) TRAVELLING W ALONG A2030 HAVANT ROAD CAUSING COLLISION. VEH 2
FAILS TO STOP AND DRIVES OFF UP RECTORY AVENUE.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH WESTWAYS, PORTSMOUTH, HAMPSHIRE

Vehicle Reference 1 Motor Cycle over 125 cc and up to 500cc Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 48 Male
Not hit and run Breath test Not requested
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 48 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Turning right
Vehicle movement from S to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 23 Male
Not hit and run Breath test Driver not contacted
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

130373649 25/09/2013 Time 1744 Vehicles 1 Casualties 1 Slight
E:469594 N: 106141 First Road: (M) 3 Road Type Slip road A 2030
Speed limit: 70 Junction Detail: Slip Road Give way or controlled
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to judge other persons path or speed	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING N ALONG A3(M) NORTHBOUND ONSLIP FROM A2030 HAVANT ROAD
OVER-REACTED TO THE PRESENCE OF ANOTHER VEHICLE AND HIT THE NEARSIDE KERB.

Occurred on A3(M) NORTHBOUND ONSLIP AT JUNCTION WITH A2030 HAVANT ROAD, HAVANT,
HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 25 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 18 Male Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
Front seat

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

130373182 02/10/2013 Time 0911 Vehicles 2 Casualties 2 Slight
E:469746 N: 106108 First Road: A 27 Road Type Single carriageway
Speed limit: 30 Junction Detail: Roundabout Give way or controlled B 2177
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Possible
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SW ALONG B2177 BEDHAMPTON HILL ROAD COLLIDED WITH VEH 2 (CAR)
WAITING AT JUNCTION TO ENTER THE RBT.

Occurred on B2177 BEDHAMPTON HILL ROAD AT JUNCTION WITH A27 HAVANT ROAD, HAVANT,
HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 24 Female
Not hit and run Breath test Not requested
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 24 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Going ahead other
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 22 Female
Not hit and run Breath test Not requested
Left hand drive: No

Casualty Reference: 2 Vehicle: 2 Age: 22 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

Notes:

130436007 18/11/2013 Time 1850 Vehicles 2 Casualties 1 Serious
E:469996 N: 106570 First Road: B 2177 Road Type Single carriageway
Speed limit: 30 Junction Detail: Mini roundabout Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Raining without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Rain, sleet, snow, or fog	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SE ALONG MAYLANDS ROAD ENTERED THE MINI-RBT AT B2177 BEDHAMPTON HILL ROAD INTO THE PATH OF VEH 2 (M/CYCLE) TRAVELLING NE ACROSS THE RBT, CAUSING VEH 2 TO BRAKE HARD AND THE RIDER TO FALL.

Occurred on B2177 BEDHAMPTON HILL ROAD AT JUNCTION WITH MAYLANDS ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Starting
Vehicle movement from NW to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Entering roundabout First impact Did not impact Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 51 Female
Not hit and run Breath test Not requested
Left hand drive: No

Vehicle Reference 2 Motorcycle 50cc and under Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Mid Junction - on roundabout or r First impact Did not impact Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 61 Male
Not hit and run Breath test Not requested
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 61 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

130449886 29/11/2013 Time 1331 Vehicles 2 Casualties 1 Slight
E:467904 N: 105704 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: Pri Drive Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Failed to judge other persons path or speed	Vehicle 2	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SW ALONG A2030 HAVANT ROAD, FAILS TO OBSERVE AND TURNS LEFT INTO TYRE GARAGE ACROSS THE PATH OF VEH 2 (M/CYCLE) TRAVELLING IN THE SAME DIRECTION ON THE INSIDE AND COLLIDES.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH 'S' SETYRES GARAGE, PORTSMOUTH, HAMPSHIRE

Vehicle Reference 1 Car Turning left
Vehicle movement from NE to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 25 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Motorcycle 50cc and under Overtaking nearside
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 60 Female
Not hit and run Breath test Not requested
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 60 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

130464214 10/12/2013 Time 1720 Vehicles 2 Casualties 1 Slight
E:469472 N: 105536 First Road: A 27 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Failed to judge other persons path or speed	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SW ALONG A27 COLLIDES WITH REAR OF VEH 2 (CAR) TRAVELLING IN FRONT.
Occurred on A27 WESTBOUND MARKER POST 50.8, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 24 Female
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Stopping
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 43 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 43 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

130485139 29/12/2013 Time 0916 Vehicles 1 Casualties 1 Slight
E:469542 N: 106080 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Frost/Ice
Daylight Fine with high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Slippery road (due to weather)	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING S ALONG GLEBE PARK AVENUE TURNS RIGHT ONTO BEDHAMPTON HILL ROAD AND LOST CONTROL ON BLACK ICE CAUSING RIDER OF VEH 1 TO DROP VEH.

Occurred on GLEBE PARK AVENUE AT JUNCTION WITH BEDHAMPTON HILL ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Motor Cycle over 50 cc and up to 125cc Turning right
Vehicle movement from N to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Did not impact Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 17 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 17 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

140017941 16/01/2014 Time 1230 Vehicles 1 Casualties 1 Serious
E:469631 N: 105837 First Road: (M) 3 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Loss of control	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING N ALONG A3(M) OVERTAKES A VEH BUT LOSES CONTROL AND LEAVES
THE ROAD TO THE OFFSIDE COLLIDING WITH CONCRETE BARRIER.

Occurred on A3(M) NORTHBOUND MARKER POST 0.5, HAVANT, HAMPSHIRE

Vehicle Reference 1 Motorcycle over 500cc Going ahead left bend
Vehicle movement from SW to N No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
Hit object in road None Off road: Cent crash barrier
O/S onto cent res Age of Driver 65 Male
Not hit and run Breath test Negative Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 65 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

140072231 28/02/2014 Time 2228 Vehicles 2 Casualties 1 Serious
E:470006 N: 106560 First Road: B 2177 Road Type 1 B 2177
Speed limit: 30 Junction Detail: Roundabout Give way or controlled
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to judge other persons path or speed	Vehicle 2	Possible
2nd:	Failed to judge other persons path or speed	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 2 (TOWER WAGON) TRAVELLING SW ALONG B2177 PORTSDOWN HILL ROAD ENTERS RBTAT SPEED,
VEH 1 (CAR) TRAVELLING SW ALONG B2177 BEDHAMPTON HILL ENTERS RBT AT SAME TIME VEH 2 FAILS
TO ANTICIPATE VEH 1 HAS TO GIVE WAY AND COLLIDES.

Occurred on B2177 BEDHAMPTON HILL AT JUNCTION WITH B2177 PORTSDOWN HILL ROAD, HAVANT,
HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 18 Male
Not hit and run Breath test Driver not contacted
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 18 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Other Vehicle Going ahead right bend
Vehicle movement from W to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 49 Male
Not hit and run Breath test Driver not contacted
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

140079681 06/03/2014 Time 1440 Vehicles 2 Casualties 3 Serious
E:469186 N: 105926 First Road: A 2030 Road Type Single carriageway
Speed limit: 40 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Loss of control	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING W ALONG A2030 HAVANT ROAD LOSES CONTROL AND VEERS INTO PATH OF
ONCOMING VEH 2 (VAN).

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH AURIOL DRIVE, BEDHAMPTON, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Cleared junction or waiting/park First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 44 Female
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 44 Female Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

Vehicle Reference	2	Van or Goods	3.5 tonnes mgw and under	Going ahead other
Vehicle movement from	W	to	E	No tow / articulation
On main carriageway				Leaving the main road
Location at impact	Jct Approach			No skidding, jack-knifing or overturning
Hit object in road	None			First impact Front
				Off road: None
Did not leave carr				Hit vehicle:
Not hit and run				Age of Driver 51
		Breath test	Positive	Male
				Left hand drive: No

Casualty Reference:	2	Vehicle:	2	Age:	51	Male	Driver/rider	Severity:	Slight
Not a pupil									
Seatbelt		Not Applicable		Cycle helmet: Not a cyclist					

Casualty Reference:	3	Vehicle:	2	Age:	49	Male	Passenger	Severity:	Slight
Not a pupil									
Seatbelt		Not Applicable		Cycle helmet: Not a cyclist					

Not car passenger

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

140116451 03/04/2014 Time 1521 Vehicles 2 Casualties 1 Slight
E:469695 N: 106000 First Road: A 2030 Road Type Single carriageway
Speed limit: 40 Junction Detail: Roundabout Give way or controlled B 2177
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING NW ALONG A2030 HARTS FARM WAY ENTERED THE RBT AT B2177 BEDHAMPTON HILL ROAD INTO THE PATH OF VEH 2 (M/CYCLE) TRAVELLING SW ON THE RBT, CAUSING VEH 2 TO COLLIDE WITH THE OFFSIDE OF VEH 1.

Occurred on A2030 HARTS FARM WAY AT JUNCTION WITH B2177 BEDHAMPTON HILL ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Starting
Vehicle movement from SE to NW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Entering roundabout First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 54 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Motor Cycle over 50 cc and up to 125cc Going ahead right bend
Vehicle movement from NE to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 56 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 56 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

140139223 21/04/2014 Time 1115 Vehicles 2 Casualties 1 Slight
E:469746 N: 106110 First Road: A 27 Road Type Single carriageway
Speed limit: 30 Junction Detail: Roundabout Give way or controlled B 2177
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Very Likely
2nd:	Failed to judge other persons path or speed	Vehicle 2	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 2 (CAR) TRAVELLING SW ALONG B2177 BEDHAMPTON HILL ROAD, FAILS TO STOP IN TIME AND COLLIDES WITH THE REAR OF VEH 1 (CAR) STATIONARY, WAITING TO ENTER THE RBT, PUSHING VEH 1 INTO THE RBT

Occurred on B2177 BEDHAMPTON HILL ROAD AT JUNCTION WITH A27 HAVANT ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead but held up
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 60 Female
Not hit and run Breath test Not requested
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 60 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Going ahead but held up
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 46 Female
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

140215121 18/06/2014 Time 0938 Vehicles 1 Casualties 1 Slight
E:469435 N: 105531 First Road: A 27 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Loss of control	Vehicle 1	Very Likely
2nd:	Distraction in vehicle	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING NE ALONG A27 EASTBOUND LOST CONTROL, LEFT THE CARRIAGEWAY TO THE NEARSIDE AND CAME TO REST BACK IN THE CARRIAGEWAY.

Occurred on A27 EASTBOUND MARKER POST 50.7, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: Oth perm objects
Nearside & rebounded Age of Driver 29 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 29 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

140239933 06/07/2014 Time 1814 Vehicles 1 Casualties 1 Slight
E:469581 N: 105597 First Road: (M) 3 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 1	Very Likely
2nd:	Loss of control	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SW ALONG A3M IN LANE 2 DRIFTS TOWARDS CENTRAL RESERVATION AND
LOSES CONTROL CAUSING VEH TO SPIN AND COLLIDE WITH BARRIER.

Occurred on A3M SOUTHBOUND MARKER POST 0.2, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead right bend
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
Hit object in road None Off road: Cent crash barrier
O/S onto cent res & rebounded Age of Driver 20 Female
Not hit and run Breath test Not requested Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 20 Female Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
Front seat

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

140305572 23/08/2014 Time 1240 Vehicles 1 Casualties 1 Slight
E:467829 N: 105690 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Automatic traffic signal Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Inexperienced or learner driver/rider	Vehicle 1	Possible
2nd:	Loss of control	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING N ALONG A2030 EASTERN ROAD LOST CONTROL WHEN TURNING LEFT
INTO HAVANT ROAD, CAUSING THE RIDER TO FALL.

Occurred on A2030 EASTERN ROAD AT JUNCTION WITH HAVANT ROAD, COSHAM, HAMPSHIRE

Vehicle Reference 1 Car Turning left
Vehicle movement from S to W No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Mid Junction - on roundabout or r First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 25 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 25 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

140358184 03/10/2014 Time 1747 Vehicles 2 Casualties 2 Slight
E:469476 N: 105539 First Road: A 27 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 1	Very Likely
2nd:	Swerved	Vehicle 1	Very Likely
3rd:	Loss of control	Vehicle 1	Possible
4th:	Dazzling sun	Vehicle 1	Possible
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SW ALONG A27 IN LANE 1 IS BLINDED BY LOW SUN CAUSING VEH TO MOVE INTO LANE 2. VEH 1 OVERCORRECTS AND MOVES BACK INTO LANE 1 COLLIDING WITH REAR OF VEH 2 (CAR) TRAVELLING IN LANE 1. VEH 2 LEAVES ROAD AND OVERTURNS.

Occurred on A27 WESTBOUND MARKER POST 50.8, BEDHAMPTON, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 21 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Going ahead other
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway Skidded and overturned
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
Hit object in road None Off road: None
Nearside Age of Driver 47 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 47 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Casualty Reference: 2 Vehicle: 2 Age: 48 Male Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
Front seat

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

140413899 18/11/2014 Time 0740 Vehicles 2 Casualties 1 Slight
E:468330 N: 105792 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Cyclist entering road from pavement	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (P/CYCLE) TRAVELLING S ALONG WEST PAVEMENT OF GILLMAN ROAD DOWN STEEP HILL FAILED TO STOP END OF PAVEMENT DUE TO BRAKE FAILURE AND ENTERED A2030 HAVANT ROAD COLLIDING WITH NEARSIDE VEH 2 (VAN) TRAVELLING E ALONG A2030 HAVANT ROAD.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH GILLMAN ROAD, PORTSMOUTH, HAMPSHIRE

Vehicle Reference 1 Pedal Cycle Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 20 Male
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 20 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: No

Vehicle Reference 2 Van or Goods 3.5 tonnes mgw and under Going ahead other
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 43 Male
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

140461409 30/12/2014 Time 0105 Vehicles 1 Casualties 1 Slight
E:469343 N: 105501 First Road: A 27 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Slip Road Give way or controlled A 2030
Crossing: Control None Facilities: None within 50m Road surface Frost/Ice
Darkness: no street lighting Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Loss of control	Vehicle 1	Very Likely
2nd:	Nervous/Uncertain/Panic	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING NE ALONG A27 EASTBOUND MISSED THE EXIT FOR THE A2030 OFFSLIP AND ATTEMPTED TO CROSS THE HATCHED LINES, LOST CONTROL AND LEFT THE CARRIAGEWAY TO THE NEARSIDE.

Occurred on A27 EASTBOUND AT JUNCTION WITH A2030 OFFSLIP, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from S to NE No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Mid Junction - on roundabout or r First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Nearside Age of Driver 20 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 20 Female Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
Front seat

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

150029129 26/01/2015 Time 1640 Vehicles 1 Casualties 1 Slight
E:468773 N: 105833 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Possible
2nd:	Aggressive driving	Vehicle 1	Very Likely
3rd:	Careless/Reckless/In a hurry	Vehicle 1	
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING W ALONG A2030 HAVANT ROAD TURNED RIGHT INTO RECTORY AVENUE AND CLIPPED CAS 1 (PEDESTRIAN) WHO WAS CROSSING RECTORY ROAD FROM THE NEARSIDE.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH RECTORY AVENUE, FARLINGTON, HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from E to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 56 Male
Not hit and run Breath test Driver not contacted
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 52 Male Pedestrian Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
In carr elsewhere E bound
Driver's nearside

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

150146444 01/05/2015 Time 1250 Vehicles 2 Casualties 1 Slight
E:469747 N: 106113 First Road: B 2177 Road Type Single carriageway
Speed limit: 40 Junction Detail: Roundabout Give way or controlled A 27
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 2 (CAR) TRAVELLING SW ALONG B2177 BEDHAMPTON HILL STOPPED AT ROUNDABOUT FOR TRAFFIC. VEH 1 (CAR) TRAVELLING BEHIND FAILED TO STOP IN TIME AND COLLIDED INTO THE REAR OF VEH 2.

Occurred on B2177 BEDHAMPTON HILL AT JUNCTION WITH A27, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 51 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Going ahead but held up
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 30 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 30 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

150158651 11/05/2015 Time 1548 Vehicles 2 Casualties 1 Slight
E:469745 N: 106115 First Road: A 27 Road Type Single carriageway
Speed limit: 40 Junction Detail: Roundabout Give way or controlled B 2177
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Possible
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (VAN) TRAVELLING SW ALONG B2177 BEDHAMPTON HILL, FAILS TO STOP IN TIME AND COLLIDES WITH THE REAR OF VEH 2 (CAR) STATIONARY WAITING TO ENTER THE RBT.

Occurred on B2177 BEDHAMPTON HILL AT JUNCTION WITH A27, HAVANT, HAMPSHIRE

Vehicle Reference 1 Van or Goods 3.5 tonnes mgw and under Stopping
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 42 Male
Not hit and run Breath test Not requested
Left hand drive: No

Vehicle Reference 2 Car Going ahead but held up
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 58 Female
Not hit and run Breath test Not requested
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 58 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

150185618 02/06/2015 Time 1330 Vehicles 2 Casualties 1 Slight
E:469558 N: 106070 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: Roundabout Give way or controlled A(M) 3
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to judge other persons path or speed	Vehicle 2	Possible
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING E ALONG A2030 HAVANT ROAD STOPPED AT THE A3(M) JUNCTION 5 RBT. VEH 2 (LORRY) FAILED TO STOP IN TIME AND COLLIDED WITH THE REAR OF VEH 1.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH A3(M) NORTHBOUND JUNCTION 5, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead but held up
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 26 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 26 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Goods over 3.5 tonnes and under 7.5 to Stopping
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 52 Male
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

150223194 01/07/2015 Time 0629 Vehicles 1 Casualties 1 Slight
E:469802 N: 105788 First Road: A 27 Road Type Single carriageway
Speed limit: 60 Junction Detail: Roundabout Give way or controlled A 27
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Distraction in vehicle	Vehicle 1	Possible
2nd:	Loss of control	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING N ALONG A27 HARTS FARM WAY APPROACHING RBT, DRIVER GETS SPOOKED BY A SPIDER IN THE VEH AND LEAVES THE CARRIAGEWAY TO THE OFFSIDE AND CRASHES INTO CENTRAL HIGH CURB ISLAND.

Occurred on A27 HARTS FARM WAY AT JUNCTION WITH A27 EASTBOUND ONSLIP, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Turning left
Vehicle movement from NW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: Oth perm objects
O/S Age of Driver 28 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 28 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

150331271 24/09/2015 Time 1010 Vehicles 2 Casualties 1 Slight
E:467916 N: 105714 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELING E ALONG A2030 HAVANT ROAD, PULLS TO NEARSIDE INTO A BUS LANE IN ORDER TO DO A U-TURN, VEH 1 DID NOT SEE VEH 2 (M/CYCLE) TO OUTSIDE CAUSING COLLISION.

Occurred on A2030 HAVANT ROAD OUTSIDE NUMBER 256, FARLINGTON, HAMPSHIRE

Vehicle Reference 1 Car U-turn
Vehicle movement from W to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 47 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Going ahead other
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 49 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 49 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

150341204 01/10/2015 Time 1903 Vehicles 3 Casualties 1 Slight
E:468745 N: 105821 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lighting unknown Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Following too close	Vehicle 1	Possible
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING E ALONG A2030 HAVANT ROAD FAILED TO STOP IN TIME AND COLLIDED
WITH REAR OF VEH 2 (CAR) STOPPED IN FRONT. VEH 2 IS PUSHED INTO REAR OF VEH 3 (CAR) STOPPED
IN FRONT AND WAITING TO TURN RIGHT INTO WESTWAYS.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH WESTWAYS, PORTSMOUTH, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 21 Female
Not hit and run Breath test Negative
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 21 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Stopping
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 28 Male
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

Vehicle Reference 3 Car Waiting to turn right
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or 1 First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 23 Male
Not hit and run Breath test Negative
Left hand drive: No

150358762 15/10/2015 Time 1741 Vehicles 1 Casualties 1 Slight
E:469694 N: 105998 First Road: A 27 Road Type 1
Speed limit: 60 Junction Detail: Roundabout Give way or controlled B 2177
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Loss of control	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING NW ALONG A27 HARTS FARM WAY ENTERS THE RBT AND FOR UNKNOWN REASON LOSES CONTROL AND THE RIDER DROPS VEH 1.

Occurred on A27 HARTS FARM WAY AT JUNCTION WITH B2177 BEDHAMPTON HILL ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Motorcycle over 500cc Starting
Vehicle movement from SE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or 1 First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 48 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 48 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

Notes:

160029666 20/01/2016 Time 1620 Vehicles 1 Casualties 1 Slight
E:468293 N: 105779 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: Central reservation Road surface Wet/Damp
Darkness: street lighting unknown Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Travelling too fast for conditions	Vehicle 1	Possible
2nd:	Failed to look properly	Vehicle 1	Possible
3rd:	Inexperienced or learner driver/rider	Vehicle 1	Very Likely
4th:	Sudden braking	Vehicle 1	Very Likely
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING SW ALONG A2030 HAVANT ROAD SLOWLY OVERTAKES A VEH THAT IS
TURNING LEFT INTO LOWER FARLINGTON ROAD HOWEVER BRAKED HARD ON SEEING CENRAL REFUGE
AND A VEH TURNING LEFT OUT OF LOWER FARLINGTON ROAD. RIDER FELL OFF.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH LOWER FARLINGTON ROAD, PORTSMOUTH,
HAMPSHIRE

Vehicle Reference 1 Motor Cycle over 50 cc and up to 125cc Overtaking moving vehicle O/S
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Did not impact Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 18 Male
Not hit and run Breath test Not requested
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 18 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

160055258 05/02/2016 Time 1755 Vehicles 2 Casualties 1 Slight
E:467836 N: 105703 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Automatic traffic signal A 2030
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Disobeyed automatic traffic signal	Vehicle 2	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING N ALONG A2030 EASTERN ROAD TURNED RIGHT INTO A2030 HAVANT ROAD AND COLLIDED WITH THE OFFSIDE OF VEH 2 (CAR) TRAVELLING E ALONG HAVANT ROAD.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH A2030 EASTERN ROAD, FARLINGTON, HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from S to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 29 Female
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Going ahead other
Vehicle movement from S to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 54 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 54 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

160149070 20/04/2016 Time 0730 Vehicles 2 Casualties 5 Serious
E:469742 N: 105964 First Road: A 27 Road Type Single carriageway
Speed limit: 60 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Disobeyed double white line	Vehicle 1	Very Likely
2nd:	Careless/Reckless/In a hurry	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING N ALONG A27 HARTS FARM WAY AFTER JUST RETURNING FROM FRANCE,
CROSSED OVER ONTO WRONG SIDE OF ROAD AND COLLIDED WITH ONCOMING VEH 2 (CAR). DRIVER
VEH 1 THOUGHT THEY WERE STILL DRIVING ABROAD.

Occurred on A27 HARTS FARM WAY 86 METRES SOUTH OF B2177 BEDHAMPTON HILL ROAD,
BEDHAMPTON, HAMPSHIRE

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

Vehicle Reference	1	Car	Going ahead other
Vehicle movement from	S	to N	No tow / articulation
On main carriageway			Leaving the main road
Location at impact	Not at, or within 20M of Jct	First impact	Front
Hit object in road	None	Off road:	None
Did not leave carr		Age of Driver	78
Not hit and run	Breath test	Negative	Male
		Left hand drive:	No

Casualty Reference:	1	Vehicle:	1	Age:	78	Male	Driver/rider	Severity:	Slight
Not a pupil									
Seatbelt		Not Applicable		Cycle helmet: Not a cyclist					

Casualty Reference:	2	Vehicle:	1	Age:	73	Female	Passenger	Severity:	Serious
Not a pupil									
Seatbelt		Not Applicable		Cycle helmet: Not a cyclist					

Front seat

Casualty Reference:	3	Vehicle:	1	Age:	78	Male	Passenger	Severity:	Slight
Not a pupil									
Seatbelt		Not Applicable		Cycle helmet: Not a cyclist					

Back seat

Casualty Reference:	4	Vehicle:	1	Age:	77	Female	Passenger	Severity:	Slight
Not a pupil									
Seatbelt		Not Applicable		Cycle helmet: Not a cyclist					

Back seat

Vehicle Reference	2	Car	Going ahead other
Vehicle movement from	N	to S	No tow / articulation
On main carriageway			Leaving the main road
Location at impact	Not at, or within 20M of Jct	First impact	Front
Hit object in road	None	Off road:	None
Did not leave carr		Age of Driver	23
Not hit and run	Breath test	Negative	Male
		Left hand drive:	No

Casualty Reference:	5	Vehicle:	2	Age:	23	Male	Driver/rider	Severity:	Slight
Not a pupil									
Seatbelt		Not Applicable		Cycle helmet: Not a cyclist					

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

160152044 22/04/2016 Time 1040 Vehicles 2 Casualties 1 Slight
E:469653 N: 106149 First Road: (M) 3 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Loss of control	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG A3(M) SOUTHBOUND LOST CONTROL, COLLIDED WITH THE
NEARSIDE BARRIER AND REBOUNDED BACK INTO THE CARRIAGEWAY, COLLIDING WITH VEH 2 (CAR).
Occurred on A3(M) SOUTHBOUND MARKER POST 0.9, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Nearside Hit vehicle:
Hit object in road None Off road: Near / off crash barrier
Nearside & rebounded Age of Driver 46 Female
Not hit and run Breath test Negative
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 46 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 57 Male
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

160179160 13/05/2016 Time 0740 Vehicles 3 Casualties 1 Slight
E:469841 N: 105693 First Road: A 27 Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to judge other persons path or speed	Vehicle 1	Possible
2nd:	Loss of control	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING S ALONG A27 HARTS FARM WAY LINK ROAD OVER BRIDGE, OVERTOOK VEH 2 (CAR) HOWEVER CLIPPED ITS OFFSIDE WING MIRROR. VEH 1 LOSES BALANCE AND CLIPS OFFSIDE WING MIRROR OF VEH 3 (CAR) IN FRONT.

Occurred on A27 HARTS FARM WAY LINK ROAD 85 METRES NORTH OF A27 WESTBOUND OFFSLIP, HAVANT, HAMPSHIRE

Vehicle Reference 1 Motor Cycle over 50 cc and up to 125cc Overtaking moving vehicle O/S
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 54 Male
Not hit and run Breath test Negative
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 54 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 47 Female
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

Vehicle Reference	3	Car	Going ahead other
Vehicle movement from	N	to S	No tow / articulation
On main carriageway			Leaving the main road
Location at impact	Not at, or within 20M of Jct	First impact	No skidding, jack-knifing or overturning
Hit object in road	None	Off road:	Offside
Did not leave carr			Hit vehicle:
Not hit and run	Breath test	Negative	Age of Driver
			27
			Female
			Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

160189435 20/05/2016 Time 1745 Vehicles 2 Casualties 1 Slight
E:469760 N: 106156 First Road: B 2177 Road Type Single carriageway
Speed limit: 40 Junction Detail: Roundabout Give way or controlled A(M) 3
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAV NE ON B2177 BEDHAMPTON HILL ROAD IN HEAVY TRAFFIC HAVING JUST EXITED THE
A3(M) JUNCTION 5 RBT CARRIED OUT A U-TURN INTO THE PATH OF VEH 2 (M/CYCLE) WHICH WAS
FILTERING PAST THE TRAFFIC, CAUSING VEH 2 TO COLLIDE WITH THE OFFSIDE OF VE
Occurred on B2177 BEDHAMPTON HILL ROAD AT JUNCTIO WITH A3(M) JUNCTION 5, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car U-turn
Vehicle movement from SW to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Cleared junction or waiting/park First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 43 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Motor Cycle over 50 cc and up to 125cc Overtaking moving vehicle O/S
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Cleared junction or waiting/park First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 27 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 27 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

160191261 22/05/2016 Time 1244 Vehicles 2 Casualties 1 Slight
E:469826 N: 105719 First Road: A 2030 Road Type Single carriageway
Speed limit: 60 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING NW ALONG A2030 HARTS FARM WAY COLLIDED WITH VEH 2 (P/CYCLE) WHICH
CROSSED FROM THE NEARSIDE INTO VEH 1'S PATH.

Occurred on A2030 HARTS FARM WAY 40 METRES SOUTH-EAST OF A27 EASTBOUND ONSLIP RBT,
HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from SE to NW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 22 Female
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Pedal Cycle Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 15 Male
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 15 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

160199520 28/05/2016 Time 1310 Vehicles 1 Casualties 2 Serious
E:469652 N: 106136 First Road: (M) 3 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Swerved	Vehicle 1	Very Likely
2nd:	Distraction in vehicle	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG A3(M) IN LANE 2, DRIVER ADJUSTS THE AIRCON AND SWERVED
ONTO CENTRAL RESERVATION BEFORE CUTTING ACROSS LANE 2 AND 1 AND COLLIDING WITH THE
NEARSIDE BARRIER AND CAUSING CAR TO SOMERSAULT 4 TIMES BEFORE LANDING ON IT'S ROO
Occurred on A3(M) SOUTHBOUND AT MARKER POST 0.9, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from NW to S No tow / articulation Leaving the main road
On main carriageway Skidded and overturned
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: Cent crash barrier
O/S onto cent res & rebounded Age of Driver 18 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 18 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Casualty Reference: 2 Vehicle: 1 Age: 23 Male Passenger Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Front seat

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

160237417 25/06/2016 Time 2305 Vehicles 3 Casualties 4 Slight
E:469420 N: 105436 First Road: A 27 Road Type Slip road
Speed limit: 70 Junction Detail: Slip Road Give way or controlled A(M) 3
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: no street lighting Fine without high winds
Special Conditions at Site None Carriageway Hazards: Inv with prev acc
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 3	Possible
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SW ALONG A27 WESTBOUND ONSLIP FROM A3(M) WAS INVOLVED IN A PREVIOUS COLLISION. VEH 2 (CAR) STOPPED TO ASSIST. VEH 3 (CAR) THEN COLLIDED WITH THE REAR OF VEH 2, PUSHING VEH 2 INTO THE REAR OF VEH 1.

Occurred on A27 WESTBOUND AT JUNCTION WITH A3(M) SOUTHBOUND JUNCTION 5, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Parked
Vehicle movement from Park to Parked No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Entering from slip road First impact Back Hit vehicle:
Hit object in road None Off road: Near / off crash barrier
Did not leave carr Age of Driver 17 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Taxi/Private hire car Parked
Vehicle movement from Park to Parked No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Entering from slip road First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 32 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 32 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Casualty Reference: 2 Vehicle: 2 Age: 39 Female Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
Back seat

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

Vehicle Reference	3	Car	Going ahead other
Vehicle movement from	NE	to SW	No tow / articulation
On main carriageway			Leaving the main road
Location at impact	Entering from slip road		No skidding, jack-knifing or overturning
Hit object in road	None		First impact Front
			Off road: None
Did not leave carr			Hit vehicle:
Not hit and run			Age of Driver 31
	Breath test	Negative	Male
			Left hand drive: No

Casualty Reference:	3	Vehicle:	3	Age:	31	Male	Driver/rider	Severity:	Slight
Not a pupil									
Seatbelt		Not Applicable		Cycle helmet: Not a cyclist					

Casualty Reference:	4	Vehicle:	3	Age:	28	Male	Passenger	Severity:	Slight
Not a pupil									
Seatbelt		Not Applicable		Cycle helmet: Not a cyclist					

Front seat

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

160293622 06/08/2016 Time 1030 Vehicles 4 Casualties 1 Slight
E:469516 N: 105576 First Road: A 27 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to judge other persons path or speed	Vehicle 1	Possible
2nd:	Failed to judge other persons path or speed	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING NE ALONG A27 IN LANE 1 COLLIDES WITH THE REAR OF VEH 2 (CAR) IN LANE 1, SHUNTING VEH 2 INTO THE REAR OF VEH 3 (CAR) SLOWING, SHUNTING VEH 3 INTO THE REAR OF VEH 4 (CAR) SLOWING DUE TO EMERGING TRAFFIC FROM SLIP ROAD.

Occurred on A27 EASTBOUND MARKER POST 50.8, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 43 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 46 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 46 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

Vehicle Reference	3	Car	Going ahead other
Vehicle movement from	SW to NE	No tow / articulation	Leaving the main road
On main carriageway		No skidding, jack-knifing or overturning	
Location at impact	Not at, or within 20M of Jct	First impact	Back
Hit object in road	None	Off road:	None
Did not leave carr		Age of Driver	25
Not hit and run	Breath test	Negative	Female
		Left hand drive:	No

Vehicle Reference	4	Car	Going ahead other
Vehicle movement from	SW to NE	No tow / articulation	Leaving the main road
On main carriageway		No skidding, jack-knifing or overturning	
Location at impact	Not at, or within 20M of Jct	First impact	Back
Hit object in road	None	Off road:	None
Did not leave carr		Age of Driver	38
Not hit and run	Breath test	Negative	Female
		Left hand drive:	No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

160310519 18/08/2016 Time 1900 Vehicles 2 Casualties 1 Slight
E:467895 N: 105712 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (VAN) TRAVELLING NE ALONG A2030 HAVANT ROAD IN LANE 2 AND COLLIDES WITH THE REAR
OF VEH 2 (CAR) TRAVELLING IN THE SAME DIRECTION WHERE THE TWO LANES MERGE TOGETHER.
Occurred on A2030 HAVANT ROAD OUTSIDE NUMBER 348, FARLINGTON, HAMPSHIRE

Vehicle Reference 1 Van or Goods 3.5 tonnes mgw and under Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 21 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 34 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 34 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

160309813 18/08/2016 Time 1020 Vehicles 1 Casualties 1 Serious
E:469739 N: 106073 First Road: (M) 3 Road Type Single carriageway
Speed limit: 60 Junction Detail: Roundabout Give way or controlled A 2030
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Aggressive driving	Vehicle 1	Possible
2nd:	Failed to judge other persons path or speed	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING S ON THE RBT FROM A3(M) SOUTHBOUND ONTO A2030 LOST CONTROL
ON THE EXIT FROM THE RBT, CAUSING THE RIDER TO FALL.

Occurred on A3(M) SOUTHBOUND AT JUNCTION WITH A2030 HARTS FARM WAY, HAVANT, HAMPSHIRE

Vehicle Reference 1 Motorcycle over 500cc Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Leaving roundabout First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 48 Male
Not hit and run Breath test Not requested
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 48 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

160314032 21/08/2016 Time 1645 Vehicles 2 Casualties 1 Slight
E:469800 N: 105789 First Road: A 27 Road Type Single carriageway
Speed limit: 60 Junction Detail: Roundabout Give way or controlled A 27
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Daylight Raining with high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Careless/Reckless/In a hurry	Vehicle 1	Possible
3rd:	Distraction in vehicle	Vehicle 1	Possible
4th:	Sudden braking	Vehicle 2	Possible
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG A27 HARTS FARM WAY FAILED TO BRAKE IN TIME AND COLLIDED WITH REAR OF VEH 2 (CAR) SLOWING FOR GIVE WAY LINES AT RBT IN FRONT. VEH 1 NOT AWARE OF GIVE WAY LINES AND WAS NOT EXPECTING TO HAVE TO STOP.

Occurred on A27 HARTS FARM WAY AT JUNCTION WITH A27 EASTBOUND ONSLIP, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 29 Female
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Stopping
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 46 Female
Not hit and run Breath test Not requested
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 46 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

160325767 30/08/2016 Time 0915 Vehicles 2 Casualties 1 Slight
E:469734 N: 105662 First Road: A 27 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Distraction in vehicle	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (GOODS VEH) TRAVELLING W IN LANE 1 OF A27 IN SLOW MOVING TRAFFIC, WHILE DRIVER
REACHES FOR TISSUES ON FLOOR FAILS TO SEE VEH 2 (CAR) IN FRONT AND COLLIDES TWICE.

Occurred on A27 WESTBOUND MARKER POST 51.0, HAVANT, HAMPSHIRE

Vehicle Reference 1 Goods 7.5 tonnes mgw and over Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 64 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 60 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 60 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

160351687 17/09/2016 Time 1745 Vehicles 2 Casualties 3 Slight
E:468774 N: 105826 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to judge other persons path or speed	Vehicle 1	Very Likely
2nd:	Careless/Reckless/In a hurry	Vehicle 1	Possible
3rd:	Dazzling sun	Vehicle 1	
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAV W ON A2030 HAVANT ROAD TURNED RIGHT FOR RECTORY AVENUE INTO PATH OF
VEH 2 (BUS) TRAV E, CAUSING VEH 2 TO COLLIDE WITH THE NEARSIDE OF VEH 1, PUSHING VEH 1 BACK
ACROSS THE ROAD INTO A BUS STOP AND FORCING VEH 2 ONTO THE NEARSIDE VERGE
Occurred on A2030 HAVANT ROAD AT JUNCTION WITH RECTORY AVENUE, FARLINGTON, HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from E to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Leaving main road First impact Nearside Hit vehicle:
Hit object in road None Off road: Bus stop / shelter
Nearside Age of Driver 23 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 23 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Casualty Reference: 2 Vehicle: 1 Age: 23 Female Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Front seat

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

Vehicle Reference	2	Bus or coach	Going ahead other
Vehicle movement from	W	to E	No tow / articulation
On main carriageway			Leaving the main road
Location at impact	Jct Approach		No skidding, jack-knifing or overturning
Hit object in road	None		First impact Front
Nearside			Hit vehicle:
Not hit and run			Off road: Road sign / ATS
			Age of Driver 46
			Male
		Breath test	Negative
			Left hand drive: No
Casualty Reference:	3	Vehicle: 2	Age: 58
			Male
			Passenger
			Severity: Slight
			Not a pupil
			Seatbelt Not Applicable
			Cycle helmet: Not a cyclist
			Not car passenger
			Seated bu

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

Notes:

160367807 29/09/2016 Time 0640 Vehicles 1 Casualties 1 Serious
E:470020 N: 106567 First Road: B 2177 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: Central reservation Road surface Wet/Damp
Daylight Raining with high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Inexperienced or learner driver/rider	Vehicle 1	Very Likely
2nd:	Slippery road (due to weather)	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING SW ALONG B2177 BEDHAMPTON ROAD ON WET ROAD SURFACE WHEN REAR WHEEL LOST TRACTION ON RECENTLY PAINTED ROAD MARKING CAUSING VEH TO LOSE CONTROL AND RIDER TO FALL OFF.

Occurred on B2177 BEDHAMPTON ROAD AT JUNCTION WITH BROOKSIDE ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Motor Cycle over 50 cc and up to 125cc Going ahead other
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Mid Junction - on roundabout or r First impact Did not impact Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 18 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 18 Female Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

160475037 17/12/2016 Time 1300 Vehicles 2 Casualties 1 Slight
E:469692 N: 106162 First Road: (M) 3 Road Type Slip road
Speed limit: 60 Junction Detail: Roundabout Automatic traffic signal B 2177
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Impaired by alcohol	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (VAN) TRAVELLING SW ALONG A3(M) OFFSLIP AND COLLIDES WITH THE REAR OF VEH 2 (CAR)
STATIONARY AT JUNCTION, SHUNTING VEH 2 ONTO THE CENTRAL VERGE.

Occurred on A3(M) SOUTHBOUND OFFSLIP AT JUNCTION WITH B2177 BEDHAMPTON HILL , HAVANT,
HAMPSHIRE

Vehicle Reference 1 Van or Goods 3.5 tonnes mgw and under Going ahead other
Vehicle movement from NW to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 29 Male
Not hit and run Breath test Positive
Left hand drive: No

Vehicle Reference 2 Car Going ahead but held up
Vehicle movement from NW to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 31 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 24 Female Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
Front seat

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

Notes:

44170197247 25/05/2017 Time 1619 Vehicles 2 Casualties 1 Slight
E:468290 N: 105777 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to judge other persons path or speed	Vehicle 1	Possible
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING N ALONG LOWER FARLINGTON ROAD AND TURNS RIGHT ONTO A2030
HAVANT ROAD AS DRIVER BELIEVED THAT VEH 2 (CAR) TRAVELLING W ALONG A2030 HAVANT ROAD
WAS INDICATING LEFT BUT WAS NOT AND COLLIDED

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH LOWER FARLINGTON ROAD, PORTSMOUTH,
HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from S to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 45 Female
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 85 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 85 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

Notes:

44170200598 01/06/2017 Time 2220 Vehicles 2 Casualties 1 Slight
E:468034 N: 105730 First Road: A 2030 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: Pelican, puffin, toucan etc. Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 1	Possible
2nd:	Failed to look properly	Vehicle 1	Possible
3rd:	Careless/Reckless/In a hurry	Vehicle 1	Possible
4th:	Disobeyed Give Way or Stop sign or markings	Vehicle 1	Possible
5th:			
6th:			

VEH 1 (CAR) TRAVELLING E ALONG A2030 HAVANT ROAD PERFORMS A U-TURN IN GALT ROAD TURNING RIGHT ACROSS THE PATH OF VEH 2 (CAR) TRAVELLING E ALONG A2030 HAVANT ROAD AND COLLIDES, CAUSING VEH 1 TO SPIN 180 DEGREES.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH GALT ROAD, FARLINGTON, HAMPSHIRE

Vehicle Reference 1 Car U-turn
Vehicle movement from W to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Offside Hit vehicle:
Hit object in road None Off road: None
O/S Age of Driver 45 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Going ahead other
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 29 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 29 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

Notes:

44170380770 01/10/2017 Time 1845 Vehicles 3 Casualties 2 Slight
E:469313 N: 105486 First Road: A 27 Road Type Dual carriageway
Speed limit: 70 Junction Detail: Slip Road Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: no street lighting Raining without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 1	Possible
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 HAS CHANGED LANE, STRIKING VEH 2 . VEH 2 HAS SPUN, IMPACTING WITH THE REAR OF VEH 3.
VEH 3 HAS LEFT THE CARRIAGEWAY TO THE NEARSIDE AND STRUCK THE BARRIERS.

Occurred on A27 EASTBOUND AT JUNCTION WITH A27 FARLINGTON OFFSLIP, FARLINGTON, HAMPSHIRE

Vehicle Reference 1 Car Changing lane to left
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver Not traced
Non-stop, not hit Breath test Driver not contacted
Left hand drive: No

Vehicle Reference 2 Car Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 29 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 2 Vehicle: 2 Age: 29 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("AW
CHQ/SR/0418/058 HAVANT ROAD")

Vehicle Reference	3	Car	Going ahead other
Vehicle movement from	SW	to NE	No tow / articulation
On main carriageway			Leaving the main road
Location at impact	Jct Approach		No skidding, jack-knifing or overturning
Hit object in road	None		First impact Back
Did not leave carr			Off road: None
Not hit and run			Age of Driver 50
	Breath test	Negative	Female
			Left hand drive: No

Casualty Reference:	1	Vehicle:	3	Age:	50	Female	Driver/rider	Severity:	Slight
Not a pupil									
Seatbelt	Not Applicable			Cycle helmet:	Not a cyclist				

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

44170494532 21/12/2017 Time 2040 Vehicles 2 Casualties 1 Slight
E:469558 N: 106043 First Road: A 2030 Road Type Single carriageway
Speed limit: 60 Junction Detail: Roundabout Give way or controlled A(M) 3
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 2	Very Likely
2nd:	Other	Vehicle 2	Very Likely
3rd:	Illegal turn or direction of travel	Vehicle 2	
4th:			
5th:			
6th:			

DRIVER WAS FOLLOWING SAT NAV INSTRUCTIONS AND WENT WRONG WAY AROUND RBT VEH1 (CAR) TRAVELLING N ON FORTY ACRES ROUNDABOUT COLLIDES HEAD ON WITH VEH2 (CAR) THAT WAS TRAVELLING THE WRONG WAY AROUND THE ROUNDABOUT. DRIVER OF VEH1 SUFFERED MINOR INJURY.

Occurred on A2030 HAVANT ROAD AT JUNCTION WITH A3(M) SLIP ROAD, HAVANT, HAMPSHIRE.

Vehicle Reference 1 Car Going ahead right bend
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 59 Female
Not hit and run Breath test Negative
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 59 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Going ahead left bend
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 77 Male
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

120007012 04/01/2012 Time 1700 Vehicles 2 Casualties 2 Slight
E:469698 N: 105999 First Road: A 27 Road Type Single carriageway
Speed limit: 40 Junction Detail: Roundabout Give way or controlled A(M) 3
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Raining with high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Possible
2nd:	Failed to judge other persons path or speed	Vehicle 2	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 2 (CAR) TRAVELLING N ALONG A27 LINK ROAD, FAILS TO STOP IN TIME AND COLLIDES WITH THE REAR OF VEH 1 (CAR) STATIONARY IN FRONT WAITING TO ENTER RBT INTENDING TO JOIN A3(M) NORTHBOUND. VEH 2 FAILED TO STOP.

Occurred on A27 LINK ROAD AT JUNCTION WITH A3(M) NORTHBOUND, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead but held up
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Back Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 31 Female
Not hit and run Breath test Driver not contacted
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 31 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Casualty Reference: 2 Vehicle: 1 Age: 10 Female Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Front seat

Vehicle Reference 2 Car Stopping
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver Male
Hit and run Breath test Driver not contacted
Left hand drive:

Accidents between dates 01/01/2012 and 31/12/2017 (72) months

Selection:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("AW CHQ/SR/0418/058 HAVANT ROAD")

Notes:

Accidents involving:

	Fatal	Serious	Slight	Total
Motor vehicles only (excluding 2-wheels)	0	5	40	45
2-wheeled motor vehicles	0	6	8	14
Pedal cycles	0	1	5	6
Horses & other	0	0	0	0
Total	0	12	53	65

Casualties:

	Fatal	Serious	Slight	Total
Vehicle driver	0	2	41	43
Passenger	0	2	16	18
Motorcycle rider	0	6	8	14
Cyclist	0	1	5	6
Pedestrian	0	1	2	3
Other	0	0	0	0
Total	0	12	72	84