

Appendix B

Site No: 00005645
SINAH LANE HAYLING ISLAND EASTERN SITE

Site Reference: 00005645

From 23/06/2016 To 04/07/2016

Channel: WESTBOUND

Time	Total	85th	Mean	Std.	Bin 1	Bin 2	Bin 3	Bin 4	Bin 5	Bin 6	Bin 7	Bin 8	Bin 9	Bin 10	Bin 11	Bin 12	Bin 13
Begin	Vol.	%ile	Ave.	Dev.	<16Mph	16-<21	21-<26	26-<31	31-<36	36-<41	41-<46	46-<51	51-<56	56-<61	61-<66	66-<71	=>71
0:00	7	-	25.5	6.1	0	2	1	0	0	0	0	0	0	0	0	0	0
1:00	3	-	24.9	-	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	2	-	24.4	4.2	0	0	1	0	0	0	0	0	0	0	0	0	0
3:00	0	-	22.3	-	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	2	-	25.6	7.8	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	7	-	26.6	8.9	1	0	0	0	1	0	0	0	0	0	0	0	0
6:00	23	33.5	25.6	7.4	3	6	3	6	4	0	0	0	0	0	0	0	0
7:00	62	32.3	25.2	7.1	5	14	13	18	9	2	0	0	0	0	0	0	0
8:00	97	30.4	23.8	6.7	7	29	25	23	8	3	0	0	0	0	0	0	0
9:00	122	28.9	22.1	6.1	16	45	31	23	8	1	0	0	0	0	0	0	0
10:00	133	28.1	21.5	5.7	18	50	34	24	6	0	0	0	0	0	0	0	0
11:00	160	28.6	22.1	6	18	59	44	27	10	1	0	0	0	0	0	0	0
12:00	169	28.8	22.1	6	20	61	42	35	8	1	0	0	0	0	0	0	0
13:00	142	28.5	21.9	5.9	16	55	36	25	9	0	0	0	0	0	0	0	0
14:00	126	28.3	21.5	6.1	20	47	29	24	6	0	0	0	0	0	0	0	0
15:00	155	29.2	22.6	6	15	57	39	32	10	3	0	0	0	0	0	0	0
16:00	158	29.7	22.8	6.2	16	56	35	35	14	1	0	0	0	0	0	0	0
17:00	146	30	23.4	6.1	11	51	33	38	12	2	0	0	0	0	0	0	0
18:00	128	30	23.2	6.2	10	44	31	28	12	2	0	0	0	0	0	0	0
19:00	106	30.4	23.8	6.1	5	34	28	23	11	0	0	0	0	0	0	0	0
20:00	62	30.5	23.8	6.5	5	20	13	15	7	1	0	0	0	0	0	0	0
21:00	49	30.3	23.8	6.9	4	15	11	11	4	1	0	0	0	0	0	0	0
22:00	28	31.3	24.1	7.1	2	10	8	5	4	1	0	0	0	0	0	0	0
23:00	15	30.3	24.3	6.5	0	5	3	4	1	0	0	0	0	0	0	0	0
12H,7-19	1598	29.3	22.5	6	171	567	392	330	112	16	0	0	0	0	0	0	0
16H,6-22	1838	29.5	22.6	6.1	188	641	448	385	138	18	0	0	0	0	0	0	0
18H,6-24	1881	29.5	22.6	6.1	190	656	459	394	143	19	0	0	0	0	0	0	0
24H,0-24	1903	29.5	22.6	6.1	191	658	462	394	144	19	0	0	0	0	0	0	0
Am	11:00	-	4:30	-	10:30	11:00	11:00	11:00	7:30	8:00	6:45	0:15	8:30	-	-	-	-
Peak	159	-	26.9	-	19	58	44	28	10	3	1	0	0	-	-	-	-
Pm	12:00	22:15	22:30	22:00	12:00	12:15	12:00	16:30	16:30	16:45	21:00	18:30	21:00	-	-	-	-
Peak	168	31.7	24.4	7.1	20	63	42	38	14	3	1	0	0	-	-	-	-

Collated from 15 minute interval data

Created at 21:09:42 on 3 Jul 2016

Site No: 00005645
SINAH LANE HAYLING ISLAND EASTERN SITE

Site Reference: 00005645

From 23/06/2016 To 04/07/2016

Channel: EASTBOUND

Time	Total	85th	Mean	Std.	Bin 1	Bin 2	Bin 3	Bin 4	Bin 5	Bin 6	Bin 7	Bin 8	Bin 9	Bin 10	Bin 11	Bin 12	Bin 13
Begin	Vol.	%ile	Ave.	Dev.	<16Mph	16-<21	21-<26	26-<31	31-<36	36-<41	41-<46	46-<51	51-<56	56-<61	61-<66	66-<71	=>71
0:00	4	-	22.8	8.2	1	0	0	0	0	0	0	0	0	0	0	0	0
1:00	3	-	23.2	11.7	0	0	0	0	0	0	0	0	0	0	0	0	0
2:00	0	-	17.6	-	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	-	19.3	-	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	1	-	26.8	-	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	10	31.5	23.5	8.2	3	1	1	1	1	0	0	0	0	0	0	0	0
6:00	38	31.3	21.9	8.7	14	6	4	8	4	3	0	0	0	0	0	0	0
7:00	98	30.1	21.5	7.8	30	20	14	20	10	2	0	0	0	0	0	0	0
8:00	139	29.7	21.6	7.3	40	26	24	36	9	0	0	0	0	0	0	0	0
9:00	144	28.3	20.5	6.9	49	27	36	26	6	0	0	0	0	0	0	0	0
10:00	139	27.8	20.2	6.7	50	25	35	26	4	0	0	0	0	0	0	0	0
11:00	146	27.7	20	6.7	52	30	32	24	6	1	0	0	0	0	0	0	0
12:00	126	28.8	20.8	7.1	41	23	29	24	8	0	0	0	0	0	0	0	0
13:00	127	28.7	20.8	7.1	42	23	29	25	7	0	0	0	0	0	0	0	0
14:00	126	27.8	19.7	7	50	23	26	20	6	0	0	0	0	0	0	0	0
15:00	114	28.8	20.7	7.1	38	19	24	23	5	0	0	0	0	0	0	0	0
16:00	119	29.1	21.1	7.1	38	20	28	24	8	1	0	0	0	0	0	0	0
17:00	107	29.9	21.9	7.4	32	17	22	27	8	0	0	0	0	0	0	0	0
18:00	93	30	21.8	7.5	27	17	17	23	8	0	0	0	0	0	0	0	0
19:00	72	30.2	21.8	7.7	22	13	13	15	6	3	0	0	0	0	0	0	0
20:00	51	30.1	21.9	7.8	16	8	8	12	5	1	0	0	0	0	0	0	0
21:00	38	29.3	21.2	7.4	11	12	4	8	3	0	0	0	0	0	0	0	0
22:00	20	29	21.7	7.1	6	4	4	5	0	0	0	0	0	0	0	0	0
23:00	10	29.9	22.8	7.6	3	1	1	2	1	0	0	0	0	0	0	0	0
12H,7-19	1479	28.9	20.7	6.9	487	272	315	298	86	6	0	0	0	0	0	0	0
16H,6-22	1678	29	20.8	7.1	551	312	344	341	104	13	0	0	0	0	0	0	0
18H,6-24	1708	29	20.8	7	560	317	349	348	105	13	0	0	0	0	0	0	0
24H,0-24	1726	29.1	20.8	7.1	564	318	350	349	107	13	0	0	0	0	0	0	0
Am	11:00	-	4:00	-	11:00	11:00	9:30	8:00	7:30	6:00	6:30	8:00	5:30	-	-	-	-
Peak	146	-	26.8	-	52	30	36	36	10	2	0	0	0	-	-	-	-
Pm	13:45	18:15	22:30	22:15	13:45	13:45	13:00	17:00	18:15	18:45	18:30	22:00	-	-	-	-	-
Peak	128	30.5	22.8	8.2	50	24	29	27	9	2	0	0	-	-	-	-	-

Collated from 15 minute interval data

Created at 21:09:43 on 3 Jul 2016

Site No: 00089645
SINAH LANE HAYLING ISLAND WESTERN SITE

Site Reference: 00089645

From 23/06/2016 To 02/07/2016 Channel: EASTBOUND

Time	Total	85th	Mean	Std.	Bin 1	Bin 2	Bin 3	Bin 4	Bin 5	Bin 6	Bin 7	Bin 8	Bin 9	Bin 10	Bin 11	Bin 12	Bin 13
Begin	Vol.	%ile	Ave.	Dev.	<16Mph	16-<21	21-<26	26-<31	31-<36	36-<41	41-<46	46-<51	51-<56	56-<61	61-<66	66-<71	=>71
0:00	2	-	28.6	-	0	0	0	2	0	0	0	0	0	0	0	0	0
1:00	2	-	24.6	-	0	0	2	0	0	0	0	0	0	0	0	0	0
2:00	0	-	20.4	-	0	0	0	0	0	0	0	0	0	0	0	0	0
3:00	0	-	23.5	-	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	1	-	27.4	-	0	0	0	1	0	0	0	0	0	0	0	0	0
5:00	8	-	29.4	4.2	0	2	1	3	1	0	0	0	0	0	0	0	0
6:00	39	-	28.3	4	8	9	8	7	4	3	0	0	0	0	0	0	0
7:00	95	31.3	27.6	4.6	27	17	14	23	10	4	0	0	0	0	0	0	0
8:00	130	30.6	27.1	4.5	22	34	28	38	7	0	0	0	0	0	0	0	0
9:00	147	30.5	26.5	5	54	25	29	29	8	0	0	0	0	0	0	0	0
10:00	142	30.3	25.7	4.8	44	31	28	32	7	0	0	0	0	0	0	0	0
11:00	143	30.5	26.4	4.9	43	38	34	22	5	0	0	0	0	0	0	0	0
12:00	123	31.9	27.6	4.6	34	29	32	22	7	0	0	0	0	0	0	0	0
13:00	125	32.3	27.3	5.3	38	24	27	26	8	0	0	0	0	0	0	0	0
14:00	129	30.6	26.6	5.3	47	26	24	24	8	0	0	0	0	0	0	0	0
15:00	106	30.5	26.8	4.7	28	22	22	29	5	0	0	0	0	0	0	0	0
16:00	111	32.2	27.7	4.6	31	19	26	22	11	1	0	0	0	0	0	0	0
17:00	109	30.7	26.5	4.9	30	18	29	26	6	0	0	0	0	0	0	0	0
18:00	89	31.7	27.1	4.8	19	17	23	21	9	0	0	0	0	0	0	0	0
19:00	69	32.2	26.9	4.7	19	12	13	16	6	3	0	0	0	0	0	0	0
20:00	55	32.3	27.8	4.4	14	11	11	12	5	1	0	0	0	0	0	0	0
21:00	36	33.6	29.1	5	8	10	6	7	4	0	0	0	0	0	0	0	0
22:00	16	32.3	26.9	5.1	2	4	2	5	3	0	0	0	0	0	0	0	0
23:00	11	33.9	28.7	5	1	1	1	2	4	0	0	0	0	0	0	0	0
12H,7-19	1449	30.9	26.9	4.3	417	300	316	314	91	5	0	0	0	0	0	0	0
16H,6-22	1664	31.1	27	4.4	466	342	354	356	110	12	0	0	0	0	0	0	0
18H,6-24	1675	31.1	27	4.3	469	347	357	363	117	12	0	0	0	0	0	0	0
24H,0-24	1688	31.1	27	4.4	469	349	360	369	118	12	0	0	0	0	0	0	0
Am	0.427083	-	0.010417	-	0.375	0.427083	0.427083	0.354167	0.291667	0.291667	0.3125	-	-	-	-	-	-
Peak	46	-	30.3	-	54	39	35	40	10	4	0	-	-	-	-	-	-
Pm	0.666667	-	0.875	0.885417	0.552083	0.59375	0.729167	0.677083	0.510417	0.791667	0.8125	-	-	-	-	-	-
Peak	40	-	29.1	5.9	49	30	30	27	11	3	0	-	-	-	-	-	-

Collated from 15 minute interval data

Created at 07:28:41 on 5 Jul 2016

Site No: 00089645
SINAH LANE HAYLING ISLAND WESTERN SITE

Site Reference: 00089645

From 23/06/2016 To 02/07/2016 Channel: WESTBOUND

Time	Total	85th	Mean	Std.	Bin 1	Bin 2	Bin 3	Bin 4	Bin 5	Bin 6	Bin 7	Bin 8	Bin 9	Bin 10	Bin 11	Bin 12	Bin 13
Begin	Vol.	%ile	Ave.	Dev.	<16Mph	16-<21	21-<26	26-<31	31-<36	36-<41	41-<46	46-<51	51-<56	56-<61	61-<66	66-<71	=>71
0:00	4	-	32.7	-	0	0	1	0	3	0	0	0	0	0	0	0	0
1:00	3	-	24.8	-	0	0	3	0	0	0	0	0	0	0	0	0	0
2:00	1	-	25.3	-	0	0	1	0	0	0	0	0	0	0	0	0	0
3:00	0	-	26.2	-	0	0	0	0	0	0	0	0	0	0	0	0	0
4:00	1	-	30.3	3.7	0	0	0	0	0	0	0	0	0	0	0	0	0
5:00	5	-	33.5	-	1	0	0	0	1	0	0	0	0	0	0	0	0
6:00	19	34.5	31.5	3.9	3	4	2	4	5	0	0	0	0	0	0	0	0
7:00	68	35	31	5.5	4	11	10	24	14	4	0	0	0	0	0	0	0
8:00	93	34	29.3	5.7	6	22	28	22	14	2	0	0	0	0	0	0	0
9:00	119	33	27.9	5.3	11	39	33	22	11	3	0	0	0	0	0	0	0
10:00	126	31.2	27.1	5	13	44	31	19	17	2	0	0	0	0	0	0	0
11:00	155	31	27.3	4.9	15	44	47	29	19	1	0	0	0	0	0	0	0
12:00	162	32.1	27.9	4.3	14	53	36	38	18	3	0	0	0	0	0	0	0
13:00	132	32.5	28.1	4.6	11	41	28	30	18	3	0	0	0	0	0	0	0
14:00	119	31.6	28	4	12	40	28	24	14	1	0	0	0	0	0	0	0
15:00	151	31.9	27.7	4.8	11	50	29	38	19	4	0	0	0	0	0	0	0
16:00	156	32.9	28.5	4.6	16	57	31	29	21	2	0	0	0	0	0	0	0
17:00	142	33.1	28.3	5.5	11	49	31	31	17	2	0	0	0	0	0	0	0
18:00	117	32.3	27.9	5.1	9	33	25	31	17	4	0	0	0	0	0	0	0
19:00	99	31.4	27.5	4.3	5	31	31	19	12	0	0	0	0	0	0	0	0
20:00	58	33.3	28.8	3.9	5	19	11	13	9	2	0	0	0	0	0	0	0
21:00	43	32.8	28	4.9	4	13	9	9	6	1	0	0	0	0	0	0	0
22:00	29	32.6	28.6	4	1	8	9	5	5	1	0	0	0	0	0	0	0
23:00	16	33.2	28.2	4.4	0	5	3	5	3	0	0	0	0	0	0	0	0
12H,7-19	1540	32.7	28.2	4.2	133	483	357	337	199	31	0	0	0	0	0	0	0
16H,6-22	1759	32.7	28.2	4.2	150	550	410	382	231	34	0	0	0	0	0	0	0
18H,6-24	1804	32.7	28.2	4.2	151	563	422	392	239	35	0	0	0	0	0	0	0
24H,0-24	1818	32.8	28.2	4.2	152	563	427	392	243	35	0	0	0	0	0	0	0
Am	0.458333	0.277083	0.229167	0.333333	0.385417	0.427083	0.458333	0.458333	0.354167	0.291667	-	-	-	-	-	-	-
Peak	155	35.4	33.9	5.7	15	48	47	29	14	4	-	-	-	-	-	-	-
Pm	0.677083	0.84375	0.84375	0.708333	0.6875	0.729167	0.5	0.677083	0.677083	0.625	-	-	-	-	-	-	-
Peak	158	33.6	29	5.5	17	58	36	39	23	4	-	-	-	-	-	-	-

Collated from 15 minute interval data

Created at 07:28:41 on 5 Jul 2016

Appendix C

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

Notes:

Selected Polygon: NS HAYLING ISLAND - PBA

120238380 21/06/2012 Time 1536 Vehicles 2 Casualties 1 Serious
E:471457 N: 99373 First Road: A 3023 Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: Zebra crossing Road surface Wet/Damp
Daylight Fine with high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to judge other persons path or speed	Vehicle 1	Very Likely
2nd:	Disobeyed pedestrian crossing facility	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING N ALONG A3023 BEACH ROAD SLOWS FOR ZEBRA CROSSING TO ALLOW A CYCLIST TO CROSS. VEH 1 BELIEVED VEH 2 (P/CYCLE) WHO WAS ON WESTSIDE PAVEMENT WAS GOING TO STOP ON PAVEMENT. VEH 1 CONTINUES ACROSS CROSSING AND HITS VEH 2.

Occurred on A3023 BEACH ROAD OUTSIDE NUMBER 53, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Car Starting
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 73 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Pedal Cycle Going ahead other
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 11 Male
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 11 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not known

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

120287837 25/07/2012 Time 2300 Vehicles 2 Casualties 1 Slight
E:471456 N: 99702 First Road: A 3023 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Distraction in vehicle	Vehicle 2	Possible
2nd:	Inexperienced or learner driver/rider	Vehicle 2	Possible
3rd:	Sudden braking	Vehicle 1	
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING N ALONG A3023 MANOR ROAD SLOWS TO A STOP HOWEVER FOLLOWING
VEH 2 (CAR) WHO IS KNOWN TO VEH 1, FAILS TO STOP IN TIME AND COLLIDES WITH REAR OF VEH 1
KNOCKING RIDER OFF.

Occurred on A3023 MANOR ROAD AT JUNCTION WITH FATHOMS REACH, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Motor Cycle over 50 cc and up to 125cc Stopping
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 17 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 17 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 18 Male
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

120340935 08/08/2012 Time 1030 Vehicles 1 Casualties 1 Slight
E:471258 N: 99596 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Driver using mobile phone	Vehicle 1	Very Likely
2nd:	Failed to look properly	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG STATION ROAD INTO A PARKING BAY OUTSIDE NUMBER 55
COLLIDED WITH CAS 1 (PEDESTRIAN) ON VEH 1'S FRONT.

Occurred on STATION ROAD AT JUNCTION WITH WEST LANE, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Car Stopping
Vehicle movement from NE to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Cleared junction or waiting/park First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 35 Female
Hit and run Breath test Driver not contacted
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 53 Male Pedestrian Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
On footpath / verge Standing still
Movement U/K

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

120423508 08/09/2012 Time 1001 Vehicles 1 Casualties 1 Slight
E:471275 N: 99596 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (MOBILITY SCOOTER) TRAVELLING SE ALONG NORTH PAVEMENT OF STATION ROAD COLLIDED
WITH BACK OF CAS 1 (PEDESTRIAN) ALSO TRAVELLING SE ALONG NORTH PAVEMENT OF STATION
ROAD.

Occurred on STATION ROAD AT JUNCTION WITH WEST LANE, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Mobility Scooter Going ahead other
Vehicle movement from NW to SE No tow / articulation Leaving the main road
9 No skidding, jack-knifing or overturning
Location at impact Cleared junction or waiting/park First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver Male
Not hit and run Breath test Not requested
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 65 Female Pedestrian Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
On footpath / verge SE bound
Movement U/K

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("NS HAYLING ISLAND - PBA")

120464238 29/11/2012 Time 1210 Vehicles 2 Casualties 1 Slight
E:470235 N: 99290 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 2	Possible
2nd:	Dazzling sun	Vehicle 2	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (P/CYCLE) TRAVELLING NE ALONG LINKS LANE WAS WAITING TO TURN RIGHT INTO FERRY ROAD. VEH 2 (CAR) TRAVELLING SE ALONG FERRY ROAD TURNED RIGHT INTO LINKS LANE AND COLLIDED WITH THE FRONT WHEEL OF VEH 2.

Occurred on FERRY ROAD AT JUNCTION WITH LINKS LANE, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Pedal Cycle Waiting to turn right
Vehicle movement from SW to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 66 Female
Not hit and run Breath test Not applicable
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 66 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: No

Vehicle Reference 2 Car Turning right
Vehicle movement from NW to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Leaving main road First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 85 Male
Not hit and run Breath test Not requested
Left hand drive: No

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

130123189 01/04/2013 Time 0340 Vehicles 1 Casualties 1 Slight
E:470806 N: 99758 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Slippery road (due to weather)	Vehicle 1	Possible
2nd:	Travelling too fast for conditions	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING W ALONG STATION LANE AT SPEED LOST CONTROL, MOUNTED THE KERB, COLLIDED WITH A TELEGRAPH POLE AND CAME TO REST IN A FRONT GARDEN HAVING DEMOLISHED THE GARDEN WALL.

Occurred on SINAH LANE OUTSIDE NUMBER 15, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
Hit object in road None Off road: Telegraph / Electricity pole
Nearside Age of Driver 21 Male
Not hit and run Breath test Negative
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 21 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("NS HAYLING ISLAND - PBA")

130124765 07/04/2013 Time 1448 Vehicles 2 Casualties 1 Slight
E:471692 N: 102017 First Road: U Road Type Single carriageway
Speed limit: 40 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 1	Very Likely
2nd:	Failed to look properly	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG S WEST LANE FAILS TO NEGOTIATE LEFT HAND BEND CORRECTLY CROSSING OVER THE CENTRAL LINE AND COLLIDES WITH VEH 2 (CAR) TRAVELLING IN THE OPPOSITE DIRECTION.

Occurred on WEST LANE 316 METRES NORTH OF DAW LANE, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Car Going ahead left bend
Vehicle movement from E to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 24 Male
Not hit and run Breath test Negative
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 22 Female Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Front seat

Vehicle Reference 2 Car Going ahead right bend
Vehicle movement from S to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 48 Male
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

130244330 04/07/2013 Time 0855 Vehicles 2 Casualties 1 Slight
E:472191 N: 99531 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control School crossing pat Facilities: Pelican, puffin, toucan etc. Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Very Likely
2nd:	Careless/Reckless/In a hurry	Vehicle 2	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 2 (CAR) TRAVELLING S ALONG ELM GROVE TURNED RIGHT INTO CHERRYWOOD GARDENS INTO THE PATH OF VEH 1 (P/CYCLE) TRAVELLING N ALONG ELM GROVE, CAUSING VEH 1 TO COLLIDE WITH THE NEARSIDE OF VEH 2 AND THE RIDER TO FALL.

Occurred on ELM GROVE AT JUNCTION WITH CHERRYWOOD GARDENS, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Pedal Cycle Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 27 Male
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 27 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not known

Vehicle Reference 2 Car Turning right
Vehicle movement from N to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 51 Male
Not hit and run Breath test Not requested
Left hand drive: No

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("NS HAYLING ISLAND - PBA")

130287665 02/08/2013 Time 1100 Vehicles 2 Casualties 1 Slight
E:471912 N: 99528 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Vehicle door opened or closed negligently	Vehicle 2	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 2 (CAR) PARKED AGAINST SOUTH KERB OF ST MARYS ROAD FACING W WHEN DRIVER OPENED DOOR INTO PATH OF VEH 1 (P/CYCLE) TRAVELLING W ALONG ST MARYS ROAD CAUSING VEH 1 TO HIT THE DOOR AND FALL OFF.

Occurred on ST MARYS ROAD OUTSIDE NUMBER 54, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Pedal Cycle Overtaking stat vehicle O/S
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 46 Male
Not hit and run Breath test Driver not contacted
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 46 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: No

Vehicle Reference 2 Van or Goods 3.5 tonnes mgw and under Parked
Vehicle movement from Park to Parked No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 56 Male
Not hit and run Breath test Driver not contacted
Left hand drive: No

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("NS HAYLING ISLAND - PBA")

Notes:

140020834 18/01/2014 Time 1630 Vehicles 2 Casualties 1 Slight
E:471339 N: 99807 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Raining without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Failed to judge other persons path or speed	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (VAN) TRAVELLING S ALONG WEST LANE, FAILS TO GIVE WAY AND ENTERS JUNCTION ACROSS THE PATH OF VEH 2 (CAR) TRAVELLING W ALONG WEST STREET CHANGES INTO NEWTON LANE AND COLIDES.

Occurred on WEST LANE AT JUNCTION WITH NEWTOWN LANE, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Van or Goods 3.5 tonnes mgw and under Starting
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 31 Female
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Going ahead right bend
Vehicle movement from SW to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 45 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 52 Female Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
Front seat

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

140060413 19/02/2014 Time 2130 Vehicles 1 Casualties 2 Serious
E:471275 N: 99582 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Raining without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Inexperienced or learner driver/rider	Vehicle 1	Very Likely
2nd:	Travelling too fast for conditions	Vehicle 1	Very Likely
3rd:	Loss of control	Vehicle 1	
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING E ALONG STATION ROAD LOST CONTROL ON A RIGHT-HAND BEND, MOUNTED THE NEAR SIDE PAVEMENT AND COLLIDED WITH A BOLLARD.

Occurred on STATION ROAD AT JUNCTION WITH WEST LANE, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Car Going ahead right bend
Vehicle movement from W to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Cleared junction or waiting/park First impact Front Hit vehicle:
Hit object in road None Off road: Oth perm objects
Nearside Age of Driver 18 Female
Not hit and run Breath test Not requested
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 18 Female Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Casualty Reference: 2 Vehicle: 1 Age: 18 Female Passenger Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Front seat

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

140176070 19/05/2014 Time 2120 Vehicles 1 Casualties 1 Slight
E:471685 N: 101603 First Road: U Road Type Single carriageway
Speed limit: 40 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: no street lighting Raining without high winds
Special Conditions at Site None Carriageway Hazards: Any animal in carriageway (except r
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Animal or object in carriageway	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING N ALONG WEST LANE COLLIDES WITH A DEER THAT RAN INTO THE ROAD.

Occurred on WEST LANE 100 METRES SOUTH OF DAW LANE, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Motor Cycle over 125 cc and up to 500cc Overtaking moving vehicle O/S
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road Any animal (except ridden horse) Off road: None
Did not leave carr Age of Driver 21 Male
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 21 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

140290842 12/08/2014 Time 0815 Vehicles 1 Casualties 1 Serious
E:470178 N: 99365 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Vehicle travelling along pavement	Vehicle 1	Possible
2nd:	Poor turn or manoeuvre	Vehicle 1	Possible
3rd:	Failed to look properly	Vehicle 1	Possible
4th:	Failed to look properly	Casualty 1	Possible
5th:	Failed to judge vehicles path or speed	Casualty 1	Possible
6th:			

VEH 1 (CAR) TRAVELLING SE ALONG FERRY ROAD COLLIDES WITH CAS 1 (PEDESTRIAN) TRAVELLING IN
THE SAME DIRECTION ON THE PAVEMENT, CAUSING CAS 1 TO FALL OVER. VEH 1 FAILS TO STOP

Occurred on FERRY ROAD AT JUNCTION WITH PARK ROAD, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from NW to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver Not traced
Hit and run Breath test Not requested Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 19 Female Pedestrian Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
On footpath / verge SE bound
Movement U/K

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("NS HAYLING ISLAND - PBA")

150086186 13/03/2015 Time 1016 Vehicles 3 Casualties 2 Serious
E:471459 N: 99321 First Road: A 3023 Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Illness or disability, mental or physical	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING N ALONG A3023 BEACH ROAD COLLIDES WITH VEH 2 (CAR) PARKED ON THE NEARSIDE. VEH 2 IS PUSHED FORWARD INTO VEH 3 (CAR) WHICH WAS ALSO PARKED. VEH 1 THEN ROLLS ONTO ITS ROOF.

Occurred on A3023 BEACH ROAD OUTSIDE OAK VIEW, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway Overturned
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 73 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 73 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Casualty Reference: 2 Vehicle: 1 Age: 72 Female Passenger Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Front seat

Vehicle Reference 2 Car Parked
Vehicle movement from Park to Parked No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver Unknown
Not hit and run Breath test Not requested
Left hand drive: No

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

Vehicle Reference	3	Car		Parked	
Vehicle movement from	Park to	Parked	No tow / articulation		Leaving the main road
On main carriageway				No skidding, jack-knifing or overturning	
Location at impact	Not at, or within 20M of Jct		First impact	Back	Hit vehicle:
Hit object in road	None		Off road:	None	
Did not leave carr				Age of Driver	Unknown
Not hit and run		Breath test	Not requested		
				Left hand drive:	No

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

Notes:

150098000 23/03/2015 Time 0955 Vehicles 2 Casualties 1 Slight
E:471362 N: 99497 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: Pelican, puffin, toucan etc. Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SE ALONG STATION ROAD WAS WAITING TO TURN RIGHT INTO A
COMMUNITY CENTRE. VEH 2 (CAR) FAILED TO STOP IN TIME AND COLLIDED WITH THE REAR OF VEH 1.
Occurred on STATION ROAD AT JUNCTION WITH COMMUNITY CENTRE ENTRANCE, HAYLING ISLAND,
HAMPSHIRE

Vehicle Reference 1 Car Waiting to turn right
Vehicle movement from NW to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 62 Female
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Going ahead other
Vehicle movement from NW to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 77 Female
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 77 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

150131740 20/04/2015 Time 0849 Vehicles 2 Casualties 1 Slight
E:472034 N: 99542 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Possible
2nd:	Failed to judge other persons path or speed	Vehicle 1	Possible
3rd:	Junction overshoot	Vehicle 2	
4th:			
5th:			
6th:			

VEH 2 (CAR) TRAVELLING N ALONG FIR TREE ROAD TURNED LEFT INTO CHERRYWOOD GARDENS AND COLLIDED WITH THE NEAR SIDE OF VEH 1 (P/CYCLE) TRAVELLING W, CAUSING THE RIDER TO FALL.

Occurred on CHERRYWOOD GARDENS AT JUNCTION WITH FIR TREE ROAD, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Pedal Cycle Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 31 Female
Not hit and run Breath test Not applicable
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 31 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Yes

Vehicle Reference 2 Car Turning left
Vehicle movement from S to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 45 Male
Not hit and run Breath test Driver not contacted
Left hand drive: No

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

150237409 11/07/2015 Time 1132 Vehicles 2 Casualties 4 Slight
E:471702 N: 102032 First Road: U Road Type Single carriageway
Speed limit: 40 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 1	Very Likely
2nd:	Loss of control	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG WEST LANE AROUND ACUTE LEFT HAND BEND CAUGHT UNAWARE
OF SEVERITY BRAKES LOCK UP, SKIDS CROSSING THE CENTRAL LINE AND COLLIDE WITH VEH 2 (CAR)
TRAVELLING IN THE OPPOSITE DIRECTION SPINS OFF TO THE NEARSIDE.

Occurred on WEST LANE 336 METRES NORTH OF DAW LANE, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Car Going ahead left bend
Vehicle movement from NE to S No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
O/S Age of Driver 36 Male
Not hit and run Breath test Not requested Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 36 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

Vehicle Reference	2	Car	Going ahead right bend
Vehicle movement from	S	to NE	No tow / articulation
On main carriageway			Leaving the main road
Location at impact	Not at, or within 20M of Jct	First impact	Offside
Hit object in road	None	Off road:	None
Nearside		Age of Driver	29
Not hit and run	Breath test	Not requested	Male
		Left hand drive:	No

Casualty Reference:	2	Vehicle:	2	Age:	29	Male	Driver/rider	Severity:	Slight
Not a pupil									
Seatbelt		Not Applicable		Cycle helmet: Not a cyclist					

Casualty Reference:	3	Vehicle:	2	Age:	19	Female	Passenger	Severity:	Slight
Not a pupil									
Seatbelt		Not Applicable		Cycle helmet: Not a cyclist					

Front seat

Casualty Reference:	4	Vehicle:	2	Age:	11	Female	Passenger	Severity:	Slight
Not a pupil									
Seatbelt		Not Applicable		Cycle helmet: Not a cyclist					

Back seat

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

160122569 30/03/2016 Time 1839 Vehicles 2 Casualties 1 Serious
E:472193 N: 99533 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lighting unknown Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Failed to judge other persons path or speed	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING E ALONG CHERRYWOOD AVENUE TURNED RIGHT ONTO ELM GROVE INTO
PATH OF VEH 2 (M/CYCLE) TRAVELLING N ALONG ELM GROVE.

Occurred on ELM GROVE AT JUNCTION WITH CHERRYWOOD AVENUE, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from W to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 53 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Motor Cycle over 50 cc and up to 125cc Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 31 Male
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 31 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("NS HAYLING ISLAND - PBA")

Notes:

160317668 24/08/2016 Time 0958 Vehicles 2 Casualties 1 Slight
E:470422 N: 99645 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: Pri Drive Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Stationary or parked vehicle	Vehicle 1	Very Likely
2nd:	Stationary or parked vehicle	Vehicle 2	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING W ALONG PARK ROAD SWERVES TO AVOID VEH 2 (CAR) REVERSING OUT OF NUMBER 41 ONTO PARK ROAD. RIDER VEH 1 FALLS FROM VEH.

Occurred on PARK ROAD AT JUNCTION WITH NUMBER 41, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Motorcycle 50cc and under Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Mid Junction - on roundabout or r First impact Did not impact Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 20 Male
Not hit and run Breath test Negative
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 20 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Reversing
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Did not impact Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 63 Male
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

44170050772 08/02/2017 Time 2128 Vehicles 1 Casualties 1 Slight
E:471694 N: 102026 First Road: U Road Type Single carriageway
Speed limit: 40 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: no street lighting Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG WEST LANE AT NIGHT IN COLD CONDITIONS, DRIVER IS
INEXPERIENCED AND NOT DRIVEN THIS ROAD BEFORE TOOK THE SHARP LEFT HAND BEND TOO FAST,
LEAVES THE CARRIAGEWAY TO THE OFFSIDE AND COLLIDES WITH TREES AND OVERTURNS.
Occurred on WEST LANE 328 METRES NORTH OF DAW LANE, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Car Going ahead right bend
Vehicle movement from NE to S No tow / articulation Leaving the main road
On main carriageway Overturned
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: Tree
O/S Age of Driver 20 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 20 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

44170200987 28/05/2017 Time 0805 Vehicles 2 Casualties 1 Slight
E:471442 N: 99470 First Road: A 3023 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Dazzling sun	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING E ALONG STATION ROAD, LOOKS BOTH WAY, FAILS TO SEE AS BLINDED BY
SUN AND TURNS RIGHT ONTO A3023 BEACH ROAD ACROSS THE PATH OF VEH 2 (P/CYCLE) TRAVELLING
N ALONG A3023 BEACH ROAD AND COLLIDES, CAUSING THE RIDER TO FALL OFF.

Occurred on A3023 BEACH ROAD AT JUNCTION WITH STATION ROAD, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from W to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 55 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Pedal Cycle Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 55 Male
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 55 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Yes

Accidents between dates 01/06/2012 and 31/05/2017 (60) months

Selection:

Notes:

Selected using Pre-defined Query : ; Refined using Accidents
within selected Polygons -HC - RPU Statistics Request ("NS
HAYLING ISLAND - PBA")

120284003 20/06/2012 Time 1900 Vehicles 2 Casualties 1 Slight
E:472038 N: 102290 First Road: A 3023 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Distraction outside vehicle	Vehicle 2	Very Likely
2nd:	Failed to judge other persons path or speed	Vehicle 2	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 2 (CAR) TRAVELLING S ALONG A3023 HAVANT ROAD DISTRACTED BY VEH TRAVELLING CLOSELY
BEHIND AND FAILED TO NOTICE VEH 1 (CAR) STOPPED IN FRONT WAITING TO TURN RIGHT INTO WEST
LANE. VEH 2 TO COLLIDED WITH REAR OF VEH 1.

Occurred on A3023 HAVANT ROAD AT JUNCTION WITH WEST LANE, HAYLING ISLAND, HAMPSHIRE

Vehicle Reference 1 Car Waiting to turn right
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 27 Female
Not hit and run Breath test Driver not contacted
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 27 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 40 Male
Not hit and run Breath test Driver not contacted
Left hand drive: No

Accidents between dates **01/06/2012 and 31/05/2017** (60) months

Selection:

Selected using Pre-defined Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("NS HAYLING ISLAND - PBA")

Notes:


Accidents involving:

	Fatal	Serious	Slight	Total
Motor vehicles only (excluding 2-wheels)	0	3	8	11
2-wheeled motor vehicles	0	1	3	4
Pedal cycles	0	1	5	6
Horses & other	0	0	1	1
Total	0	5	17	22

Casualties:

	Fatal	Serious	Slight	Total
Vehicle driver	0	1	7	8
Passenger	0	2	4	6
Motorcycle rider	0	1	3	4
Cyclist	0	1	5	6
Pedestrian	0	1	2	3
Other	0	0	0	0
Total	0	6	21	27

Appendix D



Project Number: 041.0031	Title: ACCESSIBILITY MAP	 Paul Basham Associates Ltd Lancaster Court 8 Barnes Wallis Road Fareham Hampshire PO15 5TU T +44 (0) 1489 668134 E info@paulbashamassociates.com W www.paulbashamassociates.com	Checked By: MS	Checked Date: 10.11.17	Scale: N/A
Project Name: Sinah Lane, Hayling Island			Drawn By: SB	Drawn Date: 10.11.17	Drawing No: N/A