

Introduction

With comments about vehicle usage of the service road and unloading of Lorries and Vans, it is important to clarify the intensity of the use of the service road. The applicant had CCTV available at his adjacent premises and was able to turn the camera to monitor the apron in front of the application site garages.


Data was recorded for **Wednesday 16th May** through to **Sunday 20th May**. This gives a good spread of weekday and a full weekend of traffic movements. The data was monitored between **05:00** to **23:00** every day. Outside of the monitoring period, there was a Yodel van un/loading to one of the applicant's garages, however this should not be an issue as those garages will be removed if this development is granted.

As a service road with no restriction, the public are able to use this road but as it is a short cut to nowhere, it was imagined that there was little through traffic. Nonetheless all passing vehicle movements were noted. In terms of the Lorries and Vans which stopped and made deliveries, records of the size of vehicle and the duration of waiting was recorded.


Results of CCTV Monitoring and presentation of data

Each day was monitored separately and a graph of the results can be seen as a record of the results. *(Please refer to drawing no. 1010, 1011 & 1012)* The number of passing vehicles is also shown as vehicle(s) per hour number.

The data has also been summarised into a Pie chart for average Weekday deliveries and an average for Weekend deliveries. As shown below:



Pie chart showing average weekday deliveries



Pie chart showing average weekend deliveries

Summary of CCTV records from 16/05/18 to 20/05/18 (from 05:00 – 23:00)

16.05.2018 (**Wednesday, 05:00 to 23:00**) at the proposed site

Total vehicular traffic count : **70** times
Total duration of off/loading time by lorry delivery(s) : **26** mins
Total duration of off/loading time other than lorry delivery(s) : **13** mins
Key events: 2x **Refuse vehicles** drove past the site.
1x **Co-op lorry** parked and offloaded at the site.
1x **Transit van** parked and offloaded at the site.

Please refer to **Appendix A for more detail breakdown.*

-

17.05.2018 (**Thursday, 05:00 to 23:00**) at the proposed site

Total vehicular traffic count : **71** times
Total duration of off/loading time by lorry delivery(s) : **35** mins
Total duration of off/loading time other than lorry delivery(s) : **28** mins
Main events: 2x **Transit van** parked and offloaded at the site.
1x **Warburtons lorry** drove past the site.
1x **Co-op lorry** parked and offloaded at the site

Please refer to **Appendix B for more detail breakdown.*

-

18.05.2018 (**Friday, 05:00 to 23:00**) at the proposed site

Total vehicular traffic count : **107** times
Total duration of off/loading time by lorry delivery(s) : **112** mins
Total duration of off/loading time other than lorry delivery(s) : **0** mins
Main events: 1x **Warburtons lorry** parked and loaded at the site.
1x **Kingsmill lorry** parked and offloaded at the site.
1x **Refuse vehicle** drove past the site.
2x **Co-op lorry** parked and offloaded at the site.

Please refer to **Appendix C for more detail breakdown.*

19.05.2018 (**Saturday, 05:00 to 23:00**) at the proposed site

Total vehicular traffic count : **103** times
Total duration of off/loading time by lorry delivery(s) : **15** mins
Total duration of off/loading time other than lorry delivery(s) : **5** mins
Main events: 1x **Transit van** parked and loaded at the site.
1x **Kingsmill lorry** parked and offloaded at the site.
1x **Warburtons lorry** parked and offloaded at the site.



Please refer to **Appendix D for more detail breakdown.*



-


20.05.2018 (**Sunday, 05:00 to 23:00**) at the proposed site

Total vehicular traffic count : **76** times
Total duration of off/loading time by lorry delivery(s) : **98** mins
Total duration of off/loading time other than lorry delivery(s) : **0** mins
Main events: 2x **Co-op lorry** parked and loaded at the site.

Please refer to **Appendix E for more detail breakdown.*







Appendices:

Appendix A:	CCTV footage breakdown for 16.05.2018 (Wednesday)	... p2 -4
Appendix B:	CCTV footage breakdown for 17.05.2018 (Thursday)	... p5 -8
Appendix C:	CCTV footage breakdown for 18.05.2018 (Friday)	... p9 - 11
Appendix D:	CCTV footage breakdown for 19.05.2018 (Saturday)	... p12 - 15
Appendix E:	CCTV footage breakdown for 20.05.2018 (Sunday)	... p16 - 18

Appendix A: CCTV FOOTAGE 16.05.2018 (WEDNESDAY)

05:00-

- 1 vehicle. (Pass by)

06:00-

- 3 vehicles. (Pass by)

07:00-

- 07:38 - **Refuse Vehicle** for general/recycle waste. (Pass by)



- 07:59 – **Refuse vehicle** for garden waste. (Pass by)



08:00-

- 08:01 – **Co-op lorry** delivery. (Arrival)



Offloading...



08:27 – **Co-op lorry** delivery. (Departure)

09:00-

- 3 vehicles. (Pass by)

10:00-

- 4 vehicles. (Pass by)

11:00-

- 11:04 – **Transit van**. (Arrival)



Off/Loading at
Best one's Garage?



11:17 – **Transit van**. (Departure)

- 2 vehicles. (Pass by)

12:00-

- 3 vehicles. (Pass by)

13:00-

- 4 vehicles. (Pass by)

14:00-

- 3 vehicles. (Pass by)

15:00-

- 5 vehicles. (Pass by)

16:00-

- 10 vehicles. (Pass by)

17:00-

- 7 vehicles. (Pass by)

18:00-

- 5 vehicles. (Pass by)

19:00-

- 6 vehicles. (Pass by)

20:00-

- 4 vehicles. (Pass by)

21:00-

- 5 vehicles. (Pass by)

22:00-

- 1 vehicle. (Pass by)

23:00 END

Total count = **70 times**

Appendix B: CCTV FOOTAGE 17.05.2018 (THURSDAY)

05:00-

06:00-

- 2 vehicles. (Pass by)
- 06:44 – **Transit van.** (Arrival)

*Off/Loading at
Best one's Garage?*



06:46 – **Transit van.** (Departure)

07:00-

- 1 vehicle. (Pass by)
- 07:17 – **Warburton Bread Lorry** delivery. (Pass by)
- 07:41 – **Co-op lorry** delivery. (Arrival)
- 07:41 – **Unknown lorry** delivery [Best One]) delivery. (Arrival)

Offloading...



08:00-

08:16 – **Co-op lorry.** (Departure)

08:16 – **Unknown lorry.** (Departure)

- 2 vehicles. (Pass by)

09:00-

- 09:24 – **Unknown lorry** delivery. (Arrival)

Offloading... (Not at proposed site)

10:00-



10:04 – **Unknown lorry**. (Departure)

- 2 vehicles. (Pass by)

11:00-

- 2 vehicles. (Pass by)
- 11:53 – **Transit van**. (Arrival)

12:00-

*Off/Loading at Best One's
garage?*



12:17 – **Transit van**. (Departure)

- 3 vehicles. (Pass by)

13:00-

- 13:02 – **Small truck** for pallets collection. (Arrival)



13:04 – **Small truck.** (Departure)

- 1 vehicle. (Pass by)

14:00-

- 7 vehicles. (Pass by)

15:00-

- 3 vehicles. (Pass by)

16:00-

- 9 vehicles. (Pass by)

17:00-

- 11 vehicles. (Pass by)

18:00-

- 8 vehicles. (Pass by)

19:00-

- 5 vehicles. (Pass by)

20:00-

- 2 vehicles. (Pass by)

21:00-

- 2 vehicles. (Pass by)

22:00-

- 4 vehicles. (Pass by)

23:00 END

Total count = **71 times**

Appendix C: CCTV FOOTAGE 18.05.2018 (FRIDAY)

05:00-

- 1 vehicle. (Pass by)

06:00-

- 2 vehicles. (Pass by)

07:00-

- 3 vehicles. (Pass by)
- 07:46 – **Warburtons lorry** delivery. (Arrival)



07:47 – **Warburtons lorry**. (Departure)

- 1 vehicle. (Pass by)

08:00-

- 1 vehicle. (Pass by)
- 08:15 – **Kingsmill lorry** delivery. (Arrival)



08:19 - **Kingsmill lorry**. (Departure)

- 08:21 – **Refuse vehicle** for general/recycle waste. (Pass by)

09:00-

10:00-

- 4 vehicles. (Pass by)

11:00-

- 2 vehicles. (Pass by)

- 11:25 – **Co-op lorry** delivery. (Arrival)

12:00-

Offloading...



12:02 – **Co-op lorry**. (Departure)

- 6 vehicles. (Pass by)

13:00-

- 13:00 – **Co-op lorry** delivery. (Arrival)

Offloading...



14:00-

14:10 – **Co-op lorry**. (Departure)

- 7 vehicles. (Pass by)

15:00-

- 13 vehicles. (Pass by)

16:00-

- 15 vehicles. (Pass by)

17:00-

- 11 vehicles. (Pass by)

18:00-

- 11 vehicles. (Pass by)

19:00-

- 7 vehicles. (Pass by)

20:00-

- 10 vehicles. (Pass by)

21:00-

- 3 vehicles. (Pass by)

22:00-

- 5 vehicles. (Pass by)

23:00 END

Total count = **107 times**

Appendix D: CCTV FOOTAGE 19.05.2018 (SATURDAY)

05:00-

06:00-

- 1 vehicle. (Pass by)
- 06:24 – **Transit van.** (Arrival)



06:29 – **Transit van.** (Departure)

07:00-

- 2 vehicles. (Pass by)
- 07:36 – **Kingsmill lorry** delivery. (Arrival)



07:47 – **Kingsmill lorry.** (Departure)

- 1 vehicle. (Pass by)

08:00-

- 3 vehicles. (Pass by)
- 08:42 – **Warburtons lorry** delivery. (Arrival)

Offloading



08:46 - **Warburton lorry**. (Departure)

09:00-

- 3 vehicles. (Pass by)

10:00-

- 8 vehicles. (Pass by)

11:00-

- 4 vehicles. (Pass by)

12:00-

- 5 vehicles. (Pass by)

13:00-

- 5 vehicles. (Pass by)
- 13:28 – RedStar Food Service lorry delivery. (Arrival)

Offloading...



13:42 - RedStar Food Service lorry. (Departure)

14:00-

- 5 vehicles. (Pass by)

15:00-

- 15 vehicles. (Pass by)

16:00-

- 11 vehicles. (Pass by)

17:00-

- 6 vehicles. (Pass by)

18:00-

- 1 vehicle. (Pass by)

19:00-

- 10 vehicles. (Pass by)

20:00-

- 7 vehicles. (Pass by)

21:00-

- 6 vehicles. (Pass by)

22:00-

- 6 vehicles. (Pass by)

23:00 END

Total count = **103 times**

Appendix E: CCTV FOOTAGE 20.05.2018 (SUNDAY)

05:00-

- 1 vehicle. (Pass by)

06:00-


- 2 vehicles. (Pass by)

07:00-

- 1 vehicle. (Pass by)
- 07:16 – **Co-op lorry** delivery. (Arrival)

08:00-

Offloading



08:07 – **Co-op lorry**. (Departure)

- 3 vehicles. (Pass by)

09:00-

- 1 vehicle. (Pass by)

10:00-

11:00-

- 5 vehicles. (Pass by)

12:00-

- 6 vehicles. (Pass by)

13:00-

- 3 vehicles. (Pass by)

- 13:55 – **Co-op lorry** delivery. (Arrival)

Offloading

14:00-



14:42 – **Co-op lorry**. (Departure)

15:00-

- 4 vehicles. (Pass by)

16:00-

- 9 vehicles. (Pass by)

17:00-

- 11 vehicles. (Pass by)

18:00-

- 6 vehicles. (Pass by)

19:00-

- 11 vehicles. (Pass by)

20:00-

- 4 vehicles. (Pass by)

21:00-

- 3 vehicles. (Pass by)

22:00-

- 4 vehicles. (Pass by)

23:00 END

=**76**times