



TREE
FROM
BACK DOOR

NBC Development Control

FENCE
BEHIND
TREE



REC-14175
23 AUG 2018
HBC Development Control

FENCE BEHIND
TREE



WASHING LINE AREA
WAS LEVEL WITH
RATIO



PATIO PAVING

REC'D
7 FEB 1971
FBI

PATIO PAVING

23 AUG 2018
IBC Development Centre

PATIO
PAVING

PATIO DOORS
OUTSIDE

RECEIVED

23 AUG 2018

HBC Development Control

OUTSIDE
CONSERVATORY WALL



A photograph of a stone dwarf wall, likely made of granite or similar natural stone. The wall is composed of several large, rectangular blocks. The surface of the stones is weathered and shows some discoloration. The wall is situated outdoors, with dry leaves and some greenery visible in the background. Handwritten text in blue ink is visible on the lower right portion of the wall.

DWARF WALL
AT LEFT SIDE
of TREE

DWARF WALL
IN FRONT OF TREE



OUTSIDE POND
WALL





INSIDE CONSERVATORY

INSIDE CONSERVATORY

RECEIVED
APR 27 1970
Plant Control

WINDOW SILL
INSIDE CONSERVATORY



A photograph showing the interior of a conservatory. On the left is a white vertical frame or door edge. To its right is a large glass pane reflecting the interior. At the top left, a small rectangular object with a string of white beads hangs from it. Handwritten text in blue ink is on the white frame.

INSIDE
CONSERVATORY
LOOKING AT
DOORS TO THE
OUTSIDE


FLOOR AGAINST WALL

CONSERVATORY FLOOR
AGAINST OUTER BRICKWORK

CONSERVATORY
FLOOR



INSIDE
DINING ROOM
DOWN THE
EDGE OF
CONSERVATORY
DOORS



INSIDE DINING ROOM
ABOVE CONSERVATORY
DOORS

17 JUL 2018
HBO Development Control