


44A, Braishfield Road, Havant

Foul Drain Capacity Check

HOUSE No.	Appliance	Units	Total
42	2 WC	14	28
	2 Basin	3	6
	1 Bath	7	7
	1 Shower	4	4
	1 Sink	6	6
	1 Wash Machine	4	4
	1 Dish Wash	4	4
	Sub - Total		59
40	2 WC	14	28
	2 Basin	3	6
	1 Bath	7	7
	1 Shower	4	4
	1 Sink	6	6
	1 Wash Machine	4	4
	1 Dish Wash	4	4
	Sub - Total		59
38	2 WC	14	28
	2 Basin	3	6
	1 Bath	7	7
	1 Shower	4	4
	1 Sink	6	6
	1 Wash Machine	4	4
	1 Dish Wash	4	4
	Sub - Total		59
44A	2 WC	14	28
	2 Basin	3	6
	1 Bath	7	7
	1 Shower	4	4
	1 Sink	6	6
	1 Wash Machine	4	4
	1 Dish Wash	4	4
	Sub - Total		59
TOTAL UNITS			205

**DRAINAGE PIPE SIZING GRAPH**

Capacity with drain falling at 1 in 70 is more than adequate.