



View 3: From BOAT 119/46/1 at the western end of James’s Copse, looking south into the Site’s eastern field. Mature native woodland and hedgerows good screening,even during the winter months, however there are glimpsed views into the site.



View 4: From BOAT 119/46/1 adjacent to the north-eastern corner of the site looking towards the site’s eastern field. Mature native woodland and scrub provide good screening, however there will be a glimpsed view into the site here, with a stretch of hedgerow removed to allow a new vehicular entrance to the Site, with new homes beyond.