

MONITORING RECORD SHEET**Ref:** 20131151**Insured:** Letchford Mr M & Mrs S**Adjuster:** JW**Engineer:** JW**Address:** Nirvana, Woodgaston Lane, Hayling Island, PO11 0RL**LOCATIONS: ACCESS REQ****A: EXTERNAL RIGHT FLANK BTM LEFT CORNER OF SIDE BEDROOM WINDOW****B: EXTERNAL REAR ELEVATION LHS OF DINING ROOM WINDOW / RHS OF RHS BAY****C: INTERNAL FRONT RIGHT BEDROOM BTM LEFT OF SIDE WINDOW****D: INTERNAL FRONT RIGHT BEDROOM HORIZONTAL CRACK TO FRONT CORNER****E: INTERNAL ENTRANCE PORCH SEPARATION TO CAVITY WITHIN DOOR REVEAL/EDGE OF DOOR FRAME****F: INTERNAL DINING ROOM SEPARATION TO CAVITY WITHIN REVEAL OF OPENING**

DATE	A		B	H	B	V	B	DIA	C		D		E		F		
23/04/13	62.57	0.00	67.19	0.00	68.42	0.00	98.50	0.00	69.14	0.00	70.16	0.00	46.66	0.00	52.64	0.00	0.00
17/06/13	62.72	0.15	67.24	0.05	68.44	0.02	98.63	0.13	69.21	0.07	70.14	-0.02	46.34	-0.32	52.72	0.08	
19/08/13	62.70	-0.02	67.28	0.04	68.50	0.06	98.52	-0.11	69.12	-0.09	70.12	-0.02	46.62	0.28	52.74	0.02	
24/10/13	62.76	0.06	67.32	0.04	68.42	-0.08	98.54	0.02	69.52	0.40	70.36	0.24	47.90	1.28	53.16	0.42	
18/12/13	62.72	-0.04	67.36	0.04	68.60	0.18	98.55	0.01	69.28	-0.24	70.23	-0.13	47.24	-0.66	52.97	-0.19	

OVERALL CHANGE:

0.15

0.17

0.18

0.05

0.14

0.07

0.58

0.33

0.00





