

General Image
Detailed Image



Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	


General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	B10 Tank 2 Base
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
Post excavation sample. Fibreglass tank. No evidence of contamination.	
General Observations	


Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/15/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	K8
Detailed Grid Reference:	50.8586834, -0.9713516
Stockpile Number:	
Top of Excavation:	0.0
Base of Excavation:	4.0

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☒ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	

General Image
Detailed Image






Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	K7 Tank 3 Base 3.0m
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
Post excavation sample. Fibreglass tank. No evidence of contamination.	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/11/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	Tank 2
Detailed Grid Reference:	50.8601056, -0.9695636
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	

General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	TANK 2 BASE
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
General Observations	


Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/10/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image
Detailed Image



Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	G4
Detailed Grid Reference:	50.8596048, -0.9720647
Stockpile Number:	

General Image




Detailed Image



Sampling / Comments

Origin Sample Taken:	No
Sample Reference:	
Destination Sample Take	Yes
Sample Reference:	Dt G4 01
Sampling Comments	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/10/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	F3
Detailed Grid Reference:	50.8599054, -0.9723718
Stockpile Number:	

General Image
Detailed Image






Sampling / Comments

Origin Sample Taken:	No
Sample Reference:	
Destination Sample Taken:	Yes
Sample Reference:	Dt F3 01
Sampling Comments	
General Observations	


Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/09/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	F3
Detailed Grid Reference:	50.8598334, -0.9724480
Stockpile Number:	
Top of Excavation:	0.0
Base of Excavation:	2.5

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	

General Image
Detailed Image





Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	Or F3 2.5 Drain
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
Sample collected to represent the material remaining on site.	
General Observations	
Dark stained material added to the quarantine area.	


Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/09/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☒ Stockpile	
Soil Grid Reference:	E5
Detailed Grid Reference:	50.8600258, -0.9711789
Stockpile Number:	Sp03
Top of Excavation:	
Base of Excavation:	

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	


General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	Sp03 E5 15
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
Crush pile sample	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/09/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	C5
Detailed Grid Reference:	50.8603659, -0.9713399
Stockpile Number:	Sp03
Top of Excavation:	
Base of Excavation:	

General Image



Detailed Image

