

General Image
Detailed Image






Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	Or G4 Int1
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
Collected SE corner of excavation.	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/04/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	G5
Detailed Grid Reference:	50.8595261, -0.9717523
Stockpile Number:	
Top of Excavation:	0.0
Base of Excavation:	1.3

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	

General Image
Detailed Image






Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	Or G5 DRAIN 1.3
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
From beneath drainage pipe.	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/03/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	H8
Detailed Grid Reference:	50.8589047, -0.9707890
Stockpile Number:	
Top of Excavation:	+2.0
Base of Excavation:	3.5

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	


General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	Or H8 +1.0
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
Sample collected from arisings mound made while excavating foundations. Represents surface to ~2.5m	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/03/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	H8
Detailed Grid Reference:	50.8588846, -0.9708913
Stockpile Number:	
Top of Excavation:	0.0
Base of Excavation:	4.7

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	


General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	Or H8 4.5
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
General Observations	


Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)


Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/03/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	K8
Detailed Grid Reference:	50.8586567, -0.9712168
Stockpile Number:	
Top of Excavation:	0.0
Base of Excavation:	1.8

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	


General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	Or K8 1.8
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/02/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image
Detailed Image



Destination of Moved Soil

New Soil Location: ☒ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	J11
Detailed Grid Reference:	50.8584986, -0.9702395
Stockpile Number:	

General Image



Detailed Image



Sampling / Comments

Origin Sample Taken:	No
Sample Reference:	
Destination Sample Take	Yes
Sample Reference:	Dt J11 01
Sampling Comments	
General Observations	


Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/02/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image
Detailed Image



Destination of Moved Soil

New Soil Location: ☒ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	G11
Detailed Grid Reference:	50.8589866, -0.9699522
Stockpile Number:	

General Image




Detailed Image



Sampling / Comments

Origin Sample Taken:	No
Sample Reference:	
Destination Sample Taken:	Yes
Sample Reference:	Dt G11 01a
Sampling Comments	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/02/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☒ Stockpile	
Soil Grid Reference:	D5
Detailed Grid Reference:	50.8601322, -0.9712205
Stockpile Number:	Sp03
Top of Excavation:	
Base of Excavation:	

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	

General Image
Detailed Image

