




REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/23/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☒ Stockpile	
Soil Grid Reference:	E5
Detailed Grid Reference:	50.85996, 0.97148
Stockpile Number:	SP03
Top of Excavation:	
Base of Excavation:	

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	

General Image
Detailed Image





Sampling / Comments

Origin Sample Taken:	
Sample Reference:	
Destination Sample Taken:	
Sample Reference:	
Sampling Comments	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/23/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☒ Stockpile	
Soil Grid Reference:	E4
Detailed Grid Reference:	50.85994, 0.97202
Stockpile Number:	SP03
Top of Excavation:	
Base of Excavation:	

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	


General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	
Sample Reference:	
Destination Sample Taken:	
Sample Reference:	
Sampling Comments	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)
Client:	Havant Property LLP
Date:	02/23/2022
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1

Author:	Reviewed:	Authorised:
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image
Detailed Image



Destination of Moved Soil

New Soil Location: ☒ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	G2
Detailed Grid Reference:	50.85983, 0.97278
Stockpile Number:	

General Image



Detailed Image



Sampling / Comments

Origin Sample Taken:	No
Sample Reference:	
Destination Sample Take	Yes
Sample Reference:	DT G2 01
Sampling Comments	
General Observations	


Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/23/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	K6
Detailed Grid Reference:	50.85914, 0.97150
Stockpile Number:	
Top of Excavation:	0.0
Base of Excavation:	1.0

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	


General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	ORH601
Destination Sample Take	
Sample Reference:	
Sampling Comments	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/23/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image
Detailed Image



Destination of Moved Soil

New Soil Location: ☒ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	H5
Detailed Grid Reference:	50.85938, 0.97188
Stockpile Number:	

General Image



Detailed Image





Sampling / Comments

Origin Sample Taken:	No
Sample Reference:	
Destination Sample Taken:	Yes
Sample Reference:	DTH501
Sampling Comments	
General Observations	


Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/23/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image
Detailed Image



Destination of Moved Soil

New Soil Location: ☒ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	H3
Detailed Grid Reference:	50.85963, 0.97241
Stockpile Number:	

General Image



Detailed Image





Sampling / Comments

Origin Sample Taken:	No
Sample Reference:	
Destination Sample Take	Yes
Sample Reference:	DTH301
Sampling Comments	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/17/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image
Detailed Image





Destination of Moved Soil

New Soil Location: ☒ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	H2
Detailed Grid Reference:	50.8595204, -0.9728778
Stockpile Number:	

General Image



Detailed Image






Sampling / Comments

Origin Sample Taken:	No
Sample Reference:	
Destination Sample Take	Yes
Sample Reference:	Dt H2 01
Sampling Comments	
Sample collected of material below car park tarmac. (Original material, not demo crush).	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/17/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director