




## Sampling / Comments

|                                |            |
|--------------------------------|------------|
| <b>Origin Sample Taken:</b>    | Yes        |
| <b>Sample Reference:</b>       | Sp03 D5 13 |
| <b>Destination Sample Take</b> | No         |
| <b>Sample Reference:</b>       |            |
| Sampling Comments              |            |
|                                |            |
| General Observations           |            |
|                                |            |

## Additional Images





## REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

|                             |                                                                    |                                                                                                                           |
|-----------------------------|--------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|
| <b>Project Reference:</b>   | UK21.5634                                                          |                                                                                                                           |
| <b>Title:</b>               | Remedial Oversight & Material Tracking<br>(Pfizer, Havant)         |                                                                                                                           |
| <b>Client:</b>              | Havant Property LLP                                                |                                                                                                                           |
| <b>Date:</b>                | 02/02/2022                                                         |                                                                                                                           |
| <b>EPS Contact Details:</b> | 7B Caxton House<br>Broad Street<br>Cambourne<br>Cambridge CB23 6JN | <b>T:</b> 01954 710666<br><b>F:</b> 01954 710677<br><b>E:</b> info@epstrategies.co.uk<br><b>W:</b> www.epstrategies.co.uk |
| <b>Status:</b>              | Issue 1                                                            |                                                                                                                           |

| <b>Author:</b>                                                                       | <b>Reviewed:</b>   | <b>Authorised:</b> |
|--------------------------------------------------------------------------------------|--------------------|--------------------|
|  |                    |                    |
| Paul O'Connor                                                                        | Marcus Bell        | Will Evans         |
| Consultant                                                                           | Associate Director | Director           |

## Excavation of Soil

|                                                                                                                        |                        |
|------------------------------------------------------------------------------------------------------------------------|------------------------|
| <b>Soil Location:</b><br><br><input type="checkbox"/> Soil Excavation<br><input checked="" type="checkbox"/> Stockpile |                        |
| <b>Soil Grid Reference:</b>                                                                                            | E5                     |
| <b>Detailed Grid Reference:</b>                                                                                        | 50.8600072, -0.9713218 |
| <b>Stockpile Number:</b>                                                                                               | Sp03                   |
| <b>Top of Excavation:</b>                                                                                              |                        |
| <b>Base of Excavation:</b>                                                                                             |                        |

General Image



Detailed Image





## Destination of Moved Soil

|                                                                                                                            |  |
|----------------------------------------------------------------------------------------------------------------------------|--|
| <b>New Soil Location:</b><br><br><input type="checkbox"/> Backfilled into Excavation<br><input type="checkbox"/> Stockpile |  |
| <b>Soil Grid Reference:</b>                                                                                                |  |
| <b>Detailed Grid Reference:</b>                                                                                            |  |
| <b>Stockpile Number:</b>                                                                                                   |  |


| General Image                                                                       |
|-------------------------------------------------------------------------------------|
|    |
| Detailed Image                                                                      |
|  |



## Sampling / Comments

|                                |          |
|--------------------------------|----------|
| <b>Origin Sample Taken:</b>    | Yes      |
| <b>Sample Reference:</b>       | Or E5 14 |
| <b>Destination Sample Take</b> | No       |
| <b>Sample Reference:</b>       |          |
| Sampling Comments              |          |
|                                |          |
| General Observations           |          |
|                                |          |

## Additional Images





## REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

|                             |                                                                    |                                                                                                                           |
|-----------------------------|--------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|
| <b>Project Reference:</b>   | UK21.5634                                                          |                                                                                                                           |
| <b>Title:</b>               | Remedial Oversight & Material Tracking<br>(Pfizer, Havant)         |                                                                                                                           |
| <b>Client:</b>              | Havant Property LLP                                                |                                                                                                                           |
| <b>Date:</b>                | 02/02/2022                                                         |                                                                                                                           |
| <b>EPS Contact Details:</b> | 7B Caxton House<br>Broad Street<br>Cambourne<br>Cambridge CB23 6JN | <b>T:</b> 01954 710666<br><b>F:</b> 01954 710677<br><b>E:</b> info@epstrategies.co.uk<br><b>W:</b> www.epstrategies.co.uk |
| <b>Status:</b>              | Issue 1                                                            |                                                                                                                           |

| <b>Author:</b>                                                                       | <b>Reviewed:</b>   | <b>Authorised:</b> |
|--------------------------------------------------------------------------------------|--------------------|--------------------|
|  |                    |                    |
| Paul O'Connor                                                                        | Marcus Bell        | Will Evans         |
| Consultant                                                                           | Associate Director | Director           |

## Excavation of Soil

|                                                                                                                        |                        |
|------------------------------------------------------------------------------------------------------------------------|------------------------|
| <b>Soil Location:</b><br><br><input checked="" type="checkbox"/> Soil Excavation<br><input type="checkbox"/> Stockpile |                        |
| <b>Soil Grid Reference:</b>                                                                                            | J10                    |
| <b>Detailed Grid Reference:</b>                                                                                        | 50.8586521, -0.9705097 |
| <b>Stockpile Number:</b>                                                                                               |                        |
| <b>Top of Excavation:</b>                                                                                              | 0.0                    |
| <b>Base of Excavation:</b>                                                                                             | 2.2                    |

General Image



Detailed Image





## Destination of Moved Soil

|                                                                                                                            |  |
|----------------------------------------------------------------------------------------------------------------------------|--|
| <b>New Soil Location:</b><br><br><input type="checkbox"/> Backfilled into Excavation<br><input type="checkbox"/> Stockpile |  |
| <b>Soil Grid Reference:</b>                                                                                                |  |
| <b>Detailed Grid Reference:</b>                                                                                            |  |
| <b>Stockpile Number:</b>                                                                                                   |  |

| General Image                                                                       |
|-------------------------------------------------------------------------------------|
|    |
| Detailed Image                                                                      |
|  |



## Sampling / Comments

|                                |            |
|--------------------------------|------------|
| <b>Origin Sample Taken:</b>    | Yes        |
| <b>Sample Reference:</b>       | Or J10 2.0 |
| <b>Destination Sample Take</b> |            |
| <b>Sample Reference:</b>       |            |
| Sampling Comments              |            |
|                                |            |
| General Observations           |            |
|                                |            |

## Additional Images





## REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)


|                             |                                                                    |                                                                                                                           |
|-----------------------------|--------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|
| <b>Project Reference:</b>   | UK21.5634                                                          |                                                                                                                           |
| <b>Title:</b>               | Remedial Oversight & Material Tracking<br>(Pfizer, Havant)         |                                                                                                                           |
| <b>Client:</b>              | Havant Property LLP                                                |                                                                                                                           |
| <b>Date:</b>                | 02/02/2022                                                         |                                                                                                                           |
| <b>EPS Contact Details:</b> | 7B Caxton House<br>Broad Street<br>Cambourne<br>Cambridge CB23 6JN | <b>T:</b> 01954 710666<br><b>F:</b> 01954 710677<br><b>E:</b> info@epstrategies.co.uk<br><b>W:</b> www.epstrategies.co.uk |
| <b>Status:</b>              | Issue 1                                                            |                                                                                                                           |

| <b>Author:</b>                                                                       | <b>Reviewed:</b>   | <b>Authorised:</b> |
|--------------------------------------------------------------------------------------|--------------------|--------------------|
|  |                    |                    |
| Paul O'Connor                                                                        | Marcus Bell        | Will Evans         |
| Consultant                                                                           | Associate Director | Director           |

## Excavation of Soil

|                                                                                                                        |                        |
|------------------------------------------------------------------------------------------------------------------------|------------------------|
| <b>Soil Location:</b><br><br><input type="checkbox"/> Soil Excavation<br><input checked="" type="checkbox"/> Stockpile |                        |
| <b>Soil Grid Reference:</b>                                                                                            | J5                     |
| <b>Detailed Grid Reference:</b>                                                                                        | 50.8592294, -0.9720577 |
| <b>Stockpile Number:</b>                                                                                               | Sp04                   |
| <b>Top of Excavation:</b>                                                                                              |                        |
| <b>Base of Excavation:</b>                                                                                             |                        |

General Image



Detailed Image





## Destination of Moved Soil

|                                                                                                                            |  |
|----------------------------------------------------------------------------------------------------------------------------|--|
| <b>New Soil Location:</b><br><br><input type="checkbox"/> Backfilled into Excavation<br><input type="checkbox"/> Stockpile |  |
| <b>Soil Grid Reference:</b>                                                                                                |  |
| <b>Detailed Grid Reference:</b>                                                                                            |  |
| <b>Stockpile Number:</b>                                                                                                   |  |


| General Image                                                                       |
|-------------------------------------------------------------------------------------|
|    |
| Detailed Image                                                                      |
|  |



## Sampling / Comments

|                                |            |
|--------------------------------|------------|
| <b>Origin Sample Taken:</b>    | Yes        |
| <b>Sample Reference:</b>       | Sp04 J5 02 |
| <b>Destination Sample Take</b> | No         |
| <b>Sample Reference:</b>       |            |
| Sampling Comments              |            |
|                                |            |
| General Observations           |            |
|                                |            |


## Additional Images





## REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

|                             |                                                                    |                                                                                                                           |
|-----------------------------|--------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|
| <b>Project Reference:</b>   | UK21.5634                                                          |                                                                                                                           |
| <b>Title:</b>               | Remedial Oversight & Material Tracking<br>(Pfizer, Havant)         |                                                                                                                           |
| <b>Client:</b>              | Havant Property LLP                                                |                                                                                                                           |
| <b>Date:</b>                | 02/02/2022                                                         |                                                                                                                           |
| <b>EPS Contact Details:</b> | 7B Caxton House<br>Broad Street<br>Cambourne<br>Cambridge CB23 6JN | <b>T:</b> 01954 710666<br><b>F:</b> 01954 710677<br><b>E:</b> info@epstrategies.co.uk<br><b>W:</b> www.epstrategies.co.uk |
| <b>Status:</b>              | Issue 1                                                            |                                                                                                                           |

| <b>Author:</b>                                                                       | <b>Reviewed:</b>   | <b>Authorised:</b> |
|--------------------------------------------------------------------------------------|--------------------|--------------------|
|  |                    |                    |
| Paul O'Connor                                                                        | Marcus Bell        | Will Evans         |
| Consultant                                                                           | Associate Director | Director           |

## Excavation of Soil

|                                                                                                                        |                        |
|------------------------------------------------------------------------------------------------------------------------|------------------------|
| <b>Soil Location:</b><br><br><input checked="" type="checkbox"/> Soil Excavation<br><input type="checkbox"/> Stockpile |                        |
| <b>Soil Grid Reference:</b>                                                                                            | H10                    |
| <b>Detailed Grid Reference:</b>                                                                                        | 50.8588154, -0.9703414 |
| <b>Stockpile Number:</b>                                                                                               |                        |
| <b>Top of Excavation:</b>                                                                                              | +2                     |
| <b>Base of Excavation:</b>                                                                                             | -2                     |

General Image



Detailed Image





## Destination of Moved Soil

|                                                                                                                            |  |
|----------------------------------------------------------------------------------------------------------------------------|--|
| <b>New Soil Location:</b><br><br><input type="checkbox"/> Backfilled into Excavation<br><input type="checkbox"/> Stockpile |  |
| <b>Soil Grid Reference:</b>                                                                                                |  |
| <b>Detailed Grid Reference:</b>                                                                                            |  |
| <b>Stockpile Number:</b>                                                                                                   |  |


| General Image                                                                       |
|-------------------------------------------------------------------------------------|
|    |
| Detailed Image                                                                      |
|  |



## Sampling / Comments

|                                |             |
|--------------------------------|-------------|
| <b>Origin Sample Taken:</b>    | Yes         |
| <b>Sample Reference:</b>       | Or H10 +1.5 |
| <b>Destination Sample Take</b> | No          |
| <b>Sample Reference:</b>       |             |
| Sampling Comments              |             |
|                                |             |
| General Observations           |             |
|                                |             |

## Additional Images





## REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

|                             |                                                                    |                                                                                                                           |
|-----------------------------|--------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|
| <b>Project Reference:</b>   | UK21.5634                                                          |                                                                                                                           |
| <b>Title:</b>               | Remedial Oversight & Material Tracking<br>(Pfizer, Havant)         |                                                                                                                           |
| <b>Client:</b>              | Havant Property LLP                                                |                                                                                                                           |
| <b>Date:</b>                | 01/31/2022                                                         |                                                                                                                           |
| <b>EPS Contact Details:</b> | 7B Caxton House<br>Broad Street<br>Cambourne<br>Cambridge CB23 6JN | <b>T:</b> 01954 710666<br><b>F:</b> 01954 710677<br><b>E:</b> info@epstrategies.co.uk<br><b>W:</b> www.epstrategies.co.uk |
| <b>Status:</b>              | Issue 1                                                            |                                                                                                                           |

| <b>Author:</b>                                                                       | <b>Reviewed:</b>   | <b>Authorised:</b> |
|--------------------------------------------------------------------------------------|--------------------|--------------------|
|  |                    |                    |
| Paul O'Connor                                                                        | Marcus Bell        | Will Evans         |
| Consultant                                                                           | Associate Director | Director           |

## Excavation of Soil

|                                                                                                                        |                        |
|------------------------------------------------------------------------------------------------------------------------|------------------------|
| <b>Soil Location:</b><br><br><input type="checkbox"/> Soil Excavation<br><input checked="" type="checkbox"/> Stockpile |                        |
| <b>Soil Grid Reference:</b>                                                                                            | K5                     |
| <b>Detailed Grid Reference:</b>                                                                                        | 50.8588294, -0.9720792 |
| <b>Stockpile Number:</b>                                                                                               | SP Macadam             |
| <b>Top of Excavation:</b>                                                                                              | +1                     |
| <b>Base of Excavation:</b>                                                                                             | +1                     |

General Image



Detailed Image





## Destination of Moved Soil

|                                                                                                                            |  |
|----------------------------------------------------------------------------------------------------------------------------|--|
| <b>New Soil Location:</b><br><br><input type="checkbox"/> Backfilled into Excavation<br><input type="checkbox"/> Stockpile |  |
| <b>Soil Grid Reference:</b>                                                                                                |  |
| <b>Detailed Grid Reference:</b>                                                                                            |  |
| <b>Stockpile Number:</b>                                                                                                   |  |


| General Image                                                                       |
|-------------------------------------------------------------------------------------|
|    |
| Detailed Image                                                                      |
|  |



## Sampling / Comments

|                                |             |
|--------------------------------|-------------|
| <b>Origin Sample Taken:</b>    | Yes         |
| <b>Sample Reference:</b>       | Sp Mac West |
| <b>Destination Sample Take</b> | No          |
| <b>Sample Reference:</b>       |             |
| Sampling Comments              |             |
|                                |             |
| General Observations           |             |
|                                |             |


## Additional Images





## REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

|                             |                                                                    |                                                                                                                           |
|-----------------------------|--------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|
| <b>Project Reference:</b>   | UK21.5634                                                          |                                                                                                                           |
| <b>Title:</b>               | Remedial Oversight & Material Tracking<br>(Pfizer, Havant)         |                                                                                                                           |
| <b>Client:</b>              | Havant Property LLP                                                |                                                                                                                           |
| <b>Date:</b>                | 01/31/2022                                                         |                                                                                                                           |
| <b>EPS Contact Details:</b> | 7B Caxton House<br>Broad Street<br>Cambourne<br>Cambridge CB23 6JN | <b>T:</b> 01954 710666<br><b>F:</b> 01954 710677<br><b>E:</b> info@epstrategies.co.uk<br><b>W:</b> www.epstrategies.co.uk |
| <b>Status:</b>              | Issue 1                                                            |                                                                                                                           |

| <b>Author:</b>                                                                       | <b>Reviewed:</b>   | <b>Authorised:</b> |
|--------------------------------------------------------------------------------------|--------------------|--------------------|
|  |                    |                    |
| Paul O'Connor                                                                        | Marcus Bell        | Will Evans         |
| Consultant                                                                           | Associate Director | Director           |

## Excavation of Soil

|                                                                                                                        |                        |
|------------------------------------------------------------------------------------------------------------------------|------------------------|
| <b>Soil Location:</b><br><br><input type="checkbox"/> Soil Excavation<br><input checked="" type="checkbox"/> Stockpile |                        |
| <b>Soil Grid Reference:</b>                                                                                            | K5                     |
| <b>Detailed Grid Reference:</b>                                                                                        | 50.8588385, -0.9718659 |
| <b>Stockpile Number:</b>                                                                                               | SP Macadam             |
| <b>Top of Excavation:</b>                                                                                              | +1                     |
| <b>Base of Excavation:</b>                                                                                             | +1                     |

General Image



Detailed Image





## Destination of Moved Soil

|                                                                                                                            |  |
|----------------------------------------------------------------------------------------------------------------------------|--|
| <b>New Soil Location:</b><br><br><input type="checkbox"/> Backfilled into Excavation<br><input type="checkbox"/> Stockpile |  |
| <b>Soil Grid Reference:</b>                                                                                                |  |
| <b>Detailed Grid Reference:</b>                                                                                            |  |
| <b>Stockpile Number:</b>                                                                                                   |  |

| General Image                                                                       |
|-------------------------------------------------------------------------------------|
|    |
| Detailed Image                                                                      |
|  |






## Sampling / Comments

|                                |             |
|--------------------------------|-------------|
| <b>Origin Sample Taken:</b>    | Yes         |
| <b>Sample Reference:</b>       | Sp Mac East |
| <b>Destination Sample Take</b> | No          |
| <b>Sample Reference:</b>       |             |
| Sampling Comments              |             |
|                                |             |
| General Observations           |             |
|                                |             |


## Additional Images





## REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

|                             |                                                                    |                                                                                                                           |
|-----------------------------|--------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------|
| <b>Project Reference:</b>   | UK21.5634                                                          |                                                                                                                           |
| <b>Title:</b>               | Remedial Oversight & Material Tracking<br>(Pfizer, Havant)         |                                                                                                                           |
| <b>Client:</b>              | Havant Property LLP                                                |                                                                                                                           |
| <b>Date:</b>                | 01/21/2022                                                         |                                                                                                                           |
| <b>EPS Contact Details:</b> | 7B Caxton House<br>Broad Street<br>Cambourne<br>Cambridge CB23 6JN | <b>T:</b> 01954 710666<br><b>F:</b> 01954 710677<br><b>E:</b> info@epstrategies.co.uk<br><b>W:</b> www.epstrategies.co.uk |
| <b>Status:</b>              | Issue 1                                                            |                                                                                                                           |

| <b>Author:</b>                                                                       | <b>Reviewed:</b>   | <b>Authorised:</b> |
|--------------------------------------------------------------------------------------|--------------------|--------------------|
|  |                    |                    |
| Paul O'Connor                                                                        | Marcus Bell        | Will Evans         |
| Consultant                                                                           | Associate Director | Director           |

## Excavation of Soil

|                                                                                                                        |                        |
|------------------------------------------------------------------------------------------------------------------------|------------------------|
| <b>Soil Location:</b><br><br><input type="checkbox"/> Soil Excavation<br><input checked="" type="checkbox"/> Stockpile |                        |
| <b>Soil Grid Reference:</b>                                                                                            | C5                     |
| <b>Detailed Grid Reference:</b>                                                                                        | 50.8602829, -0.9709965 |
| <b>Stockpile Number:</b>                                                                                               | SP03                   |
| <b>Top of Excavation:</b>                                                                                              |                        |
| <b>Base of Excavation:</b>                                                                                             |                        |

General Image



Detailed Image





## Destination of Moved Soil

|                                                                                                                            |  |
|----------------------------------------------------------------------------------------------------------------------------|--|
| <b>New Soil Location:</b><br><br><input type="checkbox"/> Backfilled into Excavation<br><input type="checkbox"/> Stockpile |  |
| <b>Soil Grid Reference:</b>                                                                                                |  |
| <b>Detailed Grid Reference:</b>                                                                                            |  |
| <b>Stockpile Number:</b>                                                                                                   |  |

| General Image                                                                       |
|-------------------------------------------------------------------------------------|
|    |
| Detailed Image                                                                      |
|  |





## Sampling / Comments

|                                |            |
|--------------------------------|------------|
| <b>Origin Sample Taken:</b>    | Yes        |
| <b>Sample Reference:</b>       | Sp03 C5 12 |
| <b>Destination Sample Take</b> |            |
| <b>Sample Reference:</b>       |            |
| Sampling Comments              |            |
|                                |            |
| General Observations           |            |
|                                |            |