

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	01/21/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image
Detailed Image





Destination of Moved Soil

New Soil Location: ☒ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	J13
Detailed Grid Reference:	50.8584726, -0.9695994
Stockpile Number:	

General Image




Detailed Image



Sampling / Comments

Origin Sample Taken:	No
Sample Reference:	
Destination Sample Take	Yes
Sample Reference:	Dt J13 01
Sampling Comments	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	01/21/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	J11
Detailed Grid Reference:	50.8587073, -0.9701449
Stockpile Number:	
Top of Excavation:	0.0
Base of Excavation:	1.4

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	

General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	Or J11 SF
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
Sample collected from surface representing soils from around foundation excavation ~1.5m d	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	01/21/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☒ Stockpile	
Soil Grid Reference:	H4
Detailed Grid Reference:	50.8592903, -0.9721422
Stockpile Number:	SP04
Top of Excavation:	
Base of Excavation:	

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	


General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	SP04 H4 SF
Destination Sample Taken:	No
Sample Reference:	
Sampling Comments	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	01/21/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	F3
Detailed Grid Reference:	50.8598709, -0.9721217
Stockpile Number:	
Top of Excavation:	0.0
Base of Excavation:	1.6

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	

General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	Or F3 1.5
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
Distinct layer of made ground possibly top of natural layer	
General Observations	

Additional Images

