

22, The Kench – Re-instated locker

Re-instated Locker

A locker has been re-instated on the east side of the property. I have no photos of the original locker, but the following photos show where it was and its size.




Photo 1: Aerial view from Google Earth. The locker is the black area by the side windows. Unfortunately, there is no 3D street view in the Kench, but this view shows the original locker location and size.



Photo 2: East evaluation. The unpainted area beneath the window shows the extent of the original locker in terms of height and length.



Photo 3: East evaluation. The concrete pad shows the footprint of the old locker. The new plastic cladding between the left and middle windows shows the extent of the old locker.



Photo 4: new locker looking north. Its height sits just below the window level.



Photo 5: New locker looking west shortly after completion. The new locker is the same height and roughly the same dimensions as the original but positioned further south to enable the steps to the slip to be safely fenced off with protective fencing.



Photo 6: New locker looking south shortly after completion. The new locker is the same height and roughly the same dimensions as the original but positioned slightly further south to enable the steps to the slip to be safely fenced off with protective fencing.

[Lockers within the Kench](#)

Many of the bungalows within the Kench have waist-level storage lockers attached.