

Excavation of Soil

Soil Location: ☐ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image
Detailed Image

Destination of Moved Soil

New Soil Location: ☒ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	K3
Detailed Grid Reference:	50.8591517, -0.9729210
Stockpile Number:	

General Image



Detailed Image






Sampling / Comments

Origin Sample Taken:	No
Sample Reference:	
Destination Sample Take	Yes
Sample Reference:	
Sampling Comments	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/17/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	K6
Detailed Grid Reference:	50.8587761, -0.9718994
Stockpile Number:	
Top of Excavation:	0.0
Base of Excavation:	2.0

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	


General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	Or K6 01
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/16/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image
Detailed Image



Destination of Moved Soil

New Soil Location: ☒ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	H8
Detailed Grid Reference:	50.8590891, -0.9709556
Stockpile Number:	

General Image




Detailed Image



Sampling / Comments

Origin Sample Taken:	No
Sample Reference:	
Destination Sample Take	Yes
Sample Reference:	Dt H8 01
Sampling Comments	
General Observations	

Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/16/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☒ Stockpile	
Soil Grid Reference:	F4
Detailed Grid Reference:	50.8597669, -0.9721234
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	


General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	Sp03 F4 17
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
General Observations	


Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/16/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☐ Soil Excavation ☒ Stockpile	
Soil Grid Reference:	E5
Detailed Grid Reference:	50.8599305, -0.9713821
Stockpile Number:	Sp03
Top of Excavation:	
Base of Excavation:	

General Image



Detailed Image



Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	

General Image
Detailed Image






Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	Sp03 E5 18
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
General Observations	


Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/16/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image
Detailed Image



Destination of Moved Soil

New Soil Location: ☒ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	J9
Detailed Grid Reference:	50.8587615, -0.9707246
Stockpile Number:	

General Image



Detailed Image






Sampling / Comments

Origin Sample Taken:	No
Sample Reference:	
Destination Sample Take	Yes
Sample Reference:	Dt J9 01
Sampling Comments	
General Observations	


Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/16/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	F5
Detailed Grid Reference:	50.8596961, -0.9716420
Stockpile Number:	
Top of Excavation:	
Base of Excavation:	

General Image



Detailed Image





Destination of Moved Soil

New Soil Location: ☐ Backfilled into Excavation ☐ Stockpile	
Soil Grid Reference:	
Detailed Grid Reference:	
Stockpile Number:	


General Image
Detailed Image



Sampling / Comments

Origin Sample Taken:	Yes
Sample Reference:	Or F5 01
Destination Sample Take	No
Sample Reference:	
Sampling Comments	
General Observations	


Additional Images





REMEDIAL OVERSIGHT & MATERIAL TRACKING (PFIZER, HAVANT)

Project Reference:	UK21.5634	
Title:	Remedial Oversight & Material Tracking (Pfizer, Havant)	
Client:	Havant Property LLP	
Date:	02/11/2022	
EPS Contact Details:	7B Caxton House Broad Street Cambourne Cambridge CB23 6JN	T: 01954 710666 F: 01954 710677 E: info@epstrategies.co.uk W: www.epstrategies.co.uk
Status:	Issue 1	

Author:	Reviewed:	Authorised:
		
Paul O'Connor	Marcus Bell	Will Evans
Consultant	Associate Director	Director

Excavation of Soil

Soil Location: ☒ Soil Excavation ☐ Stockpile	
Soil Grid Reference:	B10
Detailed Grid Reference:	50.8601104, -0.9695844
Stockpile Number:	
Top of Excavation:	0.0
Base of Excavation:	3.0