

22, The Kench - Steps

Pier / Steps

The sea wall to the north and east of the property is extremely exposed to the sea, weather, and other random entities. On both sides the wall was in a very poor state of repair. It has been strengthened and as part of the process a pier / steps from the property to the beach has been installed. It serve two purposes, 1) provide a pier for the sea wall to provide extra strength, 2) provide step access to the beach as per other bungalows in the adjacent area.



Photo 1: Showing pier / steps to the beach looking west.



Photo 2 Showing pier / steps to beach looking east.



Photo 3 Sea wall and pier/steps looking east on a high tide.