

ROOT IDENTIFICATION

for Subsidence Management Services

10 Linda Grove, Waterlooville, Hampshire, PO8 8UX

Client: Subsidence Management Services
Client Contact: Jose Lopez
Claim Number: 13EQ602273
Client Reference: IFS-AVI-ROF-13-0044763
Policy Holder: Mrs Lynda Emmott
Report Date: 29 August 2014
Our Ref: R6513



Intec
Parc Menai, Bangor,
Gwynedd, North Wales
LL57 4FG
Tel: 01248 672652

Sub Sample	Species Identified		Root Diameter	Starch
TP/BH1:				
0.6-1.6m	<i>Quercus</i> spp.		1.5 mm	Absent
0.6-1.6m	<i>Hebe</i> spp. shrub species, probably		1 mm	Absent
0.6-1.6m	broadleaved species, too decayed for positive identification	1	1 mm	Absent

Comments:

1 - Plus other smaller decayed roots.

Quercus spp. are oaks (both deciduous and evergreen).

Hebe spp. are common flowering evergreen shrubs.

All roots were dead and in a state of decay.

Signed: M D Mitchell

Unless we are otherwise instructed in writing, the above sample material will normally be disposed of 6 years after the date of this report.