
From: Stephen Downton
Sent: 12 October 2021 16:26
To: Nicholas Jenkins
Subject: RE: Discharge of Condition 11 of APP/20/00276 Willowdene Garages, Havant

Hello Nick

I can confirm that all foul drainage is taken to rear of back plot into existing foul drainage.

Surface water drainage is into existing surface water manhole at rear of front plot and existing system in willowdene road.

No foundations were dug to front plot as all off existing foot print

Rear plot has extensions over foul drainage, however 600mm deep, 100mm pipework and no more than 6m built over

No combined systems in place.

Kind regards

Stephen Downton
BSc (Hons) HND MRICS
Senior Building Control Surveyor
T: 0175 327 16 60
M: 07432674798

Stephen.downton@stroma.com



A co-ordinated approach to building sustainability and compliance

Stroma Building Control | Stroma Certification | Stroma Software |
Stroma Tech | BBS Environmental | HRS Services

27, Sheet Street, Windsor, Berkshire, SL4 1BN

0345 621 11 16 | stroma.com/building-control

Stroma Building Control Ltd | Place of Registration: England and Wales
Registered Office: 4 Pioneer Way, Castleford, WF10 5QU | Reg No: 04161657



From: Nick Jenkins <nicholas@jenkinsarchitecture.co.uk>
Sent: 12 October 2021 11:49
To: Stephen Downton <stephen.downton@stroma.com>
Subject: FW: Discharge of Condition 11 of APP/20/00276 Willowdene Garages, Havant

Call you soon