

APPENDIX C

Photographic Log



Walkover Photographs

Project Ref: 15.8909

Site Name: Station Road, Hayling Island

1.



2.



1) View of the site from the east

2) Inside the carpet and flooring and shop

3) Storage building to the north of the shop

4) External area north of the shop

3.



4.



constructiveevaluation
site investigation • building pathology

Walkover Photographs

Project Ref: 15.8909

Site Name: Station Road, Hayling Island

5.



6.



5) External area north of the shop – note waste materials

6) External area north of the shop – note waste materials

7) Possible ACMs in the external storage area of the site

8) External area north of the shop – note waste materials

7.



8.



Walkover Photographs

Project Ref: 15.8909

Site Name: Station Road, Hayling Island

9.



10.



- 9) Vacant residential properties in the western part of the site
- 10) Launderette south of the site