




30 degree roof with half round ridge and bonnet hip tiles

Phalempin - Volcano (Imery Tiles)

Black plastic half round gutters and down pipes

Kassandra Multi (Wienerberger) brick laid stretcher bond

Timber porch with a dark oak stain

Level threshold

Painted timber casement windows

Buff coloured reconstituted stone subcills

The drawing shows two adjacent houses, Plot 1 and Plot 2, with their respective ground lines and elevations. Plot 1 is on the left and Plot 2 is on the right. The ground line is indicated by a dashed red line with numerical values at various points. The elevations are as follows:

Point	Elevation
Plot 1 Left Corner	50.67
Plot 1 Window	50.74
Plot 1 Porch	51.02
Plot 1 Right Corner	51.02
Plot 1 Right Window	51.15
Plot 1 Right Corner	51.23
Plot 2 Left Corner	51.42
Plot 2 Window	51.38
Plot 2 Porch	51.41
Plot 2 Right Corner	51.56
Plot 2 Right Window	51.45
Plot 2 Right Corner	51.73

The existing ground line is shown as a dashed red line. The elevations are: 50.67, 50.74, 51.02, 51.02, 51.15, 51.23, 51.42, 51.38, 51.41, 51.56, 51.45, 51.73.

00.00 - Existing levels

N199	PL03	A
------	------	---