

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

Selected Polygon: NS HORNDEAN ROAD EMSWORTH

090331488 30/07/2009 Time 1830 Vehicles 2 Casualties 1 Slight
E:473756 N: 108067 First Road: B 2148 Road Type Single carriageway
Speed limit: 60 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight: street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to judge other persons path or speed	Vehicle 1	Very Likely
2nd:	Failed to look properly	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEHICLE 2 (CAR) TRAVELLING SOUTH ON B2148 HORNDEAN ROAD. VEHICLE 1 (CAR) ON EMSWORTH COMMON ROAD INTENDING TO TURN RIGHT ONTO B2148 HORNDEAN ROAD AND HEAD NORTH. VEH 1 FAILED TO SEE VEH 2 AND PULLED OUT INTO THE PATH OF VEH 2. VEH 2 HAD NO TIME TO ST
Occurred on B2148 HORNDEAN ROAD AT THE JUNCTION WITH EMSWORTH COMMON ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from E to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Offside Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 54 Male
Not hit and run Breath test Negative
Left hand drive:

Vehicle Reference 2 Car Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 25 Female
Not hit and run Breath test Negative
Left hand drive:

Casualty Reference: 1 Vehicle: 2 Age: 25 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

090438086 07/10/2009 Time 2005 Vehicles 2 Casualties 1 Slight
E:472797 N: 106576 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Disobeyed Give Way or Stop sign or markings	Vehicle 2	Possible
2nd:	Careless/Reckless/In a hurry	Vehicle 2	Possible
3rd:	Stationary or parked vehicle	Vehicle 2	
4th:			
5th:			
6th:			

VEH 2 (CAR) TRAVELLING WEST ALONG GLENLEIGH PARK TURNED RIGHT ONTO SOUTHLEIGH ROAD
FROM BETWEEN GAP IN SOUTHBOUND TRAFFIC COLLIDING WITH VEH 1 (CAR) TRAVELLING NORTHEAST
ALONG SOUTHLEIGH ROAD.

Occurred on SOUTHLEIGH ROAD AT JUNCTION WITH GLENLEIGH PARK, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or 1 First impact Offside Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 17 Male
Not hit and run Breath test Driver not contacted
Left hand drive:
Casualty Reference: 1 Vehicle: 1 Age: 17 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Vehicle Reference 2 Car Turning right
Vehicle movement from E to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or 1 First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver Male
Not hit and run Breath test Driver not contacted
Left hand drive:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

090482970 06/11/2009 Time 1840 Vehicles 2 Casualties 1 Slight
E:473368 N: 107369 First Road: U Road Type 1
Speed limit: 40 Junction Detail: Mini roundabout Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Raining with high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Slippery road (due to weather)	Vehicle 1	Possible
2nd:	Junction overshoot	Vehicle 1	Possible
3rd:	Failed to judge other persons path or speed	Vehicle 1	
4th:			
5th:			
6th:			

VEHICLE 1 (PEDAL CYCLE) TRAVELLING SOUTHWEST ALONG EASTLEIGH ROAD, ENTERS MINI RBT
INTENDING TO CONTINUE AHEAD ONTO SOUTHLEIGH ROAD. VEHICLE 2 (CAR) TRAVELLING
NORTHWEST ALONG SOUTHLEIGH ROAD PULLS ONTO RBT INTENDING TO TAKE 1ST EXIT (LEFT) ONTO
SOUT

Occurred on SOUTHLEIGH ROAD AT JUNCTION WITH EASTLEIGH ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Pedal Cycle Going ahead right bend
Vehicle movement from NE to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Nearside Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 59 Female
Not hit and run Breath test Driver not contacted
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 59 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Vehicle Reference 2 Car Turning left
Vehicle movement from SE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Entering roundabout First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver Male
Not hit and run Breath test Driver not contacted
Left hand drive:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within selected Polygons -HC - RPU Statistics Request ("NS HORNDEAN ROAD EMSWORTH")

090528495 08/12/2009 Time 2115 Vehicles 2 Casualties 2 Serious
E:474912 N: 105901 First Road: A 259 Road Type 1
Speed limit: 30 Junction Detail: Roundabout Give way or controlled B 2148
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Raining without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Disobeyed Give Way or Stop sign or markings	Vehicle 1	Possible
2nd:	Failed to look properly	Vehicle 1	Possible
3rd:	Cyclist wearing dark clothing at night	Vehicle 2	Possible
4th:	Inexperienced or learner driver/rider	Vehicle 1	Possible
5th:			
6th:			

VEH 1 (CAR), HEADING EAST ALONG HAVANT ROAD, ENTERED THE ROUNDABOUT AT NORTH STREET AND WAS STRUCK ON THE OFFSIDE BY VEH 2 (PEDAL CYCLE) WHICH WAS APPROACHING FROM THE RIGHT.

Occurred on HAVANT ROAD AT THE JUNCTION WITH NORTH STREET, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Entering roundabout First impact Offside Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 18 Male
Not hit and run Breath test Negative
Left hand drive:
Casualty Reference: 1 Vehicle: 1 Age: 18 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Vehicle Reference 2 Pedal Cycle Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 33 Female
Not hit and run Breath test Not applicable
Left hand drive:
Casualty Reference: 2 Vehicle: 2 Age: 33 Female Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

100002512 02/01/2010 Time 1615 Vehicles 2 Casualties 1 Slight
E:474931 N: 105882 First Road: A 259 Road Type 1
Speed limit: 30 Junction Detail: Roundabout Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Other
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Travelling too fast for conditions	Vehicle 1	Possible
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG NORTH STREET STATIONARY ON RBT WITH A259 HAVANT ROAD
INTENDING TO EXIT ONTO HIGH STREET BUT TEMPORARILY BLOCKED. VEH 2 (CAR) ENTERS RBT FROM
A259 HAVANT ROAD AND COLLIDES INTO REAR FO VEH 1 THEN FAILED TO STOP.

Occurred on A259 HAVANT ROAD AT JUNCTION WITH HIGH STREET, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Car Going ahead but held up
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Back Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 43 Female
Not hit and run Breath test Driver not contacted
Left hand drive:

Vehicle Reference 2 Car Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 43 Female
Hit and run Breath test Driver not contacted
Left hand drive:

Casualty Reference: 1 Vehicle: 2 Age: 43 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEN ROAD EMSWORTH")

100032488 25/01/2010 Time 1745 Vehicles 2 Casualties 1 Slight
E:474931 N: 105910 First Road: A 259 Road Type Single carriageway
Speed limit: 30 Junction Detail: Roundabout Give way or controlled B 2148
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Following too close	Vehicle 1	Very Likely
2nd:	Failed to look properly	Vehicle 1	Very Likely
3rd:	Failed to judge other persons path or speed	Vehicle 1	Very Likely
4th:	Careless/Reckless/In a hurry	Vehicle 1	Very Likely
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG B2148 NORTH STREET WAITING TO JOIN RBT, MOVES FORWARD
THINKING VEH 2 (CAR) IN FRONT WOULD HAVE MOVED AND COLLIDES INTO REAR OF VEH 2.
Occurred on A259 HAVANT ROAD AT JUNCTION WITH B2148 NORTH STREET, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Car Starting
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 55 Female
Not hit and run Breath test Negative
Left hand drive:

Vehicle Reference 2 Car Starting
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Back Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 58 Female
Not hit and run Breath test Negative
Left hand drive:

Casualty Reference: 1 Vehicle: 2 Age: 58 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

100034652 27/01/2010 Time 0847 Vehicles 2 Casualties 1 Slight
E:473747 N: 108077 First Road: B 2148 Road Type Single carriageway
Speed limit: 60 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: Central reservation Road surface Dry
Daylight:street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SW ALONG EMSWORTH COMMON ROAD TURNS RIGHT ONTO B2148
HORNDEAN ROAD FAILING TO GIVE WAY TO VEH 2 (CAR) TRAVELLING N ALONG B2148 AND COLLIDES
SENDING VEH 2 INTO A SPIN HITTING ROADSIDE FURNITURE ON CENTRAL REFUGE.

Occurred on B2148 HORNDEAN ROAD AT JUNCTION WITH EMSWORTH COMMON ROAD, HAVANT,
HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from NE to NW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Cleared junction or waiting/parke First impact Front Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 51 Male
Not hit and run Breath test Negative
Left hand drive:

Vehicle Reference 2 Car Going ahead other
Vehicle movement from SE to NW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Offside Hit vehicle:
Hit object in road Bollard / Refuge Off road: Lamp post
Did not leave carr Age of Driver 34 Female
Not hit and run Breath test Negative
Left hand drive:

Casualty Reference: 1 Vehicle: 2 Age: 35 Female Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:
Front seat

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

100041651 01/02/2010 Time 0700 Vehicles 2 Casualties 1 Slight
E:473734 N: 108107 First Road: B 2148 Road Type Single carriageway
Speed limit: 40 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Frost/Ice
Darkness: no street lighting Snowing without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Slippery road (due to weather)	Vehicle 1	Very Likely
2nd:	Junction overshoot	Vehicle 1	Very Likely
3rd:	Loss of control	Vehicle 1	
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING E ALONG BARTONS ROAD LOSES CONTROL DUE TO ICY ROAD CAUSING IT TO
OVERSHOOT THE JUNCTION INTO THE PATH OF VEH 2 (P/CYCLE) TRAVELLING N ALONG B2148
HORNDEAN ROAD AND THEY COLLIDE.

Occurred on B2148 HORNDEAN ROAD AT JUNCTION WITH BARTONS ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from W to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Offside Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 63 Male
Not hit and run Breath test Negative
Left hand drive:

Vehicle Reference 2 Pedal Cycle Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 66 Male
Not hit and run Breath test Not requested
Left hand drive:

Casualty Reference: 1 Vehicle: 2 Age: 66 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEN ROAD EMSWORTH")

100041703 01/02/2010 Time 0845 Vehicles 1 Casualties 1 Slight
E:474883 N: 106431 First Road: B 2148 Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Snow
Daylight:street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Slippery road (due to weather)	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING N ALONG B2148 NEW BRIGHTON ROAD SKIDDED DUE TO BAD ROAD
CONDITIONS AND RIDER FELL OFF.

Occurred on B2148 NEW BRIGHTON ROAD OUTSIDE NUMBER 15, HAVANT, HAMPSHIRE

Vehicle Reference 1 Motorcycle 50cc and under Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Did not impact Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 16 Male
Not hit and run Breath test Not requested
Left hand drive:
Casualty Reference: 1 Vehicle: 1 Age: 16 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

100059954 12/02/2010 Time 1955 Vehicles 2 Casualties 1 Slight
E:473756 N: 108068 First Road: B 2148 Road Type Single carriageway
Speed limit: 60 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SW ALONG EMSWORTH ROAD TURNS RIGHT ONTO B2148 HORNDEAN ROAD INTO THE PATH OF VEH 2 (CAR) TRAVELLING SE ALONG B2148 HORNDEAN ROAD AND THEY COLLIDE.

Occurred on B2148 HORNDEAN ROAD AT JUNCTION WITH EMSWORTH COMMON ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from NE to NW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Offside Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 40 Female
Not hit and run Breath test Negative
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 40 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Vehicle Reference 2 Car Going ahead other
Vehicle movement from NW to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 45 Male
Not hit and run Breath test Negative
Left hand drive:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

100094841 08/03/2010 Time 1130 Vehicles 1 Casualties 1 Slight
E:474912 N: 106018 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight:street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 1	Very Likely
2nd:	Vehicle travelling along pavement	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

CAS 1 (PEDESTRIAN) TRAVELLING NW ALONG WESTSIDE PAVEMENT OF NORTH STREET WHEN IS
STRUCK BY VEH 1 (CAR) REVERSING SE ALONG NORTH STREET.

Occurred on NORTH STREET OUTSIDE NUMBER 26, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Reversing
Vehicle movement from NW to SE No tow / articulation Leaving the main road
9 No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 40 Male
Not hit and run Breath test Driver not contacted
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 79 Female Pedestrian Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:
On footpath / verge N bound
Movement U/K

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

100211064 24/05/2010 Time 0814 Vehicles 2 Casualties 1 Slight
E:472670 N: 106109 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Automatic traffic signal Unclassified
Crossing: Control None Facilities: Pelican, puffin, toucan etc. Road surface Dry
Daylight:street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to judge other persons path or speed	Vehicle 2	Very Likely
2nd:	Stationary or parked vehicle	Vehicle 2	Very Likely
3rd:	Failed to look properly	Vehicle 2	Very Likely
4th:	Stationary or parked vehicle	Vehicle 1	Very Likely
5th:			
6th:			

VEH 1 (CAR) TRAVELLING W ALONG GREEN POND CORNER IN LANE 1 COLLIDES WITH VEH 2 (CAR)
TRAVELLING IN OPPOSITE DIRECTION AND TURNED RIGHT INTO POOK LANE ACROSS PATH OF VEH 1.
VEH 2 HAD BEEN FLASHED BY AN UNKNOWN VEH IN LANE 2 NEXT TO VEH 1.

Occurred on GREEN POND CORNER AT JUNCTION WITH POOK LANE, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Front Hit vehicle: 2
Hit object in road None Off road: Road sign / ATS
Nearside Age of Driver 35 Male
Not hit and run Breath test Negative
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 35 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Vehicle Reference 2 Car Turning right
Vehicle movement from W to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Front Hit vehicle: 1
Hit object in road None Off road: None
O/S Age of Driver 68 Male
Not hit and run Breath test Negative
Left hand drive:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

100375106 03/09/2010 Time 1620 Vehicles 1 Casualties 1 Serious
E:472830 N: 106752 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight:street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Casualty 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING S ALONG SOUTHLEIGH ROAD, STRUCK CAS 1 (PEDESTRIAN) WHO
CROSSED FROM THE OFFSIDE BEWTEEN STATIONARY NORTHBOUND TRAFFIC.

Occurred on SOUTHLEIGH ROAD OUTSIDE NUMBER 62, HAVANT, HAMPSHIRE

Vehicle Reference 1 Motorcycle over 500cc Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 53 Male
Not hit and run Breath test Negative
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 11 Male Pedestrian Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet:
In carr elsewhere E bound
Driver's offside masked

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

100381478 08/09/2010 Time 0845 Vehicles 2 Casualties 1 Slight
E:474935 N: 105988 First Road: B 2148 Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight: street lighting unknown Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Exceeding speed limit	Vehicle 2	Possible
2nd:	Failed to look properly	Vehicle 2	Possible
3rd:	Sudden braking	Vehicle 1	
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG NORTH STREET AND SLOWS DUE TO HEAVY TRAFFIC. VEH 2 (CAR)
TRAVELLING BEHIND VEH 1 FAILS TO SLOW IN TIME AND COLLIDES INTO REAR.

Occurred on B2148 NORTH STREET OUTSIDE NUMBER 17, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Car Going ahead but held up
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 35 Female
Not hit and run Breath test Driver not contacted
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 9 Male Passenger Severity: Slight
School pupil to/from school
Seatbelt Not Applicable Cycle helmet:

Front seat

Vehicle Reference 2 Car Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver Female
Not hit and run Breath test Driver not contacted
Left hand drive:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEN ROAD EMSWORTH")

100410536 26/09/2010 Time 2030 Vehicles 2 Casualties 1 Slight
E:472767 N: 106430 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Aggressive driving	Vehicle 1	Very Likely
2nd:	Vehicle in course of crime	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 2 (POLICE CAR) TRAVELLING W ALONG ST GEORGES AVENUE, ATTEMPTS TO STOP VEH 1 (CAR).
VEH 1 STOPS THEN REVERSES INTO FRONT OF VEH 2 THEN DRIVES OFF.

Occurred on ST GEORGES AVENUE OUTSIDE NUMBER 5, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Car Reversing
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver Not traced
Hit and run Breath test Driver not contacted
Left hand drive:

Vehicle Reference 2 Car Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 46 Male
Not hit and run Breath test Not applicable
Left hand drive:

Casualty Reference: 1 Vehicle: 2 Age: 46 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

100480492 12/11/2010 Time 1730 Vehicles 2 Casualties 1 Serious
E:472937 N: 107066 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Other
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Poor turn or manoeuvre	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING NE ALONG NUTWICK ROAD APPROACHES JUNCTION WITH SOUTHLEIGH ROAD
AND TURNS RIGHT ACROSS PATH OF VEH 2 (P/CYCLE) TRAVELLING NE ALONG SOUTHLEIGH ROAD.
Occurred on NUTWICK ROAD AT JUNCTION WITH SOUTHLEIGH ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Starting
Vehicle movement from NW to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Entering main road First impact Offside Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 37 Female
Not hit and run Breath test Negative
Left hand drive:

Vehicle Reference 2 Pedal Cycle Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
Cycle lane (on main carriageway) No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 43 Male
Not hit and run Breath test Not requested
Left hand drive:

Casualty Reference: 1 Vehicle: 2 Age: 43 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEN ROAD EMSWORTH")

100486149 16/11/2010 Time 1200 Vehicles 1 Casualties 1 Slight
E:474931 N: 105856 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight:street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Vehicle travelling along pavement	Vehicle 1	Very Likely
2nd:	Poor turn or manoeuvre	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (GOOD VEH) PARKED IN LAYBY FACING S, PULLS OFF AND PERFORMS A U-TURN. THE REAR OF
VEH 1 GOES OVER THE PAVEMENT AND COLLIDES INTO CAS 1 (PEDESTRIAN) WALKING S ALONG
PAVEMENT KNOCKING OVER INTO A BUSH.

Occurred on HIGH STREET OUTSIDE NUMBER 2, HAVANT, HAMPSHIRE

Vehicle Reference 1 Goods 7.5 tonnes mgw and over U-turn
Vehicle movement from N to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver Male
Not hit and run Breath test Driver not contacted
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 89 Female Pedestrian Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:
On footpath / verge S bound
Movement U/K

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

100514017 07/12/2010 Time 0741 Vehicles 2 Casualties 1 Slight
E:474431 N: 107090 First Road: B 2148 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Fatigue	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) WAS TRAVELLING NW ALONG HORNDEAN ROAD WHEN THE DRIVER FELL ASLEEP. VEH 1
VEERED TOWARDS THE OPPOSITE SIDE OF THE ROAD AND COLLIDED HEAD-ON WITH VEH 2 (CAR)
WHICH WAS TRAVELLING SE.

Occurred on B2148 HORNDEAN ROAD AT JUNCTION WITH WOODLANDS AVENUE, EMSWORTH,
HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from SE to NW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Front Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 57 Male
Not hit and run Breath test Not applicable
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 57 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Vehicle Reference 2 Car Going ahead other
Vehicle movement from NW to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 33 Female
Not hit and run Breath test Not applicable
Left hand drive:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

110169115 23/04/2011 Time 1807 Vehicles 2 Casualties 1 Slight
E:472743 N: 106475 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight:street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Nervous/Uncertain/Panic	Vehicle 1	Very Likely
2nd:	Careless/Reckless/In a hurry	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING N ALONG SOUTHLEIGH ROAD BUT WAITING IN QUEUE OF TRAFFIC AT LEVEL CROSSING, PANICKED WHEN BARRIER RAISED UP AND REVERSED INTO FRONT OF VEH 2 (CAR) WAITING BEHIND.

Occurred on SOUTHLEIGH ROAD 40 METRES NORTH OF ST GEORGES AVENUE, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Reversing
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 34 Male
Not hit and run Breath test Driver not contacted
Left hand drive:

Vehicle Reference 2 Car Going ahead but held up
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 67 Male
Not hit and run Breath test Negative
Left hand drive:

Casualty Reference: 1 Vehicle: 2 Age: 48 Female Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:
Front seat

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

110228473 02/06/2011 Time 1115 Vehicles 1 Casualties 1 Slight
E:474881 N: 106386 First Road: B 3148 Road Type Single carriageway
Speed limit: 30 Junction Detail: Other Give way or controlled B 2147
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight:street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Possible
2nd:	Careless/Reckless/In a hurry	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (SKIP LOADER) TRAVELLING N ALONG B3148 NORTH STREET, DRIVES UNDER A27 HAVANT
BY-PASS RAILWAY BRIDGE, FAILING TO RETRACT HYDRAULIC RAM ARMS, CAUSING VEH 1 TO BECOME
WEDGED UNDER BRIDGE

Occurred on B2148 NORTH STREET AT JUNCTION WITH B2147 NEW BRIGHTON ROAD, EMSWORTH,
HAMPSHIRE

Vehicle Reference 1 Goods 7.5 tonnes mgw and over Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road Bridge Roof Off road: None
Did not leave carr Age of Driver 39 Male
Not hit and run Breath test Negative
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 39 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

110293509 02/07/2011 Time 1055 Vehicles 2 Casualties 1 Slight
E:474882 N: 106051 First Road: B 2148 Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight:street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Possible
2nd:	Poor turn or manoeuvre	Vehicle 2	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (VAN) PARKED AND UNATTENDED ALONG NORTH STREET, CAS 1 (PEDESTRIAN) MAKING A
DELIVERY RETURNS TO VEH 1 AS VEH 2 (CAR) TRAVELLING NW ALONG NORTH STREET PASSES
COLLIDING WITH OFFSIDE OF VEH 1 AND CAS 1 THEN FAILS TO STOP.

Occurred on B2148 NORTH STREET OUTSIDE SPENCERS RESTAURANT, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Van or Goods 3.5 tonnes mgw and under Parked
Vehicle movement from Park to Parked No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 45 Female
Not hit and run Breath test Driver not contacted
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 45 Female Pedestrian Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

In carr not crossing NW bound

Movement U/K

Vehicle Reference 2 Car Overtaking stat vehicle O/S
Vehicle movement from SE to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Nearside Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 46 Female
Not hit and run Breath test Driver not contacted
Left hand drive:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

110285972 08/07/2011 Time 2118 Vehicles 1 Casualties 1 Fatal
E:473156 N: 107260 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Illness or disability, mental or physical	Vehicle 1	Very Likely
2nd:	Impaired by alcohol	Vehicle 1	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SE ALONG ROWAN ROAD, FAILS TO STOP AT JUNCTION WITH SOUTHLEIGH ROAD PROCEEDS OVER GIVE WAY LINE AND LEAVES ROAD STRAIGHT AHEAD COLLIDING WITH A GARDEN WALL.

Occurred on SOUTHLEIGH ROAD AT JUNCTION WITH ROWAN ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from NW to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: Oth perm objects
Straight ahead at Jun Age of Driver 36 Female
Not hit and run Breath test Not applicable
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 36 Female Driver/rider Severity: Fatal
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

110396508 17/09/2011 Time 1523 Vehicles 1 Casualties 1 Serious
E:474913 N: 106020 First Road: B 2148 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: Zebra crossing Road surface Dry
Daylight:street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to judge vehicles path or speed	Casualty 1	Very Likely
2nd:	Careless/Reckless/In a hurry	Casualty 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

CAS 1 (PEDESTRIAN) TRAVELLING W ACROSS B2148 NORTH STREET RUNS ACROSS PATH OF VEH 1 (CAR)
TRAVELLING N ALONG B2148 NORTH STREET. VEH 1 COLLIDES WITH CAS 1 THEN LEAVES ROAD TO
OFFSIDE COMING TO REST AGAINST LAMPPOST.

Occurred on B2148 NORTH STREET AT JUNCTION WITH PALMERS ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: Lamp post
O/S Age of Driver 18 Male
Not hit and run Breath test Negative
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 18 Male Pedestrian Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet:
Within 50m ped crossing W bound
Driver's offside

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

110435953 13/10/2011 Time 1909 Vehicles 2 Casualties 1 Slight
E:474931 N: 105905 First Road: A 259 Road Type 1
Speed limit: 30 Junction Detail: Roundabout Give way or controlled B 2148
Crossing: Control None Facilities: Footbridge or subway Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Very Likely
2nd:	Failed to judge other persons path or speed	Vehicle 2	Very Likely
3rd:	Inexperienced or learner driver/rider	Vehicle 2	Possible
4th:	Sudden braking	Vehicle 1	Possible
5th:			
6th:			

VEH 2 (M/CYCLE) TRAVELLING S ALONG B2148 NORTH STREET ENTERS RBT FAILING TO GIVE WAY TO
VEH 1 (CAR) TRAVELLING W ALONG A259 HAVANT ROAD ON RBT AND COLLIDES CAUSING RIDER TO
FALL OFF.

Occurred on A259 HAVANT ROAD AT JUNCTION WITH B2148 NORTH STREET, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Back Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 41 Male
Not hit and run Breath test Negative
Left hand drive:

Vehicle Reference 2 Motorcycle 50cc and under Starting
Vehicle movement from NW to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Entering roundabout First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 18 Male
Not hit and run Breath test Negative
Left hand drive:

Casualty Reference: 1 Vehicle: 2 Age: 18 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

110479576 12/11/2011 Time 1210 Vehicles 2 Casualties 1 Serious
E:473735 N: 108108 First Road: B 2148 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight:street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:	Disobeyed Give Way or Stop sign or markings	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING E ALONG BARTONS ROAD FAILED TO GIVE WAY AND TURNED RIGHT ONTO
B2148 HORNDEAN ROAD INTO PATH OF VEH 2 (M/CYCLE) TRAVELLING N ALONG B2148 HORNDEAN ROAD
CAUSING COLLISION.

Occurred on B2148 HORNDEAN ROAD AT JUNCTION WITH BARTONS ROAD, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from W to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Offside Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 35 Male
Not hit and run Breath test Negative
Left hand drive:

Vehicle Reference 2 Motorcycle over 500cc Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 53 Male
Not hit and run Breath test Negative
Left hand drive:

Casualty Reference: 1 Vehicle: 2 Age: 53 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

120041468 29/01/2012 Time 1813 Vehicles 2 Casualties 1 Slight
E:474933 N: 105888 First Road: A 259 Road Type 1
Speed limit: 30 Junction Detail: Roundabout Give way or controlled B 2148
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING W ALONG A259 HAVANT ROAD ENTERED THE RBT AT B2148 NORTH STREET
AND COLLIDED WITH THE NEAR SIDE OF VEH 2 (P/CYCLE) CROSSING THE RBT TRAVELLING S.

Occurred on A259 HAVANT ROAD AT JUNCTION WITH B2148 NORTH STREET, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Entering roundabout First impact Front Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 48 Male
Not hit and run Breath test Negative
Left hand drive:

Vehicle Reference 2 Pedal Cycle Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Nearside Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 48 Male
Not hit and run Breath test Not applicable
Left hand drive:

Casualty Reference: 1 Vehicle: 2 Age: 48 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

120043938 31/01/2012 Time 1231 Vehicles 1 Casualties 1 Slight
E:472687 N: 106119 First Road: U Road Type 2
Speed limit: 30 Junction Detail: T & Stag Jct Automatic traffic signal Unclassified
Crossing: Control Other authorised pe Facilities: Ped. phase at traffic signal junction Road surface Dry
Daylight:street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH (TAXI) REVERSES FROM A PARKING BAY IN W DIRECTION ON SOUTHLEIGH ROAD, FAILS TO LOOK
PROPERLY AND COLLIDES WITH CAS 1 (PEDESTRIAN) TRAVELLING SW ACROSS SOUTHLEIGH ROAD.
Occurred on SOUTHLEIGH ROAD AT JUNCTION WITH EMSWORTH ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Taxi/Private hire car Reversing
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 40 Female
Not hit and run Breath test Driver not contacted
Left hand drive:

Casualty Reference: 1 Vehicle: 1 Age: 66 Female Pedestrian Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:
In carr elsewhere SW bound
Driver's offside

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

120097608 10/03/2012 Time 1000 Vehicles 2 Casualties 1 Slight
E:472939 N: 107066 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (VAN) TRAVELLING SE ALONG NUTWICK ROAD TURNED RIGHT INTO SOUTHLEIGH ROAD INTO
THE PATH OF VEH 2 (P/CYCLE) TRAVELLING NE CAUSING VEH 2 TO COLLIDE WITH THE OFFSIDE OF VEH
1.

Occurred on SOUTHLEIGH ROAD AT JUNCTION WITH NUTWICK ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Van or Goods 3.5 tonnes mgw and under Turning right
Vehicle movement from NW to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Entering main road First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 45 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Pedal Cycle Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 47 Male
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 47 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not known

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

120178965 10/05/2012 Time 0935 Vehicles 2 Casualties 1 Slight
E:473747 N: 108067 First Road: B 2148 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Daylight Raining without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SW ALONG EMSWORTH COMMON ROAD TURNED RIGHT ONTO B2148
HORNDEAN ROAD FAILING TO SEE VEH 2 (M/CYCLE) TRAVELLING N ALONG B2148 HORNDEAN ROAD
BEHIND A VAN. VEH 1 COLLIDED WITH VEH 2 KNOCKING RIDER OFF.

Occurred on B2148 HORNDEAN ROAD AT JUNCTION WITH EMSWORTH COMMON ROAD, HAVANT,
HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from NE to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 63 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Motorcycle over 500cc Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 40 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 40 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

120195897 22/05/2012 Time 1124 Vehicles 2 Casualties 2 Slight
E:473735 N: 108107 First Road: B 2148 Road Type Single carriageway
Speed limit: 60 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: Central reservation Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Junction restart	Vehicle 2	Very Likely
2nd:	Failed to judge other persons path or speed	Vehicle 2	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) WAS TRAVELLING N ALONG B2148 HORNDEAN ROAD. VEH 2 (CAR) TRAVELLING E ALONG BARTONS ROAD TURNED INTO HORNDEAN ROAD INTO THE PATH OF VEH 1. VEH 1 COLLIDED WITH THE OFFSIDE OF VEH 2.

Occurred on B2148 HORNDEAN ROAD AT JUNCTION WITH BARTONS ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 42 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 42 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Turning right
Vehicle movement from W to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Entering main road First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 82 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 2 Vehicle: 2 Age: 82 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

120279801 20/07/2012 Time 1550 Vehicles 2 Casualties 1 Slight
E:473876 N: 107272 First Road: U Road Type Single carriageway
Speed limit: 60 Junction Detail: Pri Drive Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to judge other persons path or speed	Vehicle 2	Possible
2nd:	Failed to look properly	Vehicle 2	Possible
3rd:			
4th:			
5th:			
6th:			

VEH 2 (VAN) TRAVELLING N OUT OF SOUTHLEIGH FARMHOUSE TURNS RIGHT ONTO SOUTHLEIGH ROAD
COLLIDING WITH VEH 1 (P/CYCLE) TRAVELLING W ALONG SOUTHLEIGH ROAD.

Occurred on SOUTHLEIGH ROAD AT JUNCTION WITH SOUTHLEIGH FARMHOUSE, HAVANT, HAMPSHIRE

Vehicle Reference 1 Pedal Cycle Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 40 Male
Not hit and run Breath test Driver not contacted
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 40 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not known

Vehicle Reference 2 Van or Goods 3.5 tonnes mgw and under Turning right
Vehicle movement from S to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver Male
Not hit and run Breath test Driver not contacted
Left hand drive: No

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

120289020 26/07/2012 Time 1800 Vehicles 2 Casualties 1 Slight
E:473735 N: 108110 First Road: B 2148 Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 1	Very Likely
2nd:	Road layout (eg bend, hill crest)	Vehicle 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING E ALONG BARTONS ROAD TURNED RIGHT ONTO B2148 HORNDEAN ROAD
FAILING TO SEE VEH 2 (CAR) TRAVELLING N ALONG B2148 HORNDEAN ROAD CAUSING COLLISION.
Occurred on B2148 HORNDEAN ROAD AT JUNCTION WITH BARTONS ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from W to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 76 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 76 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 41 Male
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

120304517 06/08/2012 Time 1210 Vehicles 2 Casualties 1 Slight
E:472617 N: 106119 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control Other authorised pe Facilities: Pelican, puffin, toucan etc. Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Impaired by drugs (illicit or medicinal)	Vehicle 2	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 2 (CAR) TRAVELLING W ALONG EMSWORTH ROAD CROSSED CENTRE WHITE LINE FOR UNKNOWN
REASON AND COLLIDED WITH ONCOMING VEH 1 (CAR).

Occurred on EMSWORTH ROAD 27 METRES WEST OF SOUTHLEIGH ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Stopping
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 47 Male
Not hit and run Breath test Negative
Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 47 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 76 Male
Not hit and run Breath test Negative
Left hand drive: No

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

120306951 09/08/2012 Time 1630 Vehicles 2 Casualties 1 Slight
E:474874 N: 106184 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 2 (CAR) TRAVELLING S ALONG NORTH STREET OVERTAKES VEH 1 (P/CYCLE) TRAVELLING IN FRONT
HOWEVER COLLIDES WITH VEH 1 KNOCKING RIDER OFF.

Occurred on NORTH STREET OUTSIDE 81TO 83 SEAGULL COURT, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Pedal Cycle Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 22 Male
Not hit and run Breath test Not applicable Left hand drive: No
Casualty Reference: 1 Vehicle: 1 Age: 22 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not known

Vehicle Reference 2 Car Overtaking moving vehicle O/S
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver Not traced
Hit and run Breath test Driver not contacted Left hand drive: No

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEN ROAD EMSWORTH")

120329597 22/08/2012 Time 1940 Vehicles 1 Casualties 1 Serious
E:472994 N: 107107 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Loss of control	Vehicle 1	Possible
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING NE ALONG SOUTHLEIGH ROAD ACCELERATED AFTER TURNING OUT OF
JUNCTION AND LOST CONTROL CAUSING VEH TO LEAVE ROAD TO NEARSIDE AND COLLIDE WITH TREE.
Occurred on SOUTHLEIGH ROAD AT JUNCTION WITH MARLBOROUGH PARK, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Cleared junction or waiting/parked First impact Front Hit vehicle:
Hit object in road None Off road: Tree
Nearside Age of Driver 23 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 23 Female Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

120330122 23/08/2012 Time 0845 Vehicles 2 Casualties 1 Slight
E:472664 N: 106112 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Automatic traffic signal Unclassified
Crossing: Control None Facilities: Ped. phase at traffic signal junction Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Disobeyed automatic traffic signal	Vehicle 2	Possible
2nd:	Failed to judge other persons path or speed	Vehicle 2	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 2 (TAXI) TRAVELLING S ALONG SOUTHLEIGH ROAD ENTERED EMSWORTH ROAD IN ORDER TO
CROSS IT AND ENTER POOK LANE, COLLIDING WITH VEH 1 (CAR) TRAVELLING E ALONG EMSWORTH
ROAD THROUGH A GREEN LIGHT.

Occurred on EMSWORTH ROAD AT JUNCTION WITH SOUTHLEIGH ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 39 Female
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 39 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Taxi/Private hire car Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 36 Male
Not hit and run Breath test Not requested
Left hand drive: No

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

Notes:

120398957 12/10/2012 Time 0705 Vehicles 3 Casualties 2 Serious
E:473423 N: 107405 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Following too close	Vehicle 1	Possible
2nd:	Failed to look properly	Vehicle 1	Very Likely
3rd:	Careless/Reckless/In a hurry	Vehicle 1	
4th:			
5th:			
6th:			

VEH 1 (M/CYCLE) TRAVELLING NE ALONG EASTLEIGH ROAD BEGAN TO OVERTAKE VEH 3 (VAN)
TRAVELLING IN FRONT AND COLLIDED WITH ONCOMING VEH 2 (TAXI) TRAVELLING SW ALONG
EASTLEIGH ROAD CAUSING VEH 1 TO LEAVE THE ROAD TO THE NEAR SIDE.

Occurred on EASTLEIGH ROAD AT JUNCTION WITH WOODLEIGH CLOSE, HAVANT, HAMPSHIRE

Vehicle Reference 1 Motorcycle over 500cc Overtaking moving vehicle O/S
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Near side Age of Driver 49 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 49 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Taxi/Private hire car Going ahead other
Vehicle movement from NE to SW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 65 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 2 Vehicle: 2 Age: 65 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEN ROAD EMSWORTH")

Vehicle Reference 3 Van or Goods 3.5 tonnes mgw and under Going ahead other
Vehicle movement from SW to NE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Did not impact Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 63 Male
Not hit and run Breath test Negative
Left hand drive: No

120451778 19/11/2012 Time 1846 Vehicles 1 Casualties 1 Slight
E:474877 N: 106118 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Casualty 1	Very Likely
2nd:	Impaired by alcohol	Casualty 1	Very Likely
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG NORTH ROAD APPROACHED JUNCTION WITH PALMERS ROAD THEN
COLLIDED ON ITS OFFSIDE WITH CAS 1 (PEDESTRIAN) THAT HAD RAN ACROSS THE ROAD.
Occurred on NORTH STREET AT JUNCTION WITH PALERS ROAD, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 43 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 34 Male Pedestrian Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

In carr elsewhere E bound
Driver's offside

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

130009754 08/01/2013 Time 0715 Vehicles 3 Casualties 1 Slight
E:473802 N: 107971 First Road: B 2148 Road Type Single carriageway
Speed limit: 60 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Wet/Damp
Darkness: no street lighting Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Vehicle blind spot	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING SE ALONG THE B2148 HORNDEAD ROAD THEN COLLIDED ON ITS FRONT WITH
VEH 2 (CAR) TRAVELLING NW ALONG THE SAME ROAD, VEH 3 (VAN) THEN COLLIDED WITH SPINNING
VEH 1, VEH 1 THEN LEFT THE CARRIAGEWAY TO THE NEAR SIDE INTO A DITCH.

Occurred on B2148 HORNDEAN ROAD 109 METRES SE OF EMSWORTH COMMON ROAD, HAVANT,
HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from NW to SE No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: Entered ditch
Near side Age of Driver 41 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Going ahead other
Vehicle movement from SE to NW No tow / articulation Leaving the main road
On main carriageway Skidded and overturned
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 37 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 37 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

Vehicle Reference 3 Van or Goods 3.5 tonnes mgw and under Going ahead other
Vehicle movement from SE to NW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 42 Male
Not hit and run Breath test Negative
Left hand drive: No

130099574 18/03/2013 Time 0029 Vehicles 1 Casualties 1 Slight
E:473737 N: 108091 First Road: B 2149 Road Type Single carriageway
Speed limit: 60 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: Central reservation Road surface Wet/Damp
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Slippery road (due to weather)	Vehicle 1	Possible
2nd:	Exceeding speed limit	Vehicle 1	Possible
3rd:	Travelling too fast for conditions	Vehicle 1	
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING N ALONG B2149 HORNDEAN ROAD WHEN VEH LOST CONTROL AND LEFT THE
ROAD TO THE NEARSIDE COLLIDING WITH TREES. DRIVER DECAMPED AND LEFT THE SCENE POSSIBLY
DUE TO DRINK DRIVING.

Occurred on B2149 HORNDEAN ROAD AT JUNCTION WITH BARTONS ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: Lamp post
Nearside Age of Driver 22 Male
Hit and run Breath test Driver not contacted
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 19 Male Passenger Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Front seat

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

130119784 03/04/2013 Time 1400 Vehicles 2 Casualties 1 Slight
E:473734 N: 108107 First Road: B 2149 Road Type Single carriageway
Speed limit: 60 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING NE ALONG BARTONS ROAD, FAILED TO LOOK PROPERLY AND TURNED RIGHT INTO B2149 HORNDEAN ROAD ACROSS THE PATH OF VEH 2 (CAR) TRAVELLING NW ON HORNDEAN ROAD AND COLLIDES.

Occurred on B2149 HORNDEAN ROAD AT JUNCTION WITH BARTONS ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from SW to SE No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 52 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 52 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Going ahead other
Vehicle movement from SE to NW No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 26 Female
Not hit and run Breath test Not requested
Left hand drive: No

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

130204163 05/06/2013 Time 1645 Vehicles 2 Casualties 1 Slight
E:474874 N: 106102 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 2	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 2 (CAR) TRAVELLING N ALONG NORTH STREET FAILS TO STOP IN TIME AND COLLIDES WITH REAR
OF VEH 1 (CAR) WAITING TO TURN RIGHT INTO PALMER ROAD IN FRONT.

Occurred on NORTH STREET AT JUNCTION WITH PALMER ROAD, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Car Waiting to turn right
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 48 Male
Not hit and run Breath test Driver not contacted
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 48 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Jct Approach First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver Not traced
Not hit and run Breath test Driver not contacted
Left hand drive: No

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEN ROAD EMSWORTH")

130261029 11/07/2013 Time 1730 Vehicles 2 Casualties 1 Slight
E:472768 N: 106519 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site Road works Carriageway Hazards: None
Place accident reported: Elsewhere DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Poor turn or manoeuvre	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING S ALONG SOUTHLEIGH ROAD APPROACHES RAILWAY CROSSING WHERE
ROADWORKS WERE TAKEN PLACE AND DECIDED TO TURN AROUND. VEH 1 REVERSED COLLIDING WITH
VEH 2 (CAR) TRAVELLING S ALONG SOUTHLEIGH ROAD.

Occurred on SOUTHLEIGH ROAD OUTSIDE NUMBER 38, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Reversing
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 84 Male
Not hit and run Breath test Negative
Left hand drive: No

Vehicle Reference 2 Car Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 52 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 52 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

130380706 07/10/2013 Time 1512 Vehicles 1 Casualties 1 Serious
E:472717 N: 106404 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Casualty 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (VAN) TRAVELLING N ALONG SOUTHLEIGH ROAD COLLIDED WITH CAS 1 (PEDESTRIAN) WHO
WALKED OUT INTO ITS PATH FROM THE NEARSIDE.

Occurred on SOUTHLEIGH ROAD OUTSIDE WARBLINGTON SCHOOL, HAVANT, HAMPSHIRE

Vehicle Reference 1 Van or Goods 3.5 tonnes mgw and under Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver Not traced
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 11 Female Pedestrian Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
In carr elsewhere E bound
Driver's nearside

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

130394604 18/10/2013 Time 0700 Vehicles 2 Casualties 1 Serious
E:474916 N: 105902 First Road: U Road Type 1
Speed limit: 30 Junction Detail: Roundabout Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Darkness: street lights present and lit Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Not displaying lights at night or in poor visibility	Vehicle 2	Very Likely
2nd:	Disobeyed Give Way or Stop sign or markings	Vehicle 1	Possible
3rd:	Failed to judge other persons path or speed	Vehicle 1	
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING E ALONG HAVANT ROAD DID NOT SLOW COMPLETELY FOR RBT AND
COLLIDED WITH REAR WHEEL OF VEH 2 (P/CYCLE) TRAVELLING N ALONG HIGH STREET AND AROUND
RBT. VEH 1 FAILED TO STOP.

Occurred on HAVANT ROAD AT JUNCTION WITH HIGH STREET, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Car Stopping
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver Not traced
Hit and run Breath test Not requested
Left hand drive: No

Vehicle Reference 2 Pedal Cycle Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or r First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 15 Male
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 15 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: No

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEN ROAD EMSWORTH")

130416256 03/11/2013 Time 1400 Vehicles 2 Casualties 1 Slight

E:474876 N: 106059 First Road: B 2148 Road Type Single carriageway

Speed limit: 30 Junction Detail: Not within 20m of junction

Crossing: Control None Facilities: Pelican, puffin, toucan etc. Road surface Wet/Damp

Daylight Raining without high winds

Special Conditions at Site None Carriageway Hazards: None

Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Slippery road (due to weather)	Vehicle 1	Very Likely
2nd:	Road layout (eg bend, hill etc.)	Vehicle 1	Very Likely
3rd:	Travelling too fast for conditions	Vehicle 1	Possible
4th:	Inexperienced or learner driver/rider	Vehicle 1	Possible
5th:	Sudden braking	Vehicle 1	Very Likely
6th:			

VEH 1 (M/CYCLE) TRAVELLING N ALONG B2148 NORTH STREET SWERVED WHILST NEGOTIATING A
RIGHT-HAND BEND DUE TO A CAR PASSING TOO CLOSE IN THE OPPOSITE DIRECTION. VEH 1 THEN SLID
INTO VEH 2 (CAR) WHICH WAS PARKED AHEAD.

Occurred on B2148 NORTH STREET OUTSIDE NUMBER 42, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Motorcycle 50cc and under Going ahead right bend
Vehicle movement from SE to N No tow / articulation Leaving the main road
On main carriageway Skidded
Location at impact Not at, or within 20M of Jct First impact Front Hit vehicle:
Hit object in road Parked Vehicle Off road: None
Did not leave carr Age of Driver 16 Male
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 16 Male Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist

Vehicle Reference 2 Car Parked
Vehicle movement from Park to Parked No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Back Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver Not traced
Not hit and run Breath test Driver not contacted
Left hand drive: No

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

140055998 16/02/2014 Time 1100 Vehicles 2 Casualties 1 Serious
E:472690 N: 106112 First Road: U Road Type Single carriageway
Speed limit: 30 Junction Detail: T & Stag Jct Give way or controlled Unclassified
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Stationary or parked vehicle	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR) TRAVELLING W ALONG EMSWORTH ROAD, TURNS RIGHT INTO SOUTHLEIGH ROAD OUTSIDE
SHOPS AND FAILS TO SEE VEH 2 (P/CYCLE) TRAVELLING IN THE OPPOSITE DIRECTION AS VIEW AHEAD IS
OBSCURED BY VEH'S WAITING IN THE BOX JUNCTION AND COLLIDES.

Occurred on EMSWORTH ROAD AT JUNCTION WITH SOUTHLEIGH ROAD, HAVANT, HAMPSHIRE

Vehicle Reference 1 Car Turning right
Vehicle movement from E to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Front Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 41 Female
Not hit and run Breath test Not requested
Left hand drive: No

Vehicle Reference 2 Pedal Cycle Going ahead other
Vehicle movement from W to E No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Offside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 29 Male
Not hit and run Breath test Not applicable
Left hand drive: No

Casualty Reference: 1 Vehicle: 2 Age: 29 Male Driver/rider Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Yes

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEAN ROAD EMSWORTH")

140177030 20/05/2014 Time 1515 Vehicles 1 Casualties 1 Serious
E:474876 N: 106356 First Road: B 2148 Road Type Single carriageway
Speed limit: 30 Junction Detail: Not within 20m of junction
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Casualty 1	Possible
2nd:	Failed to judge vehicles path or speed	Casualty 1	Possible
3rd:			
4th:			
5th:			
6th:			

CAS 1 (PEDESTRIAN) TRAVELLING E ACROSS B2148 NEW STREET IS HIT BY VEH 1 (CAR) TRAVELLING N
ALONG B2148 NEW STREET.

Occurred on B2148 NORTH STREET 100 METRES SOUTH OF NEW BRIGHTON ROAD, EMSWORTH,
HAMPSHIRE

Vehicle Reference 1 Car Going ahead other
Vehicle movement from S to N No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Not at, or within 20M of Jct First impact Nearside Hit vehicle:
Hit object in road None Off road: None
Did not leave carr Age of Driver 76 Female
Not hit and run Breath test Negative
Left hand drive: No

Casualty Reference: 1 Vehicle: 1 Age: 16 Male Pedestrian Severity: Serious
Not a pupil
Seatbelt Not Applicable Cycle helmet: Not a cyclist
In carr elsewhere E bound
Driver's nearside

Accidents between dates 01/06/2009 and 31/05/2014 (60) months

Selection:

Notes:

Selected using Build Query : ; Refined using Accidents within
selected Polygons -HC - RPU Statistics Request ("NS
HORNDEN ROAD EMSWORTH")

090267168 20/06/2009 Time 0900 Vehicles 2 Casualties 1 Slight
E:474930 N: 105887 First Road: A 259 Road Type 1
Speed limit: 30 Junction Detail: Roundabout Give way or controlled B 2148
Crossing: Control None Facilities: None within 50m Road surface Dry
Daylight:street lights present Fine without high winds
Special Conditions at Site None Carriageway Hazards: None
Place accident reported: At scene DfT Special Projects:

Causation

	Factor:	Participant:	Confidence:
1st:	Failed to look properly	Vehicle 1	Very Likely
2nd:			
3rd:			
4th:			
5th:			
6th:			

VEH 1 (CAR), HEADING WEST ALONG THE A259, ENTERED THE ROUNDABOUT AT NORTH STREET, AND GENTLY STRUCK VEH 2 (PEDAL CYCLE) WHICH WAS APPROACHING FROM THE RIGHT.

Occurred on MAIN ROAD AT THE JUNCTION WITH NORTH STREET, EMSWORTH, HAMPSHIRE

Vehicle Reference 1 Car Starting
Vehicle movement from E to W No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Entering roundabout First impact Front Hit vehicle: 2
Hit object in road None Off road: None
Did not leave carr Age of Driver 51 Female
Not hit and run Breath test Negative
Left hand drive:

Vehicle Reference 2 Pedal Cycle Going ahead other
Vehicle movement from N to S No tow / articulation Leaving the main road
On main carriageway No skidding, jack-knifing or overturning
Location at impact Mid Junction - on roundabout or i First impact Nearside Hit vehicle: 1
Hit object in road None Off road: None
Did not leave carr Age of Driver 40 Female
Not hit and run Breath test Not applicable
Left hand drive:

Casualty Reference: 1 Vehicle: 2 Age: 40 Female Driver/rider Severity: Slight
Not a pupil
Seatbelt Not Applicable Cycle helmet:

Accidents between dates **01/06/2009 and 31/05/2014** (60) months

Selection:

Selected using Build Query : ; Refined using Accidents within
 selected Polygons -HC - RPU Statistics Request ("NS
 HORNDEAN ROAD EMSWORTH")

Notes:

Accidents involving:

	Fatal	Serious	Slight	Total
Motor vehicles only (excluding 2-wheels)	1	4	26	31
2-wheeled motor vehicles	0	3	4	7
Pedal cycles	0	4	7	11
Horses & other	0	0	0	0
Total	1	11	37	49

Casualties:

	Fatal	Serious	Slight	Total
Vehicle driver	1	1	20	22
Passenger	0	0	4	4
Motorcycle rider	0	2	4	6
Cyclist	0	4	7	11
Pedestrian	0	4	5	9
Other	0	0	0	0
Total	1	11	40	52