

Level Monitoring - Relative Movement Over Time

Our Ref: 00/29008

Date of Issue 27/01/15

Provider Details

Name: **CET Safehouse**

Monitoring Details

Instruction Date:	
First Reading Date:	05/02/14
Maximum No Visits:	4
Anticipated Expiry Date:	Aug-14
Monitoring Int (Wks):	8

Client Details

Insurance Co.:	Zurich Personal Lines
Client Name:	Cunningham Lindsey
Technical Mgr:	Gavin Catheline
Email:	
Client Ref:	7468207
Address:	
Tel:	
Other Email:	

Risk Address


Occupier:	Mr Dennis Hitchiner
Address:	18 Crystal Way
Address:	
Town:	Waterlooville
County:	
Post Code:	PO7 8NB
Tel Day:	07917 501 951
Tel Eve:	02392 266109
Mobile:	
Other:	
Other:	

Level Monitoring - Site Sketch

Our Ref: 00/29008

Date of Issue

27/01/15



Level Monitoring - Comments

Our Ref: 00/29008

Date of Issue

27/01/15

Level Monitoring - Reduced Levels

Our Ref: 00/29008

Date of Issue

27/01/15

Reading Date	05/02/14	29/04/14	25/07/14	20/10/14	21/01/15							
Point / Reading	1	2	3	4	5	6	7	8	9	10	11	12
1	10.820	10.822	10.815	10.811	10.818							
2	10.224	10.224	10.219	10.218	10.222							
3	10.238	10.239	10.236	10.236	10.239							
4	10.256	10.256	10.255	10.255	10.256							
5	10.257	10.256	10.259	10.260	10.272							
6	10.270	10.269	10.270	10.270	10.270							
7	10.261	10.266	10.262	10.268	10.268							
8	10.227	10.235	10.232	10.233	10.235							
9	10.754	10.754	10.754	10.750	10.754							
10	10.790	10.792	10.789	10.786	10.790							
11	10.779	10.781	10.772	10.767	10.777							
12	10.206	10.211	10.197	10.194	10.206							
Not used												
Not used												
Not used												
Not used												

Highest reduced level is displayed green, lowest reduced level is displayed red

Level Monitoring - Relative Movement Over Time

Our Ref: 00/29008

Date of Issue


27/01/15

[illegible]

Level Monitoring - Movement relative to datum against Date

Our Ref: 00/29008

Issue Date: 27/01/15





Giving our all

MS ref	Client ref	Client Name	Issue Date
00/29008	7468207	Cunningham Lindsey	27/01/15

Stud locations

1	INT front right corner in living room
2	
3	
4	
5	
6	

Additional instructions / notes

Studs nos.	Align-ment	Current C/W	Visit Date										
			05/02/14	29/04/14	25/07/14	20/10/14	21/01/15						
1	H		107.87	107.62	108.38	109.16	108.36						
1	V		87.04	87.11	87.49	87.43	87.16						
1	D		153.52	153.52	153.58	154.50	154.51						
2	H												
2	D												
2	Check												
3	H												
3	D												
3	Check												
4	H												
4	D												
4	Check												
5	H												
5	D												
5	Check												
6	H												
6	D												
6	Check												
Customer :			No issues	No issues	No issues	See comment	No issues						
New cracking :													
See "current c/w" :													
Calliper nos :			555	6173	555	6173	6173						
Technician :			CM	RH	Cmc	AL	AL						

Additional comments : -

Line 1				1=3 Is not a									
Line 2													
Line 3													

(max = 55 characters per line)



MS ref	Client ref	Client Name	Issue Date
00/29008	7468207	Cunningham Lindsey	27/01/15

