

NOTES:

Drainage:
All drainage invert information has been obtained through visual inspection only, with no entry into manholes. Therefore the level of critical importance we suggest the services of a specialist drainage expert be used.

Trees:
The survey has been made in January and detail all trees on site but where trees are of critical importance we suggest the use of a specialist such as an arborist. Tree spread and heights are indicative.

GPS:
GPS levels and grid are obtained using industry standard guidelines and are accurate to within 1m. All levels are relative to the datum of survey. Therefore all GPS detail is relative to the time and date of the survey.

Copyright:
This survey information is Copyright Encompass Surveys Ltd (2009). All rights reserved.

Level Datum:
Levels are related to OSGB36 derived from the GPS Network

Grid:

Northpoint:



Encompass Surveys Ltd
100, 101 & 102
Deer Park Farm Industrial Estate
Kingsley Lane
Kingsley, Leamington
Warwickshire CV35 9JZ
Tel: 033 8669300 Email: info@encompass-surveys.co.uk
Fax: 033 8669725 Website: encompass-surveys.co.uk

Client:		NH Architects	
Survey Location:		Burford Park School Cotnam	
Survey type:		Drainage-plan	Scale: Not to scale
Drawing ref:		ENC/010214-4P1-EG	Date: February 2014
Drawn/Qd:		KJS/LH	Revised: