

NOTES:


Drainage: All drainage invert information has been obtained through visual inspection only, with no entry into manholes. Therefore the complete accuracy cannot be guaranteed. Where drainage is of critical importance we suggest the services of a specialist drainage expert be used.

Trees:

Every effort has been made to identify and detail all trees on site but where trees are of critical importance we suggest the use of a specialist such as an arborist. Tree spread and heights are indicative

GPS: GPS levels and grid are obtained using industry standard guidelines and can vary according to the quality of the GPS network at the time of survey. Therefore all GPS detail is relative to the time and date of the survey.

Copyright:
This survey information is Copyright Encompass Surveys Ltd (2009).
All rights reserved.



Level Datum:
Levels are related to OSGB36 derived from the GPS Network

Grid:
Grid is related to OSGB36 derived from GPS

Northpoint



Encompass Surveys Ltd
Unit 28
Deer Park Farm Industrial Estate
Knowle Lane
Fair Oak, Easdean
Hampshire SO50 7YZ

Tel: 023 80693002
Fax: 023 80697125

Email: info@encompass-surveys.co.uk
Website: encompass-surveys.co.uk

Client: MH Architects

Survey Location:	Purbrook Park School Park Avenue Cosham
------------------	---

Survey type:	Measured Building	Scale:	1:100@A1
--------------	-------------------	--------	----------

Drawn/QA:	G.J./K.G	Revision:
-----------	----------	-----------

Block 'B'

Upper Level

