

HAVANT BOROUGH  
COUNCIL

10 JAN 2014


**RECEIVED**

**MANOR FARM,  
DENVILLES,  
HAVANT**

## **SUD'S INSPECTION REPORT**

**BARRATT DAVID WILSON HOMES SOUTHAMPTON**

Date: 23rd Sept 2013  
Ref: 13/0627/4527



# **SUD's INSPECTION REPORT** **MANOR FARM, DENVILLES, HAVANT**

|                                                  |                                                                                                                                                                                                         |
|--------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Date of Inspection:</b>                       | 23 September 2013                                                                                                                                                                                       |
| <b>Time:</b>                                     | 12.00pm                                                                                                                                                                                                 |
| <b>By:</b>                                       | Karl Gebhart                                                                                                                                                                                            |
| <b>Position in Company:</b>                      | Director                                                                                                                                                                                                |
| <b>Weather Conditions on Date of Inspection:</b> | Dry/Overcast                                                                                                                                                                                            |
| <b>SUD's Item Inspected:</b>                     | <p>Image No.1<br/>Laying of permeable sub base for road.</p> <p>Image No.2<br/>End of carriageway permeable sub base.</p> <p>Image No.3<br/>Highway drainage</p> <p>Image No.4<br/>Highway drainage</p> |
| <b>Comments:</b>                                 | No aquacell tanks have been delivered for the soakaways in rear gardens therefore unable to inspect these items yet.                                                                                    |
| <b>Date of Next Inspection:</b>                  | Date of next inspection: 14.10.13                                                                                                                                                                       |

Image No.1



Image No.2



Image No.3



Image No.4

