Existing level crossing

Position of barriers when closed

Position of barriers

Stop line

Visibility to existing signals illustrated from 2.4m setback

Swept path of typical family saloon (4.32m long x 1.69m wide)

Proposed dropped pedestrian crossing set behind vehicles waiting to exit site

Proposed 5.5m access road with 2 x 1.8m wide footways

Existing footway / cycleway route

NEW LANE

Proposed feature

View of signal head above existing white picket fence

View north-east towards level crossing (access to footway / cycleway right)

Steel Security Fence 1.8m High

Steel Security Fence 1.8m High Gate

Chainlink Fence 1.2m High

Tactile Paving

Picket Fence

Gates

Gate

Tarmac

Grass

Brambles

Ridge 17.59

Eaves 16.06

Flat Roof 13.90

Ridge 19.53

Eaves 16.36

CATV

FH

Bin

Fire

Signal

Signal No

Signal Actuation

MH 10.88cl

MH 10.69cl

MH 10.61cl

STN 1 472046.244 106542.351 10.680

STN18 472090.343 106541.892 9.690

CHERRY 0/.3/11

CHERRY 0/.2/10

SB 0/.4/16

SB 0/.2/10

SB 0/.2/15

OAK 0/.2/14

OAK 0/.25/0

MAPLE 0/.2/7

MAPLE 0/.35/15

HAW 12/.7/8

HC 14/.7/14

ASH 0/.3/11

0/.15/10

MAP 0/.2/14

MAP 0/.2/0

MAP 0/.1/0

0/.2/13

0/.2/11

0/.2/10

0/.1/13

0/.1/10

2m High

The Contractor is to check and verify in conjunction with the Architects details all setting out points, building and site dimensions, levels and sewer invert levels at connection points and ensure that they are fully conversant with the contents and of requirements the site investigation report before work starts.
The Contractor is to comply in all respects with current building legislation, British Standard Specifications, Building Regulations etc.,whether or not specifically stated on this drawing.

This drawing is not intended to show details of ground conditions or ground contaminants. Each area of ground relied upon to support any structure depicted (including drainage) must be investigated by the Contractor any areas of formation for said structures which do not accord with the anticipated conditions as described in the site investigation report are to be immediately notified to the Engineer, where applicable. Any suspect fluid ground or ground contaminants on or within the ground should be further investigated by a suitable expert. Any earthworks shown indicate typical slopes for guidance only and should be investigated further by a suitable geotechnical expert.

Where existing trees are shown to be retained they should be subject to a full Arboricultural inspection for safety. All trees are to be planted so as to ensure they are a minimum of 5 metres from buildings and 3 metres from drainage and services, where applicable. A foundation is to be provided to accommodate the proposed tree planting, where applicable.

© This drawing and the building works depicted are the copyright of Banners Gate Transportation Ltd and may not be reproduced or amended except by written permission. No liability will be accepted for amendments made by other persons.

Swept path analysis taken from Auto Track (v8.90a) and based on the following



Medium Sized Car

Overall Length	4.319m
Overall Width	1.686m
Overall Body Height	1.466m
Min Body Ground Clearance	0.228m
Max Track Width	1.591m
Lock to Lock Time	4.00 sec
Kerb to Kerb Turning Radius	5.042m

Rev.	Description	Date	By

Client

BLOOR HOMES

Project

LAND AT NEW LANE
HAVANT, HAMPSHIRE

Title

PROPOSED ACCESS ARRANGEMENTS

Banners Gate
Civil, Structural & Transportation Engineers
Cavendish House, 10–11 Birmingham Street, Halesowen B63 3HN
Tel: 0121 687 1500 Fax: 0121 687 1501
E-mail: mail@bannersgate.com

Scale	1:100 @ A1	Drawn	DJA
Date	Mar 11	Checked	NRV
File	P764	Drawing	P764/101