

1 North wall of existing clergy vestry viewed from the west. Lime rendered single skin external wall discoloured with algae and moss.



2 East gable wall of clergy vestry with lime rendered finish and modern style flush external door.