

CONDITION SURVEY

Date: 11th September 2024

Project: Downley Road, Havant

Project No. 1592

1592- Downley Road, Havant



RESHAPING THE FUTURE
www.metrodeconstruction.com

METRO

CONDITION SURVEY

Date: 11th September 2024

Introduction

This document has been prepared as a means of providing a photographed evaluation of this properties condition, and the condition of the surrounding paths and roadways during our site inspection. This survey has been undertaken to help show the condition of the property and to record any potential risks prior to our start on site.


The aim of the condition survey is to;

- Document the present condition of the property, highlighting areas of failure or concern
- Identifying causes of past, or ongoing deterioration
- Identifying issues that need attention to prevent serious damage
- Presenting conservation and maintenance recommendations

This survey and all photographs were undertaken on 11/09/2024 by Simon Barden Site Manager on behalf of Metro Deconstruction Services Ltd.

Location of Photographs

1592- Downley Road, Havant



RESHAPING THE FUTURE
www.metrodeconstruction.com

METRO

CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

1.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

2.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

3.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

4.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

5.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

6.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

7.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

8.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

9.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

10.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

11.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

12.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

13.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

14.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

15.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

16.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

17.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

18.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

19.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

20.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

21.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

22.




CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

23.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

24.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

25.



CONDITION SURVEY

Date: 11th September 2024

Photo Taken:

26.

