



DETAILS OF CRACK MONITORING

GHG Reference	S2518361
Name of Insured	[REDACTED]
Risk Address	3 Coronation Road, Waterloooville, Hampshire, PO7 7FA, United Kingdom
Telephone	
Mobile	

All measurements are in mm.

Barclays House, 20-24 Upper Market Street, Eastleigh, Hampshire, SO50 9FD
GHG Solutions Limited, Registered In England, Company Registration No: 3007129
GHG Solutions Limited is authorised and regulated by the Financial Conduct Authority, firm reference number 913965
Registered office, Barclays House 20-24 Upper Market Street, Eastleigh, Hampshire SO50 9FD




LOCATION DETAILS

Location	External - Movement joint at right elevation
Crack Width	10.00
Alignment	Vertical



GRAPH OF CRACK MOVEMENT



MONITORING READINGS

17/10/2025	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
Initial Reading		A-B	Horizontal	80.260	0.000	0.000
		B-C	Vertical	60.900	0.000	0.000
		A-C	Diagonal	99.200	0.000	0.000
29/01/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
SML		A-B	Horizontal	75.547	-4.713	-4.713
		B-C	Vertical	60.220	-0.680	-0.680
		A-C	Diagonal	95.277	-3.923	-3.923
18/03/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
SML		A-B	Horizontal	73.683	-6.577	-1.863
		B-C	Vertical	60.210	-0.690	-0.010
		A-C	Diagonal	93.847	-5.353	-1.430
19/05/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
SML		A-B	Horizontal	72.953	-7.307	-0.730
		B-C	Vertical	60.300	-0.600	0.090
		A-C	Diagonal	93.157	-6.043	-0.690

16/07/2026	Notes	Segment	Alignment	Value	+/-Initial	+/-Previous
	SML	A-B	Horizontal	77.313	-2.947	4.360
		B-C	Vertical	60.313	-0.587	0.013
		A-C	Diagonal	96.503	-2.697	3.347