

LEVEL MONITORING

for SMS (ESU)

1 Hartwood Gardens, Waterloooville, PO8 8RA

Client:	SMS (ESU)
Client Contact:	Refer to iSubs
Claim Number:	1000043560
Client Reference:	IFS-ESU-SUB-25-0122071
Policy Holder:	
Report Date:	18 August 2026
Our Ref:	M25189


Level Monitoring Readings

The following table shows the reading levels of the various Level Monitoring Station points.

Date	1	2	3	4	5	6	7	8	9	10
28/10/2025	10.0000	10.0029	9.9935	9.9933	10.0426	10.0371	10.0368	10.0474	10.0553	10.0775
08/01/2026	10.0000	10.0030	9.9938	9.9913	10.0478	10.0441	10.0459	10.0587	10.0679	10.0787
05/03/2026	10.0000	10.0031	9.9941	9.9914	10.0500	10.0458	10.0479	10.0612	10.0682	10.0773
21/04/2026	10.0000	10.0034	9.9944	9.9910	10.0483	10.0450	10.0473	10.0603	10.0687	10.0776
18/06/2026	10.0000	10.0036	9.9938	9.9908	10.0485	10.0448	10.0464	10.0588	10.0676	10.0789
12/08/2026	10.0000	10.0032	9.9932	9.9882	10.0369	10.0313	10.0316	10.0423	10.0497	10.0738



Level Monitoring Difference Graphs

The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.



Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.



FRONT

Site Visit Notes

TBM is located as point 1, it has an assumed value of 10.0000m. TBM 2 is a manhole in road to front of property. If this is not suitable, please advise if a deep datum is required.